

ReleaseOrder ID: DCSG00225802

Headline: Point Release: SAS3\_FW\_Phase16.0 - 16.00.12.00 Firmware IT/IR Release

Release Version: 16.00.12.00 SAS3\_FW UCM Project:

Sub UCM Project: SAS3\_FW\_Phase16.0 UCM Stream: SAS3\_FW\_Phase16.0\_Rel

Release Type: Point State:

Release Baseline: SAS3\_FW\_Phase16.0-2020-05-18-16.00.12.00\_REL\_1589871065@\SAS3

Release Date: 2020-05-19 06:50:42.000000

Date Generated: Jun 08, 2020

## **Defects Fixed (1):**

ID: DCSG00139294

Headline: SATA only: Controller hang is observed due to recursive function call.

Description Of Change: Avoid starting of pended commands to SATA drive from completion functions of a command to avoid recursion. Issue Description: Controller hang is observed with ATA pass through command followed by a pended command that fails.

At the completion of pass through command, PL starts the pended IOs if any.

If the pended IO is failed due to invalid CDB, then immediately completion function is called causing recursion.

Steps To Reproduce: Install the FreeNAS and try to create ZFS pool(Storage -> Pools -> Add) of the direct attached SSDs.

This causes controller hang.

- ATA command completes when there are IOs in pendlist. - The pended IO has invalid CDB