




Parameters : i=500, Thresh.= 40, $T_{rise} = 2$ s, $T_{wait} = 2$ s, $T_{meas} = 1$ s, $V_{\underline{k}\underline{m}} = 48$




Parameters : i=500, Thresh.= 40, $T_{\rm rise}$ = 2 s, $T_{\rm walt}$ = 2 s, $T_{\rm meas}$ = 1 s, $V_{\rm lim}$ = 48





Parameters : i=500, Thresh.= 40, $T_{\rm rise}$ = 2 s, $T_{\rm walt}$ = 2 s, $T_{\rm meas}$ = 1 s, $V_{\rm lim}$ = 48



Parameters : i=500, Thresh.= 40, $T_{\rm rise}$ = 2 s, $T_{\rm wair}$ = 2 s, $T_{\rm meas}$ = 1 s, $V_{\rm lim}$ = 4