



Parameters : i=500, Thresh.= 40,  $T_{rise}$  = 2 s,  $T_{wait}$  = 2 s,  $T_{meas}$  = 1 s,  $V_{kim}$  = 48






InsulationTest\_All\_Passed-Failed 40 35 30 25 20 15 10

Passed

 $Parameters: V=50 \ V, \ Thresh=100 \ M\Omega, \ T_{_{rise}}=1 \ s, \ T_{_{meat}}=8 \ s, \ I_{_{meas}}=8 \ s, \ i_{_{lim}}=1.95 \ mA, \ V_{_{mmp}}=120 \ V/s$ 



ContinuityTest\_ResistenceLV 0.8 0.4 0.2

Parameters : i=500, Thresh.= 40,  $T_{\rm rise}$  = 2 s,  $T_{\rm wall}$  = 2 s,  $T_{\rm meas}$  = 1 s,  $V_{\rm lim}$  = 48