



Parameters : i=500, Thresh.= 40, $T_{rise} = 2$ s, $T_{wait} = 2$ s, $T_{meas} = 1$ s, $V_{kim} = 48$



 $Initial\ Parameters: V=1.2\ kV,\ Thresh=1\ G\Omega,\ T_{rise}=10\ s,\ T_{wait}=8\ s,\ T_{meas}=1\ s,\ i_{\underline{lim}}=1.95\ mA,\ V_{mmp}=120\ V/s$



45 40 35 30 25 15 Passed

 $Parameters: V=50 \ V, \ Thresh=100 \ M\Omega, \ T_{_{rise}}=1 \ s, \ T_{_{meat}}=8 \ s, \ I_{_{meas}}=8 \ s, \ i_{_{lim}}=1.95 \ mA, \ V_{_{mmp}}=120 \ V/s$

InsulationTest_All_Passed-Failed

