


Parameters : i=500, Thresh.= 40, $T_{rise} = 2$ s, $T_{wait} = 2$ s, $T_{meas} = 1$ s, $V_{lim} = 48$



Parameters : i=500, Thresh.= 40, $T_{rise} = 2$ s, $T_{wait} = 2$ s, $T_{meas} = 1$ s, $V_{lim} = 48$