ENGT 3652 Project 4: Bottle opener-Milling


Leomar Durán

3rd April 2023

Chapter 1

Verification of operations in Mastercam





Chapter 2

Gcode

```
N380 X2.6263 Y.25 Z.0653 I.25 JO.
088928(BOTTLE OPENER TOP)
                                             N390 X2.8763 YO. Z.0447 IO. J-.25
(DATE=DD-MM-YY - 03-04-23 TIME=HH:MM -
                                            N400 X2.6263 Y-.25 Z.0242 I-.25 J0.
                                            N410 X2.5077 Y-.2201 Z.0177 IO. J.25
→ 19:57)
(MATERIAL - ALUMINUM INCH - 6061)
                                            N420 X2.3763 YO. Z.0036 I.1186 J.2201
( T1 | 2" FACE MILL (SFM 600.0) | H1 )
                                           N430 X2.6263 Y.25 Z-.017 I.25 JO.
( T2 | 3/16 DRILL (SFM 200.0) | H2 )
                                            N440 X2.8763 YO. Z-.0376 IO. J-.25
( T3 | 5/16 FLAT ENDMILL | H3 )
                                             N450 X2.6263 Y-.25 Z-.0581 I-.25 JO.
( T4 | 1/8 FLAT ENDMILL | H4 )
                                            N460 X2.5077 Y-.2201 Z-.0646 IO. J.25
( T5 | 1/4 INCH ENGRAVING TOOL 60 DEGREE X N470 X2.3763 YO. Z-.0788 I.1186 J.2201
                                             N480 G1 X2.6049
\rightarrow .001 TIP | H5 )
N100 G20
                                             N490 G3 X2.5463 Y.0586 I-.0586 JO.
N110 GO G17 G40 G49 G80 G90
                                             N500 X2.4877 YO. IO. J-.0586
N120 T1 M6
                                             N510 X2.6244 Y-.1367 I.1367 JO.
N130 GO G90 G54 X-2.2 YO. . S1146 M3
                                             N520 X2.7611 YO. IO. J.1367
N140 G43 H1 Z.25 M8
                                             N530 X2.5463 Y.2148 I-.2148 JO.
                                             N540 X2.3314 YO. IO. J-.2148
N150 Z.2
N160 G1 ZO. F.76
                                             N550 X2.6244 Y-.293 I.293 J0.
                                             N560 X2.9174 YO. IO. J.293
N170 X5.5464 F2.29
N180 GO Z.25
                                             N570 X2.5499 Y.3711 I-.3711 JO.
N190 M5
                                             N580 G1 X2.2002 Y.134
N200 G91 G28 Z0. M9
                                             N590 G3 X2.1752 YO. I.3461 J-.134
N210 .
                                             N600 X2.1944 Y-.1301 I.4492 JO.
N220 M01
                                             N610 G1 X2.6628 Y-.4476
N230 T2 M6
                                             N620 G3 X2.8624 Y-.381 I-.0384 J.4476
N240 GO G90 G17 G54 X.3937 YO. . S4074 M3
                                            N630 G1 X2.7884 Y.4685
N250 G43 H2 Z.5 M8
                                             N640 G3 X2.7516 Y.4857 I-.2421 J-.4685
N260 G99 G81 Z-.5 R.5 F7.82
                                             N650 X2.7416 Y.4864 I-.01 J-.0692
N270 G80
                                             N660 X2.7023 Y.4744 IO. J-.0699
N280 M5
                                             N670 G1 X2.0399 Y.0253
N290 G91 G28 Z0. M9
                                             N680 G3 X2.0265 YO. I.0171 J-.0253
N300 .
                                             N690 X2.0399 Y-.0253 I.0305 JO.
N310 M01
                                             N700 G1 X2.7023 Y-.4744
                                             N710 G3 X2.7416 Y-.4865 I.0393 J.0579
N320 T3 M6
N330 G0 G90 G17 G54 X2.5077 Y-.2201 . S6723
                                             N720 X2.7892 Y-.4677 IO. J.07
\rightarrow M3
                                             N730 X2.9834 YO. I-.4664 J.4677
N340 G43 H3 Z.25 M8
                                             N740 X2.7892 Y.4677 I-.6606 JO.
N350 Z.2
                                             N750 X2.7516 Y.4857 I-.0476 J-.0512
N360 G1 Z.1 F12.12
                                             N760 G1 Z.1212 F12.12
N370 G2 X2.3763 YO. Z.0859 I.1186 J.2201
                                            N770 GO Z.1713
→ F33.35
                                             N780 X2.5077 Y-.2201
```

```
N790 Z.1212
                                                                   N1320 G3 X2.7416 Y-.4965 I.0449 J.0662
                                                                 N1330 X2.7962 Y-.4749 IO. J.08
 N800 G1 Z.0213 F12.12
 N810 G2 X2.3763 YO. Z.0072 I.1186 J.2201 N1340 X2.9933 YO. I-.4734 J.4749
                                                                  N1350 X2.7962 Y.4749 I-.6705 JO.
 .. F33 35
 N820 X2.6263 Y.25 Z-.0134 I.25 JO.
                                                                   N1360 X2.7416 Y.4964 I-.0546 J-.0584
 N830 X2.8763 YO. Z-.034 IO. J-.25
                                                                 N1370 X2.6967 Y.4827 IO. J-.0799

      N840
      X2.6263
      Y-.25
      Z-.0546
      I-.25
      J0.
      N1380
      G1
      X2.3655
      Y.2581

      N850
      X2.5077
      Y-.2201
      Z-.0611
      I0.
      J.25
      N1390
      G3
      X2.2284
      Y-.0005
      I.1753

      N860
      X2.3763
      Y0.
      Z-.0752
      I.1186
      J.2201
      N1400
      X2.2822
      Y-.1759
      I.3124
      J0.

                                                                 N1390 G3 X2.2284 Y-.0005 I.1753 J-.2586
 N870 X2.6263 Y.25 Z-.0958 I.25 JO.
                                                                 N1410 G1 X2.2993 Y-.2012
 N880 X2.8763 YO. Z-.1164 IO. J-.25
                                                                 N1420 Z.1212 F12.12
 N890 X2.6263 Y-.25 Z-.1369 I-.25 J0.
                                                                 N1430 GO Z.1713
N890 X2.6263 Y-.25 Z-.1369 I-.25 J0.
N900 X2.5077 Y-.2201 Z-.1434 I0. J.25
N910 X2.3763 Y0. Z-.1575 I.1186 J.2201
                                                                 N1440 X2.9749 Y-.0839
                                                                 N1450 Z.1212
 N920 G1 X2.6049
                                                                  N1460 G1 Z-.1575 F12.12
                                                     N1470 X2.7995 Y.1748 F33.35
 N930 G3 X2.5463 Y.0586 I-.0586 JO.
N940 X2.4877 Y0. I0. J-.0586
N950 X2.6244 Y-.1367 I.1367 J0.
N960 X2.7611 Y0. I0. J.1367
N970 X2.5463 Y.2148 I-.2148 J0.
N980 X2.3314 Y0. I0. J-.2148
N990 X2.6244 Y-.293 I.293 J0.
N1530 G1 X2.0342 Y-.0336 I.0406 J0
N990 X2.9174 Y0. I0. J.293
N1000 X2.9174 Y0. I0. J.293
N1010 X2.5499 Y.3711 I-.3711 J0.
N1550 X2.7962 Y-.4749 I0. J.08
N1020 G1 X2.2002 Y.134
                                                                  N1480 G3 X2.5408 Y.312 I-.2587 J-.1753
                                                                 N1490 X2.3655 Y.2581 IO. J-.3125
                                                                  N1510 G3 X2.0164 YO. I.0228 J-.0336
                                                                 N1520 X2.0342 Y-.0336 I.0406 J0.
                                                                 N1540 G3 X2.7416 Y-.4965 I.0449 J.0662
                                                                  N1560 X2.9933 YO. I-.4734 J.4749

      N1020 G1 X2.2002 1.134
      N1030 K2.3333 10. 1 .476

      N1030 G3 X2.1752 Y0. I.3461 J-.134
      N1570 X2.7962 Y.4749 I-.

      N1040 X2.1944 Y-.1301 I.4492 J0.
      N1580 X2.7416 Y.4964 I-.

      N1050 G1 X2.6628 Y-.4476
      N1590 X2.6967 Y.4827 I0.

      N1060 G3 X2.8624 Y-.381 I-.0384 J.4476
      N1600 G1 X2.3655 Y.2581

      N1070 G1 X2.7884 Y.4685
      N1610 G3 X2.2284 Y-.0008

                                                                 N1570 X2.7962 Y.4749 I-.6705 JO.
                                                                 N1580 X2.7416 Y.4964 I-.0546 J-.0584
                                                                  N1590 X2.6967 Y.4827 IO. J-.0799
                                                                  N1610 G3 X2.2284 Y-.0005 I.1753 J-.2586
N1080 G3 X2.7516 Y.4857 I-.2421 J-.4685 N1620 X2.2822 Y-.1759 I.3124 J0.
N1090 X2.7416 Y.4864 I-.01 J-.0692 N1630 G1 X2.2993 Y-.2012
N1100 X2.7023 Y.4744 IO. J-.0699
                                                                 N1640 Z.0425 F12.12
N1110 G1 X2.0399 Y.0253
                                                                 N1650 GO Z.25
N1120 G3 X2.0265 Y0. I.0171 J-.0253 N1660 M5
N1130 X2.0399 Y-.0253 I.0305 J0. N1670 G9:
N1140 G1 X2.7023 Y-.4744 N1680 .
                                                                 N1670 G91 G28 Z0. M9
N1140 G1 X2.7023 Y-.4744
                                                                  N1680 .
N1150 G3 X2.7416 Y-.4865 I.0393 J.0579 N1690 M01
N1160 X2.7892 Y-.4677 I0. J.07 N1700 T4 I
N1170 X2.9834 Y0. I-.4664 J.4677 N1710 G0 (
                                                                  N1700 T4 M6
                                                                 N1710 GO G90 G17 G54 X2.5509 Y.2894 . S8862
 N1170 X2.9834 YO. I-.4664 J.4677
N1180 X2.7892 Y.4677 I-.6606 JO.
                                                                   \hookrightarrow M3
 N1190 X2.7516 Y.4857 I-.0476 J-.0512
                                                                 N1720 G43 H4 Z.0925 M8
 N1200 G1 Z.0425 F12.12
                                                                   N1730 Z.0425
N1210 GO Z.0925
                                                                   N1740 G1 Z-.28 F11.74
N1220 Z.2
                                                                  N1750 X2.614 Y.3973 F14.44
N1230 X2.9749 Y-.0839
                                                                  N1760 G2 X2.7219 Y.4592 I.1079 J-.0631
 N1240 G1 Z-.0788 F12.12
                                                                  N1770 X2.785 Y.4422 IO. J-.125
N1250 X2.7995 Y.1748 F33.35
                                                                 N1780 X2.8516 Y.3262 I-.0678 J-.116
N1260 G3 X2.5408 Y.312 I-.2587 J-.1753
                                                               N1790 X2.8513 Y.3182 I-.1344 JO.
N1270 X2.3655 Y.2581 IO. J-.3125
                                                                  N1800 G1 X2.8502 Y.3006
 N1280 G1 X2.0342 Y.0336
                                                                  N1810 X2.8585 Y.2851
N1290 G3 X2.0164 Y0. I.0228 J-.0336
N1300 X2.0342 Y-.0336 I.0406 J0.
                                                                 N1820 G2 X2.9296 YO. I-.5357 J-.2851
                                                                 N1830 X2.8585 Y-.2851 I-.6068 JO.
 N1310 G1 X2.6967 Y-.4827
                                                                   N1840 G1 X2.8502 Y-.3006
```

N1850 X2.8513 Y3182	N2370 Z.25
N1860 G2 X2.8515 Y3262 I1341 J008	N2380 X.7072 Y.0596
N1870 X2.7172 Y4605 I1343 JO.	N2390 Z.2
N1880 X2.6444 Y439 IO. J.1343	N2400 G1 Z001 F12.22
N1890 G1 X2.4731 Y3285	N2410 X.6874 Y.065 F30.56
N1900 G2 X2.4477 Y2819 I.0301 J.0466	N2420 X.683 Y.0652
N1910 X2.4646 Y242 I.0555 JO.	N2430 X.6722 Y.0642
N1920 G3 X2.4837 Y197 I0434 J.045	N2440 X.6559 Y.0568
N1930 X2.4789 Y173 I0625 JO.	N2450 X.6552 Y.0563
N1940 G2 X2.4443 YO. I.4147 J.173	N2460 X.6471 Y.0464
N1950 X2.4789 Y.173 I.4493 JO.	N2470 X.6444 Y.0348
N1960 G3 X2.4837 Y.197 I0577 J.024	N2480 X.6484 Y.0224
N1970 X2.4646 Y.242 I0625 JO.	N2490 X.6557 Y.0158
N1980 G2 X2.4477 Y.2819 I.0386 J.0399	N2500 X.673 Y.0095
	N2510 X.6849 Y.0086
N2000 G1 X2.6444 Y.439	N2520 X.6924 Y.0089
N2010 G2 X2.7172 Y.4605 I.0728 J1128	
	N2540 X.7144 Y.0288
N2030 X2.847 Y.3342 I0631 J108	
N2040 X2.8298 Y.2712 I1251 JO.	
	N2570 X.7072 Y.0596
N2060 Z08 F11.74	N2580 Z.199 F12.22
N2070 GO Z.0925	N2590 GO Z.249
N2080 M5	N2600 Z.25
N2090 G91 G28 Z0. M9	N2610 X.7082 Y.0614
N2100 .	N2620 Z.2
N2110 M01	N2630 G1 Z001 F12.22
N2120 T5 M6 N2130 G0 G90 G17 G54 X.7395 Y.0275 . S7640	N2640 X.6963 Y.0655 F30.56
N2130 GO G90 G17 G54 X 7395 Y 0275 S7640	
→ M3	N2660 X.6668 Y.0644
→ M3 N2140 G43 H5 Z.25 M8	N2660 X.6668 Y.0644 N2670 X.653 Y.0569
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.651 Y0339
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534 N2250 X.7628 Y.0584	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.651 Y0325
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534 N2250 X.7628 Y.0584 N2260 X.7579 Y.06	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.6385 Y0325 N2800 X.6275 Y0349
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534 N2250 X.7628 Y.0584 N2260 X.7579 Y.06 N2270 X.7476 Y.056	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.6385 Y0325 N2800 X.6275 Y0349 N2810 X.6266 Y0355
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534 N2250 X.7628 Y.0584 N2260 X.7579 Y.06 N2270 X.7476 Y.056 N2280 X.7462 Y.0551	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.651 Y0339 N2790 X.6385 Y0325 N2800 X.6275 Y0349 N2810 X.6266 Y0355 N2820 X.6233 Y0387
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534 N2250 X.7628 Y.0584 N2260 X.7579 Y.06 N2270 X.7476 Y.056 N2280 X.7462 Y.0551 N2290 X.7325 Y.0417	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.651 Y0339 N2790 X.6385 Y0325 N2800 X.6275 Y0349 N2810 X.6266 Y0355 N2820 X.6233 Y0387 N2830 X.6222 Y0426
M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534 N2250 X.7628 Y.0584 N2260 X.7579 Y.06 N2270 X.7476 Y.056 N2280 X.7462 Y.0551 N2290 X.7325 Y.0417 N2300 X.7372 Y.0353	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.651 Y0339 N2790 X.6385 Y0325 N2800 X.6275 Y0349 N2810 X.6266 Y0355 N2820 X.6233 Y0387 N2830 X.6222 Y0426 N2840 X.6262 Y0496
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534 N2250 X.7628 Y.0584 N2260 X.7579 Y.06 N2270 X.7476 Y.056 N2280 X.7462 Y.0551 N2290 X.7325 Y.0417 N2300 X.7372 Y.0353 N2310 X.7387 Y.0315	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.651 Y0339 N2790 X.6385 Y0325 N2800 X.6275 Y0349 N2810 X.6266 Y0355 N2820 X.6233 Y0387 N2830 X.6222 Y0426 N2840 X.6262 Y0496 N2850 X.6274 Y0503
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534 N2250 X.7628 Y.0584 N2260 X.7579 Y.06 N2270 X.7476 Y.056 N2280 X.7462 Y.0551 N2290 X.7325 Y.0417 N2300 X.7372 Y.0353 N2310 X.7387 Y.0315 N2320 X.7384 Y.031	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.6385 Y0325 N2800 X.6275 Y0349 N2810 X.6266 Y0355 N2820 X.6233 Y0387 N2830 X.6222 Y0426 N2840 X.6262 Y0496 N2850 X.6274 Y0503 N2860 X.6413 Y0531
→ M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534 N2250 X.7628 Y.0584 N2260 X.7579 Y.06 N2270 X.7476 Y.056 N2280 X.7462 Y.0551 N2290 X.7325 Y.0417 N2300 X.7372 Y.0353 N2310 X.7387 Y.0315 N2320 X.7384 Y.031 N2330 X.7378 Y.0309	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.651 Y0339 N2790 X.6385 Y0325 N2800 X.6275 Y0349 N2810 X.6266 Y0355 N2820 X.6233 Y0387 N2830 X.6222 Y0426 N2840 X.6262 Y0496 N2850 X.6274 Y0503 N2860 X.6413 Y0531 N2870 X.6544 Y0511
M3 N2140 G43 H5 Z.25 M8 N2150 Z.2 N2160 G1 Z001 F12.22 N2170 G3 X.735 Y.0339 I2076 J1392 → F30.56 N2180 G1 X.7309 Y.0397 N2190 X.7225 Y.0265 N2200 X.7157 Y.013 N2210 X.7421 Y.0259 N2220 X.751 Y.0324 N2230 X.7611 Y.0433 N2240 X.7644 Y.0534 N2250 X.7628 Y.0584 N2260 X.7579 Y.06 N2270 X.7476 Y.056 N2280 X.7462 Y.0551 N2290 X.7325 Y.0417 N2300 X.7372 Y.0353 N2310 X.7387 Y.0315 N2320 X.7384 Y.031 N2330 X.7378 Y.0309 N2340 X.735 Y.0339	N2660 X.6668 Y.0644 N2670 X.653 Y.0569 N2680 X.644 Y.0456 N2690 X.641 Y.0317 N2700 X.6437 Y.0195 N2710 X.6518 Y.01 N2720 X.6644 Y.0038 N2730 X.6644 Y.002 N2730 X.6807 Y.0017 N2740 X.6891 Y.002 N2750 X.6981 Y.0027 N2760 X.6804 Y027 N2770 X.6705 Y0385 N2780 X.651 Y0339 N2790 X.6385 Y0325 N2800 X.6275 Y0349 N2810 X.6266 Y0355 N2820 X.6233 Y0387 N2830 X.6222 Y0426 N2840 X.6262 Y0496 N2850 X.6274 Y0503 N2860 X.6413 Y0531 N2870 X.6544 Y0511 N2880 X.669 Y0443

N2910 X.7173 Y0491	N3450 X.7988 Y042
N2920 X.7179 Y0488	N3460 X.7993 Y0374
N2930 X.7355 Y0366	N3470 X.8199 Y0301
N2940 X.7401 Y0313	N3480 X.8238 Y0278
N2950 X.7422 Y0283	N3490 X.8307 Y0214
N2960 X.7418 Y0278	N3500 X.833 Y0147
N2970 X.7414 Y0274	N3510 X.8305 Y0091
N2980 X.7381 Y0304	N3520 X.8234 Y0068
N2990 X.7359 Y0334	N3530 X.8097 Y0108
N3000 X.722 Y0433	N3540 X.8086 Y0115
N3010 X.7082 Y0463	N3550 X.7928 Y0239
N3020 X.6931 Y0445	N3560 X.7884 Y0295
N3030 X.676 Y0401	N3570 Z.199 F12.22
N3040 X.6954 Y0208	N3580 GO Z.249
N3050 X.7124 Y.0069	N3590 Z.25
N3060 X.7385 Y.0197	N3600 X.8196 Y0254
N3070 X.7517 Y.0297	N3610 Z.2
N3080 X.7625 Y.0423	N3620 G1 Z001 F12.22
N3090 X.7662 Y.0536	N3630 X.8271 Y0158 F30.56
N3100 X.7638 Y.0594	N3640 X.8279 Y0119
N3110 X.7578 Y.0617	N3650 X.8267 Y0098
N3120 X.7459 Y.0578	N3660 X.8247 Y0085
N3130 X.729 Y.0455	N3670 X.8158 Y0125
N3140 X.7109 Y.06	N3680 X.8119 Y0162
N3150 X.7082 Y.0614	N3690 X.8015 Y0325
N3160 Z.199 F12.22	N3700 X.8005 Y0351
N3170 GO Z.249	N3710 X.8162 Y028
N3180 Z.25	N3720 X.8196 Y0254
N3190 X.7884 Y0295	N3730 Z.199 F12.22
N3200 Z.2	N3740 GO Z.249
N3210 G1 Z001 F12.22	N3750 Z.25
N3220 X.7867 Y0321 F30.56	N3760 X.8572 Y0325
N3230 X.7869 Y0325	N3770 Z.2
N3240 X.7873	N3780 G1 Z001 F12.22
N3250 X.7885 Y0316	N3790 X.8576 F30.56
N3260 X.7908 Y0288	N3800 X.8588 Y0321
N3270 X.7903 Y0323	N3810 X.8613 Y0301
N3280 X.7902 Y0357	N3820 X.8606 Y0339
N3290 X.7926 Y0463	N3830 X.8604 Y0372
N3300 X.794 Y0484	N3840 X.8627 Y0484
N3310 X.7984 Y0519	N3850 X.8632 Y0492
N3320 X.8042 Y0531	N3860 X.8666 Y0521
N3330 X.8147 Y0502	N3870 X.8712 Y0531
N3340 X.8279 Y0402	N3880 X.8814 Y0501
N3350 X.8348 Y0328	N3890 X.8931 Y041
N3360 X.8364 Y0302	N3900 X.8943 Y0411
N3370 X.836 Y0296	N3910 X.8967
N3380 X.8352 Y0291	N3920 X.9052 Y039
N3390 X.8317 Y033	N3930 X.9129 Y0325
N3400 X.8262 Y04	N3940 X.9146 Y0307
N3410 X.8145 Y0487	N3950 X.915 Y0305
N3420 X.8049 Y0514	N3960 X.9153 Y0302
N3430 X.8005 Y0495	N3970 X.9149 Y0295
N3440 X.7987 Y0441	N3980 X.9143 Y0291

N3990 X.9139 Y0295	N4530	X.9821 Y0179
N4000 X.9129 Y03	N4540	X.9912 Y01
N4010 X.9111 Y0319	N4550	X.9948 Y0085
N4020 X.9046 Y0374	N4560	X.9969 Y0091
N4030 X.8974 Y0394	N4570	X.9976 Y011
N4040 X.8955 Y0392	N4580	X.9964 Y0141
N4050 X.8951 Y039	N4590	X.9918 Y0212
N4060 X.9026 Y0283	N4600	X.9704 Y0531
N4070 X.905 Y0188	N4610	X.9823 Y0523
N4080 X.9018 Y0101	N4620	X1.0084 Y0203
N4090 X.8933 Y0068	N4630	X1.0173 Y0115
N4100 X.8802 Y0108	N4640	X1.0226 Y0085
N4110 X.879 Y0115	N4650	X1.0241 Y0094
N4120 X.8639 Y0237	N4660	X1.025 Y011
N4130 X.8581 Y0302	N4670	X1.021 Y0176
N4140 X.857 Y0321	N4680	X1.0202 Y0185
N4150 X.8572 Y0325	N4690	X1.0175 Y0217
N4160 Z.199 F12.22	N4700	X1.0097 Y0342
N4170 GO Z.249	N4710	X1.0079 Y042
N4180 Z.25	N4720	X1.0098 Y0501
N4190 X.8684 Y0501	N4730	X1.0151 Y0531
N4200 Z.2	N4740	X1.0215 Y05
N4210 G1 Z001 F12.22	N4750	X1.0325 Y0394
N4220 X.8718 Y0514 F30.56	N4760	X1.0336 Y0388
N4230 X.8792 Y0487	N4770	X1.0404 Y0306
N4240 X.888 Y0419		Y0302
N4250 X.8966 Y0293		X1.04 Y0296
N4260 X.8999 Y017		X1.0392 Y0291
N4270 X.8982 Y0109		X1.0362 Y0323
N4280 X.8933 Y0085		X1.0323 Y0374
N4290 X.8855 Y0119		X1.0215 Y0478
N4300 X.8763 Y0222		X1.0153 Y0514
N4310 X.8695 Y0348		X1.0134 Y0509
N4320 X.8673 Y0457		X1.013 Y0489
N4330 X.8684 Y0501		X1.0143 Y0439
N4340 Z.199 F12.22		X1.0202 Y035
N4350 GO Z.249		X1.0202 Y032
N4360 Z.25		X1.0294 Y0192
N4370 X.9378 Y0324		X1.0302 Y015
N4380 Z.2		X1.0285 Y0092
N4390 G1 Z001 F12.22		X1.0238 Y0068
N4400 X.9381 Y0325 F30.56		X1.0155 Y0108
N4410 X.9418 Y029		X1.0142 Y0119
N4420 X.9463 Y0246		X.9951 Y0318
N4430 X.9591 Y0119		X1.001 Y0224
N4440 X.9658 Y0085		X1.001 Y0224 X1.0027 Y0136
		X1.0027 Y0136 X1.0006 Y009
N4450 X.9678 Y0092 N4460 X.9684 Y0111		X1.0006 Y009 X.9959 Y0068
N4470 X.9644 Y0188		X.9866 Y0108
N4480 X.9637 Y0199		X.9844 Y0126
N4490 X.9626 Y0212		X.9661 Y032
N4500 X.9413 Y0531		X.9719 Y0225
N4510 X.9524 Y0523		X.9736 Y0148
N4520 X.9574 Y046	N5060	X.9715 Y009

N5070 X.9669 Y0068	N5610 Z.199 F12.22
N5080 X.9592 Y0098	N5620 GO Z.249
N5090 X.9466 Y0204	N5630 Z.25
N5100 X.9413 Y0265	N5640 X1.074 Y0502
N5110 X.9381 Y0302	N5650 Z.2
N5120 X.9376 Y032	N5660 G1 Z001 F12.22
N5130 X.9378 Y0324	N5670 X1.0769 Y0514 F30.56
N5140 Z.199 F12.22	N5680 X1.0838 Y0487
N5150 GO Z.249	N5690 X1.0925 Y0409
N5160 Z.25	N5700 X1.1033 Y0266
N5170 X1.0629	N5710 X1.1073 Y0144
N5180 Z.2	N5720 X1.1056 Y0101
N5190 G1 Z001 F12.22	N5730 X1.1013 Y0085
N5200 X1.0634 Y0325 F30.56	N5740 X1.0924 Y0124
N5210 X1.065 Y0316	N5750 X1.0825 Y0222
N5220 X1.0668 Y029	N5760 X1.0756 Y0355
N5230 X1.0663 Y0329	N5770 X1.073 Y0462
N5240 X1.0662 Y0369	N5780 X1.074 Y0502
N5250 X1.0684 Y0487	N5790 Z.199 F12.22
N5260 X1.0712 Y052	N5800 GO Z.249
N5270 X1.0752 Y0531	N5810 Z.25
N5280 X1.0852 Y0497	N5820 X1.152 Y0324
N5290 X1.0957 Y0401	N5830 Z.2
N5300 X1.0954 Y0434	N5840 G1 Z001 F12.22
N5310 X1.0953 Y0457	N5850 X1.1524 Y0325 F30.56
N5320 X1.0971 Y0512	N5860 X1.1561 Y029
N5330 X1.1022 Y0531	N5870 X1.1606 Y0247
N5340 X1.1101 Y0505	N5880 X1.1733 Y012
N5350 X1.1232 Y0391	N5890 X1.18 Y0085
N5360 X1.1292 Y033	N5900 X1.1821 Y0092
N5370 X1.1313 Y0301 N5380 X1.1308 Y0295	N5910 X1.1827 Y0112 N5920 X1.1787 Y0188
N5390 X1.1308 Y0295 N5390 X1.1301 Y0291	N5930 X1.1779 Y0199
N5400 X1.1271 Y0323	N5940 X1.1779 Y0199
N5410 X1.122 Y0374	N5950 X1.1769 Y0212
N5410 X1.122 10374 N5420 X1.1098 Y0483	N5960 X1.1667 Y0524
N5430 X1.1038 Y0521	N5970 X1.181 Y0357
N5440 X1.1008 Y0514	N5980 X1.1923 Y0251
N5450 X1.1000 Y0492	N5990 X1.1915 Y0301
N5460 X1.1016 Y0449	N6000 X1.1913 Y0333
N5470 X1.108 Y0358	N6010 X1.1931 Y038
N5480 X1.1264 Y0078	N6020 X1.1983 Y0394
N5490 X1.115 Y0082	N6030 X1.2069 Y0358
N5500 X1.1081 Y0178	N6040 X1.2119 Y0302
N5510 X1.1087 Y0158	N6050 X1.2114 Y0299
N5520 X1.109 Y0144	N6060 X1.2106 Y0291
N5530 X1.1066 Y009	N6070 X1.2061 Y0334
N5540 X1.0997 Y0068	N6080 X1.1971 Y0377
N5550 X1.0864 Y0108	N6090 X1.1941 Y0366
N5560 X1.086 Y011	N6100 X1.193 Y0335
N5570 X1.0702 Y0232	N6110 X1.1944 Y0266
N5580 X1.0647 Y0292	N6120 X1.2001 Y0204
N5590 X1.0627 Y0321	N6130 X1.2023 Y0187
N5600 X1.0629 Y0324	N6140 X1.2115 Y0107

N6150 X1.2119 Y0096	N6690 X1.2778 Y0493
N6160 X1.2106 Y0076	N6700 X1.2656 Y0469
N6170 X1.2076 Y0068	N6710 X1.2503 Y0445
N6180 X1.2004 Y0099	N6720 X1.2447 Y0457
N6190 X1.1941 Y0204	N6730 X1.2427 Y0479
N6200 X1.1796 Y0339	N6740 X1.2467 Y0518
N6210 X1.1795 Y034	N6750 X1.2471 Y0519
N6220 X1.1863 Y0222	N6760 X1.2589 Y0531
N6230 X1.1879 Y0143	N6770 X1.269 Y053
N6240 X1.1858 Y009	N6780 X1.2762
N6250 X1.1812 Y0068	N6790 X1.2862
N6260 X1.1735 Y0098	N6800 X1.2966 Y0531
N6270 X1.1609 Y0204	N6810 X1.3222 Y0503
N6280 X1.1556 Y0266	N6820 X1.3247 Y0496
N6290 X1.1524 Y0303	N6830 X1.3475 Y039
N6300 X1.1519 Y0321	N6840 X1.3649 Y0214
N6310 X1.152 Y0324	N6850 X1.3688 Y0152
N6320 Z.199 F12.22	N6860 X1.3745 Y0009
N6330 GO Z.249	N6870 X1.3764 Y.014
	N6880 X1.3735 Y.0305
N6340 Z.25	
N6350 X1.236 Y.0142	N6890 X1.365 Y.0453
N6360 Z.2 N6370 G1 Z001 F12.22	N6900 X1.3768 Y.0548
N6370 G1 Z001 F12.22	N6910 X1.3833 Y.0591
N6380 X1.2397 Y.0282 F30.56 N6390 X1.2502 Y.0463	N6920 X1.3829 Y.0593
	N6930 X1.3821 Y.06
N6400 X1.2594 Y.0553	N6940 X1.3738 Y.0569
N6410 X1.2725 Y.0627	N6950 X1.3615 Y.0485
N6420 X1.2867 Y.0652	N6960 X1.345 Y.0581
N6430 X1.2968 Y.0637	N6970 X1.344 Y.0584
N6440 X1.305 Y.0593	N6980 X1.3218 Y.0617
N6450 X1.2804 Y.0492	N6990 X1.3156 Y.0613
N6460 X1.2673 Y.0384	N7000 X1.3084 Y.0604
N6470 X1.2566 Y.0227	N7010 X1.2982 Y.0653
N6480 X1.253 Y.0059	N7020 X1.2874 Y.0669
N6490 X1.254 Y0018	N7030 X1.2687 Y.0629
N6500 X1.2593 Y0108	N7040 X1.2619 Y.0592
N6510 X1.2666 Y0155	N7050 X1.2512 Y.0501
N6520 X1.276 Y0171	N7060 X1.2428 Y.038
N6530 X1.2906 Y0136	N7070 X1.2363 Y.0223
N6540 X1.3038 Y0042	N7080 X1.2342 Y.009
N6550 X1.3157 Y.0136	N7090 X1.2344 Y.0073
N6560 X1.3199 Y.0333	N7100 X1.2348 Y.0069
N6570 X1.3178 Y.0458	N7110 X1.236 Y.0142
N6580 X1.312 Y.0569	N7120 Z.199 F12.22
N6590 X1.3189 Y.0578	N7130 GO Z.249
N6600 X1.3252 Y.0583	N7140 Z.25
N6610 X1.3443 Y.0552	N7150 X1.2653 Y0117
N6620 X1.3596 Y.0468	N7160 Z.2
N6630 X1.3359 Y.0194	N7170 G1 Z001 F12.22
N6640 X1.3169 Y0109	N7180 X1.2748 Y0154 F30.56
N6650 X1.3117 Y02	N7190 X1.2763
N6660 X1.298 Y039	N7200 X1.2898 Y0126
N6670 X1.2946 Y0422	N7210 X1.3017 Y0044
N6680 X1.2862 Y0475	N7220 X1.313 Y.0116
NOOOO AI.ZOOZ I .OTIO	MIZZO VI OTO I OTTO

N7230 X1.3139 Y.0135	N7770 X1.4382 Y0426
N7240 X1.3182 Y.0333	N7780 X1.4401 Y0503
N7250 Y.0336	N7790 X1.4456 Y0531
N7260 X1.3159 Y.0458	N7800 X1.4536 Y0494
N7270 X1.3089 Y.056	N7810 X1.4659 Y0383
N7280 X1.2885 Y.0457	N7820 X1.4711 Y0322
N7290 X1.2754 Y.0329	N7830 X1.4724 Y0301
N7300 X1.265 Y.0159	N7840 X1.472 Y0295
N7310 X1.2616 Y001	N7850 X1.4712 Y0291
N7320 X1.264 Y0101	N7860 X1.4679 Y0322
N7330 X1.2653 Y0117	N7870 X1.4639 Y0372
N7340 Z.199 F12.22	N7880 X1.4519 Y0483
N7350 GO Z.249	N7890 X1.4456 Y0514
N7360 Z.25	N7900 X1.4437 Y0509
N7370 X1.2926 Y0513	N7910 X1.4433 Y0489
N7380 Z.2	N7920 X1.4473 Y0393
N7390 G1 Z001 F12.22	N7930 X1.4475 Y039
N7400 X1.2996 Y0514 F30.56	N7940 X1.4677 Y0068
N7410 X1.3229 Y0486	N7950 X1.4562 Y0078
N7420 X1.3253 Y0479	N7960 X1.4372 Y035
N7430 X1.3464 Y0376	N7970 X1.4327 Y0399
N7440 X1.3466 Y0375	N7980 X1.4227 Y0485
N7450 X1.3633 Y021	N7990 X1.4148 Y0514
N7460 X1.3672 Y0147	N8000 X1.413 Y0505
N7470 X1.3743 Y.0064	N8010 X1.4124 Y0489
N7480 X1.3747 Y.0129	N8020 X1.4164 Y0402
N7490 X1.3717 Y.0293	N8030 X1.4197 Y0351
N7500 X1.3633 Y.0434	N8040 X1.421 Y0334
N7510 X1.3485 Y.0226	N8050 X1.4384 Y0068
N7520 X1.3444 Y.0154	N8060 X1.4254 Y0078
N7530 X1.3292 Y011	N8070 X1.4104 Y0252
N7540 X1.3091 Y0356	N8080 X1.4056 Y0322
N7550 X1.307 Y0376	N8090 X1.4057 Y0325
N7560 X1.2873 Y05	N8100 Z.199 F12.22
N7570 X1.2847 Y0509	N8110 GO Z.249
N7580 X1.2926 Y0513	N8120 Z.25
N7590 Z.199 F12.22	N8130 X1.4932 Y0324
N7600 GO Z.249	N8140 Z.2
N7610 Z.25	N8150 G1 Z001 F12.22
N7620 X1.4057 Y0325	N8160 X1.4936 Y0325 F30.56
N7630 Z.2	N8170 X1.4972 Y029
N7640 G1 Z001 F12.22	N8180 X1.5017 Y0247
N7650 X1.4061 F30.56	N8190 X1.5145 Y012
N7660 X1.4106 Y0278	N8200 X1.5212 Y0085
N7670 X1.4114 Y027	N8210 X1.5232 Y0092
N7680 X1.42 Y0167	N8220 X1.5239 Y0112
N7690 X1.4186 Y0184	N8230 X1.5199 Y0188
N7700 X1.4083 Y0381	N8240 X1.5191 Y0199
N7710 X1.4073 Y0428	N8250 X1.5181 Y0212
N7720 X1.4096 Y0504	N8260 X1.4969 Y0531
N7730 X1.4164 Y0531	N8270 X1.5078 Y0524
N7740 X1.4259 Y0493	N8280 X1.5221 Y0357
N7750 X1.4386 Y0385	N8290 X1.5334 Y0251
N7760 X1.4383 Y0411	N8300 X1.5327 Y0301

```
N8310 X1.5324 Y-.0333
                                             N8850 X1.64 Y-.033
N8320 X1.5342 Y-.038
                                            N8860 X1.6422 Y-.0301
N8330 X1.5395 Y-.0394
                                           N8870 X1.6417 Y-.0295
N8340 X1.5481 Y-.0358
                                            N8880 X1.6409 Y-.0291
N8350 X1.553 Y-.0302
                                             N8890 X1.6379 Y-.0323
N8360 X1.5526 Y-.0299
                                            N8900 X1.6328 Y-.0374
N8370 X1.5517 Y-.0291
                                            N8910 X1.6207 Y-.0483
N8380 X1.5473 Y-.0334
                                            N8920 X1.6137 Y-.0521
N8390 X1.5382 Y-.0377
                                             N8930 X1.6117 Y-.0514
N8400 X1.5353 Y-.0366
                                            N8940 X1.6113 Y-.0492
N8410 X1.5342 Y-.0335
                                            N8950 X1.6125 Y-.0449
N8420 X1.5356 Y-.0266
                                            N8960 X1.6188 Y-.0358
N8430 X1.5413 Y-.0204
                                             N8970 X1.6373 Y-.0078
N8440 X1.5434 Y-.0187
                                            N8980 X1.6259 Y-.0082
N8450 X1.5526 Y-.0107
                                             N8990 X1.619 Y-.0178
N8460 X1.553 Y-.0096
                                             N9000 X1.6195 Y-.0158
N8470 X1.5517 Y-.0076
                                             N9010 X1.6199 Y-.0144
N8480 X1.5488 Y-.0068
                                            N9020 X1.6174 Y-.009
N8490 X1.5416 Y-.0099
                                            N9030 X1.6106 Y-.0068
N8500 X1.5352 Y-.0204
                                            N9040 X1.5972 Y-.0108
N8510 X1.5207 Y-.0339
                                            N9050 X1.5968 Y-.011
N8520 X1.5206 Y-.034
                                            N9060 X1.581 Y-.0232
N8530 X1.5274 Y-.0222
                                            N9070 X1.5756 Y-.0292
N8540 X1.529 Y-.0143
                                             N9080 X1.5736 Y-.0321
N8550 X1.5269 Y-.009
                                            N9090 X1.5737 Y-.0324
N8560 X1.5223 Y-.0068
                                            N9100 Z.199 F12.22
N8570 X1.5146 Y-.0098
                                            N9110 GO Z.249
N8580 X1.502 Y-.0204
                                             N9120 Z.25
N8590 X1.4967 Y-.0266
                                            N9130 X1.5849 Y-.0502
N8600 X1.4935 Y-.0303
                                            N9140 Z.2
N8610 X1.493 Y-.0321
                                             N9150 G1 Z-.001 F12.22
N8620 X1.4932 Y-.0324
                                             N9160 X1.5877 Y-.0514 F30.56
N8630 Z.199 F12.22
                                            N9170 X1.5947 Y-.0487
N8640 GO Z.249
                                            N9180 X1.6034 Y-.0409
N8650 Z.25
                                             N9190 X1.6142 Y-.0266
N8660 X1.5737
                                            N9200 X1.6182 Y-.0144
N8670 Z.2
                                            N9210 X1.6165 Y-.0101
N8680 G1 Z-.001 F12.22
                                           N9220 X1.6121 Y-.0085
N8690 X1.5742 Y-.0325 F30.56
                                            N9230 X1.6033 Y-.0124
N8700 X1.5759 Y-.0316
                                            N9240 X1.5934 Y-.0222
N8710 X1.5777 Y-.029
                                            N9250 X1.5865 Y-.0355
N8720 X1.5772 Y-.0329
                                            N9260 X1.5839 Y-.0462
N8730 X1.577 Y-.0369
                                             N9270 X1.5849 Y-.0502
N8740 X1.5792 Y-.0487
                                            N9280 Z.199 F12.22
N8750 X1.5821 Y-.052
                                            N9290 GO Z.249
N8760 X1.5861 Y-.0531
                                            N9300 Z.25
N8770 X1.596 Y-.0497
                                             N9310 X1.6161 Y-.0024
N8780 X1.6066 Y-.0401
                                            N9320 Z.2
N8790 X1.6062 Y-.0434
                                            N9330 G1 Z-.001 F12.22
N8800 Y-.0457
                                             N9340 X1.6244 Y.002 F30.56
N8810 X1.6079 Y-.0512
                                            N9350 X1.6364 Y.0103
N8820 X1.6131 Y-.0531
                                            N9360 X1.6404 Y.0191
N8830 X1.621 Y-.0505
                                            N9370 X1.639 Y.0226
N8840 X1.6341 Y-.0391
                                             N9380 X1.6354 Y.024
```

```
N9390 X1.6297 Y.02
                                             N9930 X1.7271 Y-.0192
N9400 X1.6278 Y.0161
                                             N9940 X1.7279 Y-.015
N9410 X1.6251 Y.0095
                                            N9950 X1.7262 Y-.0095
N9420 X1.6165 Y.0019
                                            N9960 X1.7215 Y-.0075
N9430 X1.6113 Y-.0026
                                             N9970 X1.7127 Y-.0115
N9440 X1.6115 Y-.0032
                                            N9980 X1.7109 Y-.0129
N9450 X1.6122 Y-.0034
                                            N9990 X1.6912 Y-.032
N9460 X1.6161 Y-.0024
                                            N100 X1.6971 Y-.0225
N9470 Z.199 F12.22
                                             N110 X1.6987 Y-.0148
N9480 GO Z.249
                                             N120 X1.6967 Y-.009
N9490 Z.25
                                             N130 X1.692 Y-.0068
N9500 X1.6629 Y-.0324
                                             N140 X1.6843 Y-.0098
                                             N150 X1.6717 Y-.0204
N9510 Z.2
N9520 G1 Z-.001 F12.22
                                            N160 X1.6665 Y-.0265
N9530 X1.6633 Y-.0325 F30.56
                                            N170 X1.6632 Y-.0302
N9540 X1.6669 Y-.029
                                             N180 X1.6627 Y-.032
N9550 X1.6714 Y-.0246
                                             N190 X1.6629 Y-.0324
N9560 X1.6842 Y-.0119
                                            N200 Z.199 F12.22
N9570 X1.6909 Y-.0085
                                            N210 GO Z.249
N9580 X1.6929 Y-.0092
                                             N220 Z.25
N9590 X1.6936 Y-.0111
                                             N230 X.6475 Y-.0374
N9600 X1.6896 Y-.0188
                                             N240 Z.2
N9610 X1.6891 Y-.0196
                                             N250 G1 Z-.001 F12.22
N9620 X1.6878 Y-.0212
                                             N260 X.6368 Y-.036 F30.56
N9630 X1.6666 Y-.0531
                                            N270 X.6285 Y-.0381
N9640 X1.6775 Y-.0523
                                            N280 X.6256 Y-.0428
N9650 X1.7052 Y-.0207
                                             N290 X.6296 Y-.0489
N9660 X1.7147 Y-.0121
                                             N300 X.6301 Y-.0492
N9670 X1.7203 Y-.0092
                                             N310 X.6414 Y-.0514
N9680 X1.7222 Y-.0095
                                             N320 X.6531 Y-.0493
N9690 X1.7227 Y-.011
                                             N330 X.6644 Y-.0427
N9700 X1.7187 Y-.0176
                                             N340 X.6475 Y-.0374
N9710 X1.7179 Y-.0185
                                             N350 Z.199 F12.22
N9720 X1.7152 Y-.0217
                                             N360 GO Z.25
N9730 X1.7074 Y-.0342
                                             N370 M5
N9740 X1.7056 Y-.042
                                             N380 G91 G28 Z0. M9
N9750 X1.7075 Y-.0501
                                             N390 .
N9760 X1.7128 Y-.0531
                                             N400 M01
N9770 X1.7193 Y-.05
                                             N410 T4 M6
N9780 X1.7302 Y-.0394
                                             N420 GO G90 G17 G54 X-.1647 Y.4501 . S8862
N9790 X1.7314 Y-.0388
N9800 X1.7381 Y-.0306
                                            N430 G43 H4 Z.25 M8
N9810 X1.7382 Y-.0302
                                             N440 Z.2
N9820 X1.7377 Y-.0296
                                             N450 G1 Z-.26 F11.74
N9830 X1.7369 Y-.0291
                                             N460 X-.0825 Y.3559 F14.44
N9840 X1.7339 Y-.0323
                                             N470 G3 X.0117 Y.313 I.0942 J.0821
N9850 X1.7301 Y-.0374
                                             N480 X.0939 Y.3438 IO. J.125
N9860 X1.7193 Y-.0478
                                             N490 G2 X.3937 Y.4562 I.2998 J-.3438
N9870 X1.713 Y-.0514
                                             N500 X.4557 Y.452 IO. J-.4562
N9880 X1.7111 Y-.0509
                                             N510 G1 X.8532 Y.3974
N9890 X1.7107 Y-.0489
                                             N520 X.9255 Y.3875 Z-.187
N9900 X1.712 Y-.0439
                                             N530 X1.3305 Y.3319
N9910 X1.7179 Y-.035
                                             N540 G3 X1.4004 Y.3251 I.12 J.8742
N9920 X1.7198 Y-.032
                                             N550 X1.4505 Y.3237 Z-.2371 I.0501 J.881
```

```
N560 X1.4733 Y.324 Z-.26 IO. J.8824
```

N570 X1.9455 Y.4756 I-.0228 J.8821

N580 G1 X2.4637 Y.8267

N590 G2 X2.7416 Y.912 I.2779 J-.4102

N600 X3.0995 Y.7592 IO. J-.4955

N610 X3.3253 Y.418 I-.7767 J-.7592

N620 X3.3511 Y.3497 Z-.187 I-1.0025 J-.418

N630 X3.4089 YO. I-1.0283 J-.3497

N640 X3.4019 Y-.1227 I-1.0861 JO.

N650 X3.3913 Y-.1949 Z-.26 I-1.0791 J.1227

N660 X3.0995 Y-.7592 I-1.0685 J.1949

N670 X2.7416 Y-.912 I-.3579 J.3427

N680 X2.4637 Y-.8267 IO. J.4955

N690 G1 X1.9502 Y-.4788

N700 X1.9455 Y-.4756 Z-.2542

N710 G3 X1.8884 Y-.44 Z-.187 I-.495 J-.7305

N720 X1.4505 Y-.3237 I-.4379 J-.7661

N730 X1.4297 Y-.3239 IO. J-.8824

N740 X1.3569 Y-.3287 Z-.26 I.0208 J-.8822

N750 X1.3305 Y-.3319 I.0936 J-.8774

N760 G1 X.4557 Y-.452

N770 G2 X.3937 Y-.4562 I-.062 J.452

N780 X-.0625 YO. IO. J.4562

N790 X.0939 Y.3438 I.4562 JO.

N800 G3 X.1367 Y.438 I-.0822 J.0942

N810 X.1059 Y.5202 I-.125 JO.

N820 G1 X.0237 Y.6144

N830 Z-.06 F11.74

N840 GO Z.25

N850 M5

N860 G91 G28 Z0. M9

N870 G28 XO. YO. .

N880 M30

%

Chapter 2

Plot in NCViewer



