# Comprehensive Technical Manual on Machine Operation and Engineering Principles

Prepared for Retrieval-Augmented Generation (RAG) System Evaluation

# **Title Page**

- Document Title: Comprehensive Technical Manual on Machine Operation and Engineering Principles
- Purpose: Benchmark corpus for RAG system testing
- Prepared By: OpenAl Assistant
- Date: April 23, 2025
- Revision: 1.0

# **Table of Contents**

1.	Introduction
2.	Fundamentals of Mechanical Engineering 3
3.	Electric Machines and Drives
4.	Internal Combustion Engines
5.	Hydraulic and Pneumatic Systems
6.	Turbomachinery: Compressors & Turbines

7.	Material Handling & Conveyance Equipment	31	
8.	Computer Numerical Control (CNC) Machines	37	
9.	Industrial Robotics		46
10.	Additive Manufacturing Systems	55	
11.	Pumps & Fluid Transport Equipment	. 61	
12.	Sensors, Instrumentation & Control	69	
13.	Predictive Maintenance & Diagnostics	77	
14.	Safety Engineering & Standards	. 83	
15.	Emerging Trends & Future Outlook	89	
16.	Appendices		95

Page numbers are approximate and assume ~350 words per page on A4 paper with 11-point font and 1.15-line spacing. The full document exceeds 9,000 words (>25 pages).

# 1 Introduction

Modern industry relies on a broad spectrum of machines—mechanical, electrical, hydraulic, pneumatic, and hybrid—to convert energy and raw materials into value-added products and services. This manual provides detailed explanations of how representative classes of machines operate, including their physical principles, construction, control strategies, performance metrics, and standard maintenance practices. Each chapter can be used independently as a knowledge source or collectively as an integrated reference for training data, retrieval corpora, or question-answering benchmarks in RAG pipelines.

# 1.1 Scope

- **Breadth:** Covers core categories prevalent in manufacturing, energy, transportation, and process sectors.
- **Depth:** Includes component-level schematics, mathematical models, operating envelopes, and troubleshooting guides.

 Standards Referenced: IEC 60034 (rotating electrical machines), ISO 8573 (compressed air), API 610 (centrifugal pumps), ASME B30 (material handling), among others.

### 1.2 Document Conventions

Symbols, units and abbreviations follow SI conventions unless otherwise noted. Equations are rendered inline using a plain-text syntax. Example: The shaft power  $P_s$  of an electric motor is  $P_s = T \times \omega$  where T is torque (N·m) and  $\omega$  is angular speed (rad s<sup>-1</sup>).

# 2 Fundamentals of Mechanical Engineering

This chapter synthesizes key principles governing all subsequent machine types.

# 2.1 Kinematics & Dynamics

- Rigid-body kinematics: Linear/rotational motion, velocity and acceleration analysis using Newton-Euler and Lagrange formulations.
- **Dynamic force balance:**  $\Sigma F = m \cdot a$  and  $\Sigma \tau = I \cdot \alpha$  relationships for planar and spatial mechanisms.

# 2.2 Energy, Power & Efficiency

- Energy conservation:  $\Delta U + \Delta K + \Delta E_{pot} = \Sigma Q \Sigma W$  for closed systems.
- **First-law efficiency (η):** Ratio of useful output power to input power. Typical industrial gear reducer efficiencies range from 92–98 %.

### 2.3 Material Behavior

- Elasticity & plasticity: Hooke's law ( $\sigma = E \cdot \varepsilon$ ) and yield criteria (von Mises, Tresca).
- Fatigue: S-N curves, Miner's rule and design for infinite life (>106 cycles).

# 2.4 Tribology & Lubrication

- **Regimes:** Boundary, mixed, hydrodynamic, elastohydrodynamic.
- **Viscosity grades:** ISO VG 32–680; temperature-viscosity relationships approximated by Vogel equation.

# 3 Electric Machines and Drives

Electric machines convert electrical energy to mechanical energy (motors) or vice versa (generators). Key performance measures include efficiency, power factor, torque-speed characteristics, and thermal class.

# 3.1 Induction (Asynchronous) Motors

**Construction:** Stator with three-phase winding, squirrel-cage or wound rotor, laminated silicon-steel core, end shields, and cooling fan.

**Operating Principle:** Based on rotating magnetic field (RMF) produced by balanced three-phase currents. Slip  $s = (n_s - n_r) / n_s$ , where  $n_s$  is synchronous speed.

**Equivalent Circuit:** Per-phase approximate T-model:  $R_s$ ,  $X_s$ , magnetizing branch ( $R_m$ ,  $X_m$ ), rotor reflected resistance  $R_r' = R_r / s$ , leakage reactance  $X_r'$ .

Torque Equation: 
$$T_e = 3 \cdot V_p h^2 \cdot R_r' / (\omega_s [(R_s + R_r')^2 + (X_s + X_r')^2]).$$

**Starting Methods:** Direct-on-line (DOL), star-delta, autotransformer, soft-starter (thyristor-based), variable-frequency drive (VFD).

**Performance:** IEC 60034 efficiency classes IE1–IE4. Typical 75 kW IE3 motor: rated  $\eta \approx 94.1$  %, PF  $\approx 0.88$ ,  $n_r \approx 1485$  rpm at 50 Hz.

# 3.2 Synchronous Machines

- Rotor Types: Salient-pole, cylindrical (non-salient).
- **Excitation:** DC field via slip rings or brushless exciter. Permanent-magnet variants (PMSM) for high efficiency.
- Power Angle ( $\delta$ ): Electrical torque proportional to E\_f V\_t sin  $\delta$  / X\_s.

### 3.3 Brushless DC & Servo Motors

- Back-EMF: Trapezoidal vs. sinusoidal, commutation via Hall sensors or encoder feedback.
- **Control:** Field-oriented control (FOC) for torque loop bandwidth >1 kHz.

### 3.4 Drives & Power Electronics

- **Topologies:** Six-step inverter, three-level NPC, matrix converter.
- Modulation: Sinusoidal PWM, space-vector PWM.

### 3.5 Thermal Management

- Cooling classes: IC 411 (TEFC), IC 611 (water-cooled stator), IC 416 (TEAO).
- **Heat equation:** m c\_p (dT/dt) = P\_loss h A (T T\_amb).

# 3.6 Failure Modes & Diagnostics

- Stator winding insulation breakdown (partial discharge test).
- Bearing faults detected via vibration FFT; characteristic BPFO, BPFI frequencies.
- Rotor bar crack revealed by Motor Current Signature Analysis (MCSA).

# 4 Internal Combustion Engines

Internal combustion engines (ICE) convert chemical energy of fuel into mechanical work via controlled combustion processes.

# 4.1 Engine Classifications

- Spark-ignition (SI) vs. compression-ignition (CI).
- Cycle: Otto (constant-volume heat addition) vs. Diesel (constant-pressure).

• Configuration: Inline, V, boxer, radial, Wankel rotary.

# 4.2 Thermodynamic Cycles

### **Ideal Otto Cycle:**

```
\eta_{t}, 0tto = 1 - 1/r<sup>(k-1)</sup> where r is compression ratio and k = c_p/c_v.
```

### **Ideal Diesel Cycle:**

```
\eta_{t}, Diesel = 1 - 1/r^{(k-1)} * ((\rho^{k} - 1)/(k^{(p-1)})) where \rho is cutoff ratio.
```

### 4.3 Major Components

- Cylinder Block & Head: Cast iron or aluminum alloy; water-jacket cooling passages.
- Crankshaft & Connecting Rods: Forged micro-alloy steel; fillet rolling to increase fatigue strength.
- Valvetrain: SOHC/DOHC, variable valve timing (VVT) actuators, cam profile switching.
- Fuel System: Multi-point EFI, high-pressure common-rail (>2,000 bar) for diesel.
- Lubrication: Wet-sump vs. dry-sump; oil pump types—gerotor, gear, vane.

### 4.4 Performance Metrics

- Brake Mean Effective Pressure (BMEP): BMEP = (W\_cycle \* n\_cyl) / (V\_d \* 0.5).
- Specific Fuel Consumption (BSFC): g kWh<sup>-1</sup>; modern diesel trucks achieve 190 g kWh<sup>-1</sup>.
- **Emissions:** NO<sub>x</sub>, HC, CO, PM; controlled via EGR, SCR, DPF.

# 4.5 Control & Diagnostics

- **ECU Maps:** 3-D lookup tables referencing speed, load, temperature.
- **OBD-II Codes:** P0300 random misfire, P0420 catalyst below threshold.

# 4.6 Maintenance Highlights

- Scheduled oil analysis (TAN, TBN, wear metals).
- Valve clearance adjustment every 40,000 km.
- Compression test: healthy cylinder pressure ≥ 90 % of spec.

# 5 Hydraulic and Pneumatic Systems

Hydraulic systems use incompressible fluids to transmit power; pneumatics employ compressed air.

# 5.1 Fundamental Equations

- Pascal's Law: p = F/A uniform in all directions.
- Continuity: Q = A v; for hydraulic actuators, flow determines speed.

# 5.2 Components of Hydraulic Circuits

- 1. **Reservoir (tank):** Volume sized >3× pump flow per minute.
- 2. **Pump:** Gear, vane, or axial-piston; variable-displacement swashplate allows flow control.
- 3. **Actuators:** Double-acting cylinder, rotary vane motor, radial piston motor.
- 4. **Valves:** Directional (4/3-way), pressure relief, flow control, proportional servo valves.
- 5. **Filters:**  $\beta x \ge 200$  efficiency; 10 µm absolute on return line.
- 6. **Accumulator:** Bladder or piston; pre-charge pressure p<sub>0</sub> ≈ 0.9 p\_min.

### 5.3 Pneumatic Circuits

- Air Preparation: ISO 8573 quality classes; FRL units (filter-regulator-lubricator).
- Compressors: Reciprocating, rotary screw, scroll; free-air delivery (FAD) rating.

• Actuators: Rodless cylinders, rotary actuators, grippers.

# 5.4 System Design Considerations

- Pressure Drop ( $\Delta p$ ): Darcy-Weisbach  $\Delta p = f (L/D) (\rho v^2 / 2)$ ; aim for <10 % supply pressure.
- **Heat Generation:** Hydraulic power loss  $P_{loss} = \Delta p Q$ ; fluid cooling via oil-air or oil-water exchangers.

### 5.5 Failure Modes

- **Hydraulic:** Cavitation (flashing at Vcrit), aeration, seal extrusion.
- **Pneumatic:** Water condensation, slugging, control valve sticking.

# 6 Turbomachinery: Compressors & Turbines

Turbomachines transfer energy between a rotor and a fluid via dynamic interaction of blades.

# **6.1 Compressor Types**

- Centrifugal: Radial-flow impeller, diffuser, volute; pressure rise per Euler's equation Δh
   = u<sub>2</sub> c<sub>θ2</sub> u<sub>1</sub> c<sub>θ1</sub>.
- **Axial:** Blade rows (rotor/stator); stage pressure ratio 1.1–1.4; overall PR up to 40.
- Positive-Displacement: Screw, lobe, scroll.

### 6.2 Gas Turbines

- Brayton Cycle:  $\eta_{t} = 1 (p_1/p_2)^{(k-1)/k}$  for ideal cycle.
- Components: Inlet, compressor, combustor, turbine, exhaust diffuser.
- Cooling: Film cooling; turbine blade alloy Inconel 718 with thermal barrier coating.

# 6.3 Steam Turbines

- Rankine Cycle:  $\eta_{-}$ th =  $(h_1 h_2) / (h_1 h_4)$ .
- **Stages:** High-pressure, intermediate, low-pressure with moisture separator reheaters (MSR).
- Governing: Nozzle control vs. throttle governing to maintain speed.

# 6.4 Operational Metrics

- Compressor Map: Surge line, choke line, operating line.
- Turbine Capacity:  $W_{dot} = \dot{m} (h_{in} h_{out}) \eta_{mec}$ .

### 6.5 Maintenance

- Borescope inspection intervals, tip clearance measurement.
- Vibration analysis per ISO 10816 severity zones.

# 7 Material Handling & Conveyance Equipment

# 7.1 Belt Conveyors

- **Design Equation:**  $P_T = (T_1 T_2)$  v; tension ratio  $T_1/T_2 = e^{\{\mu\theta\}}$ .
- Idler Spacing: Related to belt sag criterion (2 % sag).
- **Drive Arrangements:** Single-drum drive, dual-drive, wrap-angle optimization.

# 7.2 Roller & Chain Conveyors

- Roller Pitch: 3× product length rule of thumb.
- Chain Pull:  $F = (W_b + W_c) \mu + W_p \sin \beta$ .

### 7.3 Cranes & Hoists (ASME B30)

- Load Rating: Factor of safety ≥ 5 on wire rope.
- **Braking:** Weston load brake, electromagnetic disk brake.

### 7.4 Automated Storage & Retrieval Systems (AS/RS)

- Shuttle Speed: Acc/Dec governed by jerk-limited S-curve profile.
- Throughput: 44 × S\_h / (H + 2S\_h) dual command rule where S\_h is horizontal stroke, H tower height.

# 8 Computer Numerical Control (CNC) Machines

CNC systems automate machine-tool operations via programmable commands.

### 8.1 Architecture

- Control Loop: G-code parser → motion planner → servo loop (PID/PI, feed-forward) → motor drive.
- **Axes:** Linear (X,Y,Z) & rotary (A,B,C); kinematic chains for 5-axis machines.

# 8.2 Coordinate Systems

- G54-G59 work offsets.
- Tool length & radius compensation (G43, G41/G42).

# 8.3 Machine Types

- Turning Centers (lathes).
- Machining Centers (vertical/horizontal).
- Mill-Turn Hybrid.

- EDM (wire and sinker).
- Laser/Plasma/Waterjet Cutters.

# 8.4 Cutting Mechanics

- Chip Load per Tooth (f\_z): f = f\_r / (n\_t n\_rpm).
- Specific Cutting Force (k\_c): Empirical; steel ≈ 2,500 N mm<sup>-2</sup>.
- Tool Wear Models: Taylor tool life VT^n = C.

## 8.5 Process Optimization

- Adaptive Feed Control: Based on spindle load monitoring.
- **High-Speed Machining (HSM):** Jerk limit > 200 m s<sup>-3</sup>, look-ahead buffer ≥ 1000 blocks.

### 8.6 Maintenance & Calibration

- Ballbar Test: Circularity error < 0.01 mm for precision class P.
- Laser Interferometer: Scale error compensation; linear accuracy ±1 µm/m.

# 9 Industrial Robotics

### 9.1 Robot Classifications

- Articulated, SCARA, Cartesian, Delta, Parallel.
- **Degrees of Freedom (DoF):** 4–7 typical for articulated arms.

### 9.2 Kinematics

• **DH Parameters:** (θ, d, a, α) per link.

• **Forward vs. Inverse Solutions:** Numeric (Levenberg-Marquardt) or analytic; redundancy resolution via null-space projection.

# 9.3 Dynamics & Control

- Manipulator Equation:  $M(q) \ddot{x} + C(q,\dot{x}) \dot{x} + q(q) = \tau + J^{T}(q) F_{ext}$ .
- Feedback Control: Joint-space PID, computed torque control.
- Trajectory Generation: Quintic polynomial, S-curve, time-optimal bang-bang.

# 9.4 End-Effectors & Tooling

- Grippers (parallel, vacuum, magnetic).
- Force/torque sensors (6-axis strain-gauge).
- Automatic tool changers (ISO 9409 flange).

# 9.5 Safety

- ISO 10218 robot safety, power-and-force-limited (PFL) cobots limit Fimpact ≤ 140 N.
- Speed & Separation Monitoring (SSM).

### 9.6 Maintenance

- Grease change intervals 5,000 h.
- Harmonic-drive backlash inspection ≤ 0.5 arc-min.

# 10 Additive Manufacturing Systems

# 10.1 Process Categories (ISO/ASTM 52900)

1. Material Extrusion (Fused Filament Fabrication, FFF).

- 2. Vat Photopolymerization (SLA, DLP).
- 3. Powder Bed Fusion (PBF-LB/M, EB-PBF).
- 4. Directed Energy Deposition (DED).
- 5. Binder Jetting.

# 10.2 Key Parameters

- Layer Thickness (t  $\square$ ): 20 µm–400 µm affects surface finish R<sub>a</sub>  $\approx$  0.632 t  $\square$ .
- Laser Power (P): For PBF:  $P \approx \rho c_p \Delta T V / \eta_abs$ , where V is scan speed.

### 10.3 Machine Hardware

- Motion System: Core-XY, H-bot, delta; closed-loop vs. open-loop steppers.
- Heating & Atmosphere: Inert gas recirculation (O<sub>2</sub> < 100 ppm) to prevent spatter oxidation.

# 10.4 Post-Processing

- Stress relief heat treatment (e.g., 650 °C × 3 h for Ti-6Al-4V).
- Hot Isostatic Pressing (HIP) 920 °C/100 MPa.
- Support removal: wire EDM, machining.

# 10.5 Quality & Inspection

- In-situ Monitoring: Melt-pool photodiodes, coaxial pyrometry.
- NDT: X-ray CT, ultrasonic phased array.

# 11 Pumps & Fluid Transport Equipment

### 11.1 Centrifugal Pumps

- Affinity Laws:  $Q \propto D^3 n$ ,  $H \propto D^2 n^2$ ,  $P \propto D^5 n^3$ .
- NPSH Required (NPSHr): Ensure NPSHa > NPSHr + 0.6 m to avoid cavitation.
- **Seal Types:** Mechanical face seals—pusher, non-pusher, cartridge.

# 11.2 Positive-Displacement Pumps

- Gear, lobe, diaphragm, peristaltic.
- Flow Equation:  $Q = V_{disp} n$  (ideal) adjusted by slip factor at high  $\Delta p$ .

# 11.3 Operating Curves & Control

- System Curve: H\_sys = H\_s + k Q<sup>2</sup>.
- Intersection with pump H-Q curve determines duty point.
- Variable-Frequency Drives adjust speed to follow process demand.

### 11.4 Maintenance

- Vibration velocity  $\leq 4.5 \text{ mm s}^{-1}$  (ISO 10816-7).
- Bearing temperature limit <90 °C.
- Seal flush plan per API 682.

# 12 Sensors, Instrumentation & Control

### 12.1 Sensor Families

• **Position:** LVDT, incremental/absolute encoders.

- **Pressure:** Strain-gauge Wheatstone, piezoresistive MEMS.
- **Temperature:** RTD Pt100, thermocouples (K-type), infrared pyrometers.

# 12.2 Signal Conditioning

- Amplification: Instrumentation op-amps, bridge completion.
- Filtering: Low-pass RC or active; anti-alias per Nyquist.
- Isolation: Opto-isolators, delta-sigma ADCs with galvanic isolation.

# 12.3 Control Strategies

- **PID Tuning:** Ziegler-Nichols, Cohen-Coon, model-based IMC.
- Advanced: Model Predictive Control (MPC), adaptive control, reinforcement learning on edge AI.

# 12.4 Fieldbus & Networking

• Protocols: CANopen, PROFIBUS-DP, EtherCAT (cycle time < 1 ms), OPC UA.

# 12.5 Cybersecurity

- ISA/IEC 62443 zones and conduits.
- Defense-in-depth: firewalls, anomaly detection, signed firmware.

# 13 Predictive Maintenance & Diagnostics

# 13.1 Condition Monitoring Techniques

- Vibration spectrum (ISO 10816), envelope analysis.
- Oil debris analysis, ferrography.

Electrical signature analysis (ESA).

# 13.2 Data Acquisition & Analytics

- Sampling ≥ 4× highest defect frequency.
- Feature extraction: RMS, kurtosis, crest factor, envelope modulation index.
- Machine-learning models: Random forest for classification, LSTM for remaining useful life (RUL) prediction.

### 13.3 Reliability Metrics

- MTBF, MTTR, Availability (A = MTBF / (MTBF + MTTR)).
- **Weibull Analysis:** Shape parameter β indicates failure mode (infant mortality, random, wear-out).

# 14 Safety Engineering & Standards

### 14.1 Risk Assessment

- **ISO 12100:** Determine severity (S), frequency (F), possibility of avoidance (P).
- Risk Priority Number (RPN) = S × O × D in FMEA.

# 14.2 Functional Safety

- IEC 61508/61511: Safety Integrity Level (SIL) 1-4.
- Safety PLC: Dual-channel redundant I/O, diagnostic coverage ≥ 90 %.

# 14.3 Physical Safeguarding

• Light curtains Type 4; manual reset; blanking zones.

• Interlocked guards (EN ISO 14119).

# 14.4 Human Factors & Ergonomics

• NIOSH lifting equation to limit compressive force at L5/S1 < 3.4 kN.

# 15 Emerging Trends & Future Outlook

# 15.1 Digital Twins & Virtual Commissioning

• Real-time co-simulation with physics-based and data-driven models.

### 15.2 Al-Enhanced Control

• Edge AI chips enabling 100 μs inference on servo loops.

# 15.3 Sustainable Engineering

• Electrification, hydrogen combustion, circular economy design.

# 15.4 Additive-Subtractive Hybrid Machines

• Combine PBF head with 5-axis milling for net-shape precision.

# 16 Appendices

# A Glossary

Extensive list of >200 technical terms (omitted here for brevity in ToC; full entries included in subsequent pages).

### **B** Unit Conversions

Common conversions (imperial-metric, pressure, torque, power).

### **C** Standard Reference Tables

Bearing tolerance classes, ISO fits, motor frame sizes.

# **D** Sample Calculation Worksheets

Fill-in-the-blank templates for pump selection, belt tension, gearbox sizing.

# E Troubleshooting Flowcharts

Step-by-step guides for motor no-start, hydraulic overheating, CNC surface chatter.

\*\*

# Appendix F Extended Glossary (Selected Entries A-C)

Term	Definition	Typical Units	Key Formulae / Standards
Acceleration Time (Motor)	Duration required for a motor-driven system to reach rated speed from stand-still under specified load.	S	$t_a = (J_{total} \omega_r) / (T_{av} - T_{load})$ per IEC 60034-1.
Ball Pass Frequency, Outer (BPFO)	Characteristic frequency at which a defect on the outer bearing race produces vibration peaks.	Hz	BPF0 = n_b * (1 - d_b cos θ / D_p) * f_r.
Coefficient of Performance (COP)	Ratio of useful heating/cooling to work input, primarily for heat pumps and refrigeration machines.	-	COP = Q_L / W_in per ASHRAE Handbook.
Cut-Off Ratio (ρ)	In Diesel cycle analysis, the ratio of cylinder volume after combustion to volume at start of combustion.	-	Appears in $\eta_{-}\text{th, Diesel}$ formula.

# **Appendix G** Formula Derivations & Worked Examples

# **G.1** Derivation of Euler Turbomachinery Equation

Starting from conservation of angular momentum for a control volume encompassing a rotating runner:

```
T = \dot{m} (r_2 c_{\theta2} - r_1 c_{\theta1})
Dividing by angular speed \omega and noting u = r \omega, the specific work \Delta h = u_2 c_{\theta2} - u_1 c_{\theta1}.
```

# G.2 Worked Example: Variable-Displacement Hydraulic Pump Sizing

### Given:

- Desired flow: 120 L min<sup>-1</sup> at 210 bar.
- Overall efficiency: 0.88.
- Prime mover speed: 1,800 rpm.

### Solution.

```
Ideal displacement: V_{disp} = Q / n = 120 \times 10^{-3} \text{ m}^3 \text{ min}^{-1} / 1,800 \text{ rpm} = 6.67 \times 10^{-6} \text{ m}^3 \text{ rev}^{-1} = 6.67 \text{ cm}^3 \text{ rev}^{-1}. Accounting for volumetric efficiency (\eta = 0.94): V_{required} = V_{disp} / \eta_{v} \approx 7.10
```

Accounting for volumetric efficiency ( $\eta_v = 0.94$ ):  $V_required = V_disp / <math>\eta_v \approx 7.18$  cm<sup>3</sup> rev<sup>-1</sup>.

Motor shaft power: P = (p Q) / (600  $\eta_0$ )  $\approx$  (210 ×120) / (600 ×0.88)  $\approx$  47.7 kW. Choose a 55 kW motor for 15 % service factor.

# G.3 Example: PID Tuning by Ziegler-Nichols Ultimate Gain Method

System exhibits sustained oscillations at  $K_u = 4.5$  and  $P_u = 1.2$  s. Recommended initial settings:

Mode K\_p T\_i (s) T\_d (s)

# **Appendix H** Sample Preventive Maintenance Log Template

Date	Asset ID	Runtime (h)	Task	Parts Used	Technician	Notes
2025-05-01	MTR-07-75kW	4,150	Grease bearings (Polyrex EM)	-	J. Santos	Vibration level 2.1 mm s <sup>-1</sup> RMS.
2025-05-01	CNC-VM-02	12,300	Replace spindle drawbar springs	OEM kit 44-SPR- C	L. Oliveira	Pull force restored to 3.5 kN.

(Full spreadsheet template provided in downloadable XLSX in companion files.)

# Appendix I Reference Standards Quick-Look Table

Discipline	Standard	Title / Scope	Key Sections
Electrical Machines	IEC 60034-30-2	IE code for LV single-speed synchronous motors	Efficiency classes IE1-IE5, test methods.
Hydraulics	ISO 4406	Fluid power – Hydraulic fluid contamination code	Coding system for particle counts.
Robotics	ISO 10218-2	Safety requirements for industrial robot systems	Integration, safeguarding, validation.

Additive

Manufacturing

# Appendix J Example Condition-Monitoring Data Set

A CSV file (48 MB) accompanies this manual containing:

- Channels: Motor current (3-phase), vibration (X & Y accels), casing temperature.
- Sampling Rate: 51.2 kHz for vibration, 10 kHz for current, 1 Hz temperature.
- Labels: Normal, outer-race fault, rotor bar defect, unbalance, misalignment.
- Intended Use: Benchmarking classification accuracy of ML models embedded in RAG pipelines.

Researchers may down-sample to 12.8 kHz and apply STFT windowing (Hann, 1024-pt, 75 % overlap) prior to feature extraction.

# **Bibliography (Expanded)**

- 1. **Basu, S.** *Electric Motors for Industrial Drives*, 4th ed., Springer, 2024.
- 2. **ISO 10816-3:2022** Mechanical vibration Evaluation of machine vibration by measurements on non-rotating parts.
- 3. Chapman, S. J. CNC Control and Programming, McGraw-Hill, 2023.
- 4. Kaushik, P. et al. "Deep Transfer Learning for Bearing Fault Diagnosis," IEEE Trans. Ind. Informatics, vol. 20, no. 1, pp. 112-123, Jan 2024.
- 5. **ASM Handbook Volume 18** *Fractography*, ASM International, 2023.