## 3GPP TS 38.133 V16.7.0 (2021-03)

Technical Specification

3rd Generation Partnership Project; Technical Specification Group Radio Access Network; NR; Requirements for support of radio resource management (Release 16)





A GLOBAL INITIATIV

The present document has been developed within the 3rd Generation Partnership Project (3GPP<sup>TM</sup>) and may be further elaborated for the purposes of 3GPP. The present document has not been subject to any approval process by the 3GPP Organizational Partners and shall not be implemented. This Specification is provided for future development work within 3GPP only. The Organizational Partners accept no liability for any use of this Specification. Specifications and Reports for implementation of the 3GPP TM system should be obtained via the 3GPP Organizational Partners' Publications Offices.

## 3GPP

Postal address

3GPP support office address

650 Route des Lucioles - Sophia Antipolis Valbonne - FRANCE Tel.: +33 4 92 94 42 00 Fax: +33 4 93 65 47 16

Internet

http://www.3gpp.org

## **Copyright Notification**

No part may be reproduced except as authorized by written permission. The copyright and the foregoing restriction extend to reproduction in all media.

© 2021, 3GPP Organizational Partners (ARIB, ATIS, CCSA, ETSI, TSDSI, TTA, TTC). All rights reserved.

UMTS<sup>TM</sup> is a Trade Mark of ETSI registered for the benefit of its members 3GPP<sup>TM</sup> is a Trade Mark of ETSI registered for the benefit of its Members and of the 3GPP Organizational Partners LTE<sup>TM</sup> is a Trade Mark of ETSI registered for the benefit of its Members and of the 3GPP Organizational Partners GSM® and the GSM logo are registered and owned by the GSM Association

## Contents

Forew	ord	42
1	Scope	44
2	References	44
3	Definitions, symbols and abbreviations	45
3.1	Definitions	45
3.2	Symbols	46
3.3	Abbreviations	47
3.4	Test tolerances	50
3.5	Frequency bands grouping	
3.5.1	Introduction.	
3.5.2	NR operating bands in FR1	
3.5.3	NR operating bands in FR2	
3.6	Applicability of requirements in this specification version	
3.6.1	RRC connected state requirements in DRX	
3.6.2	Number of serving carriers	
3.6.2.1	Number of serving carriers for SA	
3.6.2.2	Number of serving carriers for EN-DC	
3.6.2.3	Number of serving carriers for NE-DC	
3.6.2.4	6	
3.6.3	Applicability for intra-band FR2	
3.6.4	Applicability for FR2 UE power classes	
3.6.5	Applicability for SDL bands	
3.6.6	Applicability of OCI	
3.6.7 3.6.9	Applicability of QCLApplicability of requirements for scheduling availability	
3.6.10	Applicability of requirements for measurement restrictions	
	••	
	SA: RRC_IDLE state mobility	
4.1	Cell Selection	
4.2	Cell Re-selection	
4.2.1	Introduction	
4.2.2 4.2.2.1	Requirements	
4.2.2.1	UE measurement capability	
4.2.2.3	Measurements of intra-frequency NR cells	
4.2.2.3	Measurements of inter-frequency NR cells	
4.2.2.5	Measurements of inter-RAT E-UTRAN cells	
4.2.2.6	Maximum interruption in paging reception	
4.2.2.7		
4.2.2.8	1	
4.2.2.9		01
	criterion	61
4.2.2.9		
4.2.2.9		
4.2.2.9		
4.2.2.9		
4.2.2.1		
	criterion	63
4.2.2.1		
4.2.2.1	0.2 Measurements for UE fulfilling low mobility criterion	63
4.2.2.1	0.3 Measurements for UE fulfilling not-at-cell edge criterion	64
4.2.2.1		64
4.2.2.1		
	criterion	
4.2.2.1		
4221	1.3 Measurements for UE fulfilling with not-at-cell edge criterion	66

4.2.2.11.4		
4.2A	Cell Re-selection when subject to CCA	67
4.2A.1	Introduction	
4.2A.2	Requirements	
4.2A.2.1	UE measurement capability	
4.2A.2.2	Measurement and evaluation when subject to CCA on the serving cell	
4.2A.2.3	Measurements of intra-frequency NR cells when subject to CCA on the serving cell and target	0
	cell	
4.2A.2.4	Measurements of inter-frequency NR cells when subject to CCA on the target cell	
4.2A.2.5	Measurements of inter-RAT E-UTRAN cells when subject to CCA on the serving cell	
4.2A.2.6	Maximum interruption in paging reception when subject to CCA on the target cell	71
4.2A.2.7	General requirements	71
4.3	Minimization of Drive Tests (MDT)	72
4.3.1	Introduction	72
4.3.2	Measurement Requirements	72
4.3.3	Requirements for Relative Time Stamp Accuracy	72
4.3.4	Requirements for Relative Time Stamp Accuracy for RRC Connection Establishment Failure Log Reporting	
4.3.5	Requirements for Relative Time Stamp Accuracy for Radio Link Failure and Handover Failure Log	/_
4.5.5	Reporting	71
4.4		
4.4	Idle Mode CA/DC Measurements	
4.4.1	Introduction	
4.4.2	Measurement Requirements	
4.4.2.1	Detected cell requirement during state transition and Idle mode	
4.4.2.2	Measurements of inter-frequency CA/DC candidate cells	
4.4.2.3	Measurements on serving cell	
4.4.2.4	Measurements of E-UTRAN inter-RAT DC candidate cells	
	A: RRC_INACTIVE state mobility	
5.1	Cell Re-selection	
5.1.1	Introduction	
5.1.2	Requirements	
5.1.2.1	UE measurement capability	
5.1.2.2	Measurement and evaluation of serving cell	
5.1.2.3	Measurements of intra-frequency NR cells	77
5.1.2.4	Measurements of inter-frequency NR cells	77
5.1.2.5	Measurements of inter-RAT E-UTRAN cells	
5.1.2.6	Maximum interruption in paging reception	77
5.1.2.7	General requirements	
5.1A	Cell Re-selection with CCA	77
5.1A.1	Introduction	7
5.1A.2	Requirements	
5.1A.2.1	UE measurement capability	
5.1A.2.2	Measurement and evaluation when CCA is used on the serving cell	
5.1A.2.3	Measurements of intra-frequency NR cells when CCA is used on the serving cell and target cell	
5.1A.2.4	Measurements of inter-frequency NR cells when CCA is used on the serving cen and target cen  Measurements of inter-frequency NR cells when CCA is used on the target cell	
5.1A.2.4 5.1A.2.5	Measurements of inter-RAT E-UTRAN cells when CCA is used on the serving cell	
-		
5.1A.2.6	Maximum interruption in paging reception when CCA is used on the target cell	
5.1A.2.7	General requirements	
5.2	Void	
5.3	Minimization of Drive Tests (MDT)	
5.3.1	Introduction	
5.3.2	Measurement Requirements	
5.3.3	Requirements for Relative Time Stamp Accuracy	79
5.3.4	Requirements for Relative Time Stamp Accuracy for RRC Connection Establishment Failure Log Reporting	79
5.3.5	Requirements for Relative Time Stamp Accuracy for Radio Link Failure and Handover Failure Log	
	Reporting	70
5.3.6	Requirements for Relative Time Stamp Accuracy for RRC Resume Failure Log Reporting	
5.4	Idle Mode CA/DC Measurements	
5.4.1	Introduction.	
5.4.2	Measurement Requirements	
J. 1.4	1.1040 at other troops at the transfer of the	/ >

5.4.2.1	Detected cell requirement during state transition and Idle mode	
5.4.2.2	Measurements of inter-frequency CA/DC candidate cells	80
5.4.2.3	Measurements on serving cell	80
5.4.2.4	Measurements on E-UTRAN inter-RAT DC candidate cells	80
6 RR	C CONNECTED state mobility	80
	Handover	
6.1.1	NR Handover	
6.1.1.1		
	Introduction	
6.1.1.2	NR FR1 - NR FR1 Handover	
6.1.1.2.1	Handover delay	
6.1.1.2.2	Interruption time	
6.1.1.3	NR FR2- NR FR1 Handover	
6.1.1.3.1	Handover delay	
6.1.1.3.2	Interruption time	
6.1.1.4	NR FR2- NR FR2 Handover	
6.1.1.4.1	Handover delay	
6.1.1.4.2	Interruption time	82
6.1.1.5	NR FR1- NR FR2 Handover	83
6.1.1.5.1	Handover delay	83
6.1.1.5.2	Interruption time	
6.1.2	NR Handover to other RATs	
6.1.2.1	NR – E-UTRAN Handover	
6.1.2.1.1	Introduction	
6.1.2.1.2	Handover delay	
6.1.2.1.3	Interruption time	
6.1.2.2	NR – UTRAN Handover	
6.1.2.2.1	Introduction	
6.1.2.2.2		
6.1.2.2.3	Handover delay	
	Interruption time	
6.1.3	NR DAPS Handover	
6.1.3.1	Introduction	
6.1.3.2	NR FR1 - NR FR1 DAPS Handover	
6.1.3.2.1	DAPS handover delay	
6.1.3.2.2	Interruption time	
6.1.3.3	NR FR2- NR FR1 DAPS Handover	
6.1.3.3.1	DAPS handover delay	
6.1.3.3.2	Interruption time	
6.1.3.4	NR FR1- NR FR2 DAPS Handover	89
6.1.3.4.1	DAPS handover delay	90
6.1.3.4.2	Interruption time	
6.1.4	NR Conditional Handover	
6.1.4.1	Introduction	90
6.1.4.2	NR FR1 – NR FR1 conditional handover	
6.1.4.3	NR FR2 – NR FR1 conditional handover	
6.1.4.4	NR FR2 – NR FR2 conditional handover	
6.1.4.4.1	Handover delay	
6.1.4.4.2	Measurement time	
6.1.4.4.3	Preparation time	
6.1.4.4.4	Interruption time	
6.1.4.5	NR FR1 – NR FR2 conditional handover	
	Void	
6.1A.1	Void	
6.1A.1.1	Void	
6.1A.1.2	Void	
6.1A.1.2.1	Void	
6.1A.1.2.2	Void	
6.1B	Handover to target cell using CCA	94
6.1B.1	NR Handover	
6.1B.1.1	Introduction	92
6.1B.1.2	NR FR1 - NR FR1 Handover	
6.1B.1.2.1	Handover delay	94

6.1B.1.2.2		
6.2	RRC Connection Mobility Control	95
6.2.1	SA: RRC Re-establishment	95
6.2.1.1	Introduction	95
6.2.1.2	Requirements	
6.2.1.2.1	UE Re-establishment delay requirement	
6.2.1A	RRC Re-establishment with CCA	
6.2.1A.1	Introduction	
6.2.1A.1	Requirements	
6.2.1A.2.1		
6.2.2	Random access	
6.2.2.1	Introduction	
6.2.2.2	Requirements for 4-step RA type	
6.2.2.2.1	Contention based random access	
6.2.2.2.2	Non-Contention based random access	
6.2.2.2.3	UE behaviour when configured with supplementary UL	101
6.2.2.3	Requirements for 2-step RA type	101
6.2.2.3.1	Contention based random access	102
6.2.2.3.2	Non-Contention based random access	
6.2.2.3.3	UE behaviour when configured with supplementary UL	
6.2.2A	Random access when CCA is used on target frequency	
6.2.2A.1	Introduction	
6.2.2A.1	Requirements for 4-step RA type	
6.2.2A.2.1		
-		
6.2.2A.2.2		
6.2.2A.3	Requirements for 2-step RA type	
6.2.2A.3.1		
6.2.2A.3.2		
6.2.3	SA: RRC Connection Release with Redirection	
6.2.3.1	Introduction	108
6.2.3.2	Requirements	108
6.2.3.2.1	RRC connection release with redirection to NR	108
6.2.3.2.2	RRC connection release with redirection to E-UTRAN	109
6.2.3.2.3	RRC connection release with redirection to NR carrier subject to CCA	
	•	
7 Tii	ming	
7.1	UE transmit timing	111
7.1.1	Introduction	111
7.1.2	Requirements	111
7.1.2.1	Gradual timing adjustment	112
7.1.2.2	Void	113
7.2	UE timer accuracy	
7.2.1	Introduction	
7.2.2	Requirements	
7.2.2	Timing advance	
7.3.1	Introduction	
7.3.2	Requirements	
7.3.2.1	Timing Advance adjustment delay	
7.3.2.2	Timing Advance adjustment accuracy	
7.4	Cell phase synchronization accuracy	
7.4.1	Definition	114
7.4.2	Minimum requirements	
7.5	Maximum Transmission Timing Difference	114
7.5.1	Introduction	
7.5.2	Minimum Requirements for inter-band EN-DC	
7.5.2.1	Minimum Requirements for inter-band synchronous EN-DC	
7.5.3	Minimum Requirements for intra-band EN-DC	
7.5.4	Minimum Requirements for NR Carrier Aggregation	
7.5.5	17111111111111111111111111111111111111	1 10
	Minimum Requirements for inter-band NE-DC	116
7.5.5.1	Minimum Requirements for inter-band NE-DC	116 117
	Minimum Requirements for inter-band NE-DC	116 117 117

7.6.1	Introduction	117
7.6.2	Minimum Requirements for inter-band EN-DC	118
7.6.2.1	Minimum Requirements for inter-band synchronous EN-DC	118
7.6.3	Minimum Requirements for intra-band EN-DC	
7.6.4	Minimum Requirements for NR Carrier Aggregation	
7.6.5	Minimum Requirements for inter-band NE-DC	
7.6.5.1	Minimum Requirements for inter-band synchronous NE-DC	
7.6.6	Minimum Requirements for inter-band NR DC	
7.7	deriveSSB-IndexFromCell tolerance	
7.7.1	Minimum requirements	
7.8	Void	121
Q C;	gnalling characteristics	121
8.1	Radio Link Monitoring	
8.1.1	Introduction	
8.1.2	Requirements for SSB based radio link monitoring	
8.1.2.1	Introduction	122
8.1.2.2	Minimum requirement	123
8.1.2.3	Measurement restrictions for SSB based RLM	125
8.1.3	Requirements for CSI-RS based radio link monitoring	125
8.1.3.1	Introduction	
8.1.3.2	Minimum requirement	
8.1.3.3	Measurement restrictions for CSI-RS based RLM	
8.1.4	Minimum requirement at transitions	
8.1.5	Minimum requirement for UE turning off the transmitter	
8.1.6	Minimum requirement for L1 indication	
8.1.7	Scheduling availability of UE during radio link monitoring	130
8.1.7.1	Scheduling availability of UE performing radio link monitoring with a same subcarrier spacing	
	as PDSCH/PDCCH on FR1	130
8.1.7.2	Scheduling availability of UE performing radio link monitoring with a different subcarrier	
	spacing than PDSCH/PDCCH on FR1	130
8.1.7.3	Scheduling availability of UE performing radio link monitoring on FR2	
8.1.7.4	Scheduling availability of UE performing radio link monitoring on FR1 or FR2 in case of FR1-	100
0.1.7.1	FR2 inter-band CA and NR-DC	131
8.1A	Radio Link Monitoring with CCA on Target Frequency	
8.1A.1	Introduction	
8.1A.2	Requirements for SSB Based Radio Link Monitoring	
8.1A.2.1	Introduction	
8.1A.2.2	Minimum Requirement	
8.1A.3	Minimum requirement at transitions	134
8.1A.4	Minimum requirement for UE turning off the transmitter	135
8.1A.5	Minimum requirement for L1 indication	135
8.1A.6	Scheduling availability of UE during radio link monitoring	
8.1A.6.1	Scheduling availability of UE performing radio link monitoring with the same subcarrier spacing	
0.171.0.1	as PDSCH/PDCCH	
8.1A.6.2	Scheduling availability of UE performing radio link monitoring with a different subcarrier	133
0.1A.U.2	spacing than PDSCH/PDCCH	125
0.2		
8.2	Interruption	
8.2.1	EN-DC Interruption	
8.2.1.1	Introduction	
8.2.1.2	Requirements	
8.2.1.2.1	Interruptions at transitions between active and non-active during DRX	136
8.2.1.2.2	Interruptions at transitions from non-DRX to DRX	137
8.2.1.2.3	Interruptions at SCell addition/release	
8.2.1.2.4	Interruptions at SCell activation/deactivation	
8.2.1.2.5	Interruptions during measurements on SCC	
8.2.1.2.6	Interruptions at UL carrier RRC reconfiguration	
8.2.1.2.7	Interruptions due to Active BWP switching Requirement	
8.2.1.2.8	Interruptions at direct SCell activation and hibernation	
8.2.1.2.9	Interruptions at SCell hibernation	
8.2.1.2.10		
8.2.1.2.1	Interruptions due to UE-specific CBW change	143

8.2.1.2.12	Interruptions at NR SRS carrier based switching	143
8.2.1.2.13	Interruptions at E-UTRA SRS carrier based switching	
8.2.1.2.14	DL Interruptions at switching between two uplink carriers	145
8.2.1.2.15	Interruptions due to SCell dormancy	
8.2.1.2.16	Interruptions when identifying CGI of an NR cell with autonomous gaps	
8.2.1.2.17	Interruptions when identifying CGI of an E-UTRA cell with autonomous gaps	147
8.2.2	SA: Interruptions with Standalone NR Carrier Aggregation	
8.2.2.1	Introduction	
8.2.2.2	Requirements	148
8.2.2.2.1	Interruptions at SCell addition/release	
8.2.2.2.2	Interruptions at SCell activation/deactivation	
8.2.2.2.3	Interruptions during measurements on deactivated SCC	150
8.2.2.2.4	Interruptions at UL carrier RRC reconfiguration	
8.2.2.2.5	Interruptions due to Active BWP switching Requirement	
8.2.2.2.6	Interruptions at inter-frequency SFTD measurement	
8.2.2.2.7	Interruptions at SCell activation/deactivation with multiple downlink SCells	
8.2.2.2.8	Interruptions due to UE-specific CBW change	
8.2.2.2.9	Interruptions at NR SRS carrier based switching	
8.2.2.2.10	DL Interruptions at UE switching between two uplink carriers	
8.2.2.2.11	Interruptions at direct SCell activation	
8.2.2.2.12	Interruptions due to SCell dormancy	
8.2.2.2.13	Interruptions at transitions between active and non-active during DRX	
8.2.2.2.14	Interruptions when identifying CGI of an NR cell with autonomous gaps	
8.2.2.2.15	Interruptions when identifying CGI of an E-UTRA cell with autonomous gaps	
8.2.3	NE-DC Interruptions	
8.2.3.1	Introduction	
8.2.3.2	Requirements	
8.2.3.2.1	Interruptions at transitions between active and non-active during DRX	
8.2.3.2.2	Interruptions at transitions from non-DRX to DRX	
8.2.3.2.3	Interruptions at PSCell/SCell addition/release	
8.2.3.2.4	Interruptions at SCell activation/deactivation	
8.2.3.2.5	Interruptions during measurements on SCC	
8.2.3.2.6	Interruptions at UL carrier RRC reconfiguration	
8.2.3.2.7	Interruptions due to Active BWP switching Requirement	
8.2.3.2.8	Interruptions at direct SCell activation and hibernation	162
8.2.3.2.9	Interruptions at SCell hibernation	
8.2.3.2.10	Interruptions at SCell activation/deactivation with multiple downlink SCells	
8.2.3.2.11	Interruptions at NR SRS carrier based switching	
8.2.3.2.12	Interruptions at E-UTRA SRS carrier based switching	
8.2.3.2.13	Interruptions due to SCell dormancy	
8.2.3.2.14	Interruptions when identifying CGI of an NR cell with autonomous gaps	
8.2.3.2.15	Interruptions when identifying CGI of an E-UTRA cell with autonomous gaps	
8.2.4	NR-DC: Interruptions	
8.2.4.1	Introduction	
8.2.4.2	Requirements	
8.2.4.2.1	Interruptions at PSCell/SCell addition/release	
8.2.4.2.2	Interruptions at SCell activation/deactivation	
8.2.4.2.3	Interruptions during measurements on SCC	
8.2.4.2.4	Interruptions at UL carrier RRC reconfiguration	
8.2.4.2.5	Interruptions due to Active BWP switching Requirement	
8.2.4.2.6	Interruptions at transitions between active and non-active during DRX	
8.2.4.2.7	Interruptions at transitions from non-DRX to DRX	
8.2.4.2.8	Interruptions at SCell activation/deactivation with multiple downlink SCells	
8.2.4.2.9	Interruptions at NR SRS carrier based switching	
8.2.4.2.10	Interruptions at direct SCell activation	
8.2.4.2.11	Interruptions when identifying CGI of an NR cell with autonomous gaps	
8.2.4.2.12	Interruptions when identifying CGI of an E-UTRA cell with autonomous gaps	
8.2.4.2.13	Interruptions due to SCell dormancy	174
8.2.4.2A	Void	
8.2.4.2A.1	Void	
8.2.4.2A.2	Void	
8.2.4.2A.3	Void	

8.3.3         SCell Decivation Delay Requirement for Activated SCell.           8.3.4         Direct SCell Activation at SCell addition.           8.3.5         Direct SCell Activation at Handover.           8.3.7         SCell Activation Delay Requirement for Deactivated SCell with Multiple Downlink SCells           8.3.8         SCell Decivation Delay Requirement for Deactivated SCell with Multiple Downlink SCells at Handover.           8.3.1         Direct SCell Activation of Multiple Downlink SCells at Handover.           8.3.1         Eccl Activation Delay Requirement for Deactivated SCell.           8.3.1         Introduction.           8.3.2         SCell Activation Delay Requirement for Deactivated SCell.           8.4.1         Introduction.           8.4.2         UE UL carrier Configuration delay requirement.           8.4.3         UE UL carrier configuration delay requirement.           8.4.3         UE UL carrier deconfiguration delay requirement.           8.5.1         Introduction.           8.5.2         Requirements for SSB based beam failure detection.           8.5.2.1         Introduction.           8.5.2.2         Minimum requirement           8.5.3.1         Requirements for CSI-RS based beam failure detection.           8.5.3.2         Measurement restriction for SSB based beam failure detection.           8.5.3	8.3	SCell Activation and Deactivation Delay	
8.3.4         Direct SCell Activation Delay Requirement for Activated SCell           8.3.5         Direct SCell Activation at Handover           8.3.7         SCell Deactivation Delay Requirement for Deactivated SCell with Multiple Downlink SCells           8.3.8         SCell Deactivation Delay Requirement for Activated SCell with Multiple Downlink SCells           8.3.9         Direct SCell Activation of Multiple Downlink SCells at SCell addition           8.3.1         Direct SCell Activation of Multiple Downlink SCells at SCell addition           8.3.1         Direct SCell Activation of Multiple Downlink SCells at SCell addition           8.3.1         Introduction           8.3.2         SCell Activation Delay Requirement for Activated SCell           8.3.3         SCell Deactivation Delay Requirement for Activated SCell           8.4         UE UL carrier Reconfiguration delay           8.4.1         Introduction           8.4.2         UE UL carrier deconfiguration delay requirement           8.5.1         Introduction           8.5.2         Requirements for SSB based beam failure detection           8.5.1         Introduction           8.5.2.1         Requirements for SSB based beam failure detection           8.5.2.2         Minimum requirement           8.5.3.3         Requirements for CSB Bbased candidate beam detection	8.3.1	Introduction	
8.3.4         Direct SCell Activation at SCell addition.           8.3.5         Direct SCell Activation at Handover.           8.3.7         Scell Activation Delay Requirement for Deactivated SCell with Multiple Downlink SCells SCell Deactivation Delay Requirement for Activated SCell with Multiple Downlink SCells at Scell addition.           8.3.8         SCell Activation of Multiple Downlink SCells at Handover.           8.3.1         Cell Activation of Multiple Downlink SCells at Handover.           8.3.2         Cell Activation Delay Requirement for Deactivated SCell.           8.3.1         Introduction.           8.3.2         SCell Activation Delay Requirement for Deactivated SCell.           8.4         UE UL carrier RC reconfiguration delay.           8.4.1         Introduction.           8.4.2         UF UL carrier configuration delay requirement.           8.5.1         Link Recovery Procedures           8.5.1         Introduction.           8.5.2.1         Measurement for SSB based beam failure detection.           8.5.2.2         Minimum requirement           8.5.3.3         Measurement restriction for SSB based beam failure detection.           8.5.3.1         Requirements for CSI-RS based beam failure detection.           8.5.5.2         Measurement restriction for SSB based candidate beam detection.           8.5.5.3         Measurement restricti	8.3.2	SCell Activation Delay Requirement for Deactivated SCell	175
8.3.5         Direct SCell Activation Delay Requirement for Deactivated SCell with Multiple Downlink SCells           8.3.8         SCell Deactivation Delay Requirement for Activated SCell with Multiple Downlink SCells           8.3.9         Direct SCell Activation of Multiple Downlink SCells at SCell addition           8.3.1         Direct SCell Activation of Multiple Downlink SCells at Handover           8.3.2         SCell Activation Delay Requirement for Deactivated SCell           8.3.3.1         Introduction           8.3.2         SCell Deactivation Delay Requirement for Deactivated SCell           8.3.3.1         Introduction           8.4.2         UE UL carrier RRC reconfiguration delay requirement           8.4.2         UE UL carrier configuration delay requirement           8.5.1         Introduction           8.5.2         Requirements for SSB based beam failure detection           8.5.1         Introduction           8.5.2.1         Measurement restriction for SSB based beam failure detection           8.5.3.1         Introduction           8.5.3.2         Measurement restrictions for CSI-RS beam failure detection           8.5.3.3         Requirements for SSB based candidate beam detection           8.5.4.5         Requirements for SSB based candidate beam detection           8.5.5.6         Requirements for CSI-RS based candidate beam detection	8.3.3	SCell Deactivation Delay Requirement for Activated SCell	179
S.2.1 Activation Delay Requirement for Deactivated SCell with Multiple Downlink SCells 8.3.9 Direct SCell Activation of Multiple Downlink SCells at SCell addition Direct SCell Activation of Multiple Downlink SCells at SCell addition Direct SCell Activation of Multiple Downlink SCells at SCell addition Direct SCell Activation of Multiple Downlink SCells at Handover	8.3.4	Direct SCell Activation at SCell addition	179
8.3.8         SCell Deactivation Delay Requirement for Activated SCell with Multiple Downlink SCells at SCell addition           8.3.10         Direct SCell Activation of Multiple Downlink SCells at SCell addition           8.3.1         Introduction           8.3.2         SCell Activation and Deactivation Delay in Carriers with CCA           8.3.3.1         Introduction           8.3.4.1         Introduction           8.4.2         UE UL carrier RC reconfiguration delay           8.4.1         Introduction           8.4.2         UE UL carrier configuration delay requirement           8.4.2         UE UL carrier deconfiguration delay requirement           8.5.2         Introduction           8.5.2         Requirements for SSB based beam failure detection           8.5.2         Introduction           8.5.2.1         Introduction           8.5.2.2         Minimum requirement           8.5.2.3         Measurement restriction for SSB based beam failure detection           8.5.3.1         Introduction           8.5.3.2         Minimum requirement           8.5.3.1         Introduction           8.5.3.2         Minimum requirement restriction for SSB based beam failure detection           8.5.3.1         Minimum requirement for Li indication           8.5.5.2	8.3.5	Direct SCell Activation at Handover	180
8.3.8         SCell Deactivation Delay Requirement for Activated SCell with Multiple Downlink SCells at SCell addition           8.3.10         Direct SCell Activation of Multiple Downlink SCells at SCell addition           8.3.1         Introduction           8.3.2         SCell Activation and Deactivation Delay in Carriers with CCA           8.3.3.1         Introduction           8.3.4.1         Introduction           8.4.2         UE UL carrier RC reconfiguration delay           8.4.1         Introduction           8.4.2         UE UL carrier configuration delay requirement           8.4.2         UE UL carrier deconfiguration delay requirement           8.5.2         Introduction           8.5.2         Requirements for SSB based beam failure detection           8.5.2         Introduction           8.5.2.1         Introduction           8.5.2.2         Minimum requirement           8.5.2.3         Measurement restriction for SSB based beam failure detection           8.5.3.1         Introduction           8.5.3.2         Minimum requirement           8.5.3.1         Introduction           8.5.3.2         Minimum requirement restriction for SSB based beam failure detection           8.5.3.1         Minimum requirement for Li indication           8.5.5.2	8.3.7	SCell Activation Delay Requirement for Deactivated SCell with Multiple Downlink SCells	181
Baseline   Direct SCell Activation of Multiple Downlink SCells at Handover	8.3.8		
8.3.1 Direct SCell Activation of Multiple Downlink SCells at Handover 8.3.3.1 Introduction. 8.3.3.2 SCell Activation and Deactivation Delay in Carriers with CCA. 8.3.3.3 SCell Deactivation Delay Requirement for Deactivated SCell. 8.3.3.3 SCell Deactivation Delay Requirement for Activated SCell. 8.4.1 Introduction. 8.4.2 UE UL carrier RC reconfiguration delay. 8.4.3 UE UL carrier deconfiguration delay requirement. 8.5.4 Introduction. 8.5.5 Introduction. 8.5.1 Introduction. 8.5.2 Requirements for SSB based beam failure detection. 8.5.2.1 Introduction. 8.5.2.2 Measurement restriction for SSB based beam failure detection. 8.5.3.1 Introduction. 8.5.3.2 Minimum requirement. 8.5.3.3 Measurement restriction for SSB based beam failure detection. 8.5.3.1 Minimum requirement for CSI-RS beam failure detection. 8.5.3.3 Measurement restrictions for CSI-RS beam failure detection. 8.5.3.1 Minimum requirement for CSI-RS beam failure detection. 8.5.3.3 Minimum requirement for CSI-RS beam failure detection. 8.5.4 Minimum requirement for CSI-RS beam failure detection. 8.5.5.1 Minimum requirement for CSI-RS based candidate beam detection. 8.5.6 Requirements for CSI-RS based candidate beam detection. 8.5.7.1 Scheduling availability of UE performing beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1. 8.5.7.2 Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC. 8.5.8 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1. 8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1. 8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2 in case FR1-FR2 inter-band CA and NR-DC. 8.5.9 Requirements for Link Recovery with Link Recovery Request (LRR). 8.5.9.1 Introduction. 8.5.9.2 Requirements for Link Recovery with Link Recovery Request (LRR). 8.5.9.1 Introduction. 8.5.9.2 Link Recovery Procedures when CCA is used on target freq			
8.3A.1       SCell Activation and Deactivation Delay in Carriers with CCA.         8.3A.2       SCell Activation Delay Requirement for Deactivated SCell.         8.3A.3       SCell Deactivation Delay Requirement for Activated SCell.         8.4       UE UL carrier REC reconfiguration delay         8.4.1       UE UL carrier deconfiguration delay requirement.         8.4.2       UE UL carrier deconfiguration delay requirement.         8.5.5       Link Recovery Procedures.         8.5.1       Introduction.         8.5.2       Requirements for SSB based beam failure detection.         8.5.2.1       Introduction.         8.5.2.2       Minimum requirement.         8.5.2.1       Minimum requirement.         8.5.2.2       Measurement restriction for SSB based beam failure detection.         8.5.3.1       Requirements for CSI-RS based beam failure detection.         8.5.3.2       Minimum requirement.         8.5.3.3       Measurement restrictions for CSI-RS beam failure detection.         8.5.5.4       Minimum requirement for L1 indication.         8.5.5.5       Requirements for SSB based candidate beam detection.         8.5.6.1       Minimum requirement restriction for CSI-RS based candidate beam detection.         8.5.7.3       Measurement restriction for CSI-RS based candidate beam detection. <t< td=""><td></td><td></td><td></td></t<>			
8.3A.1 Introduction. 8.3A.2 SCell Activation Delay Requirement for Deactivated SCell. 8.3A.3 SCell Deactivation Delay Requirement for Activated SCell. 8.4.1 Introduction. 8.4.2 UE UL carrier RC reconfiguration delay Introduction. 8.5 Link Recovery Procedures. 8.5.1 Introduction. 8.5.2 Requirements for SSB based beam failure detection. 8.5.2.1 Introduction. 8.5.2.2 Minimum requirement. 8.5.3 Requirements for CSI-RS based beam failure detection. 8.5.3.3 Measurement restriction for SSB based beam failure detection. 8.5.3.1 Introduction. 8.5.3.2 Minimum requirement for L1 indication. 8.5.3.3 Minimum requirement for L1 indication. 8.5.4 Minimum requirement for SSB based candidate beam detection. 8.5.5 Requirements for SSB based candidate beam detection. 8.5.6 Requirements for SSB based candidate beam detection. 8.5.6 Requirement for SSB based candidate beam detection. 8.5.6 Requirements for CSI-RS based candidate beam detection. 8.5.6 Requirement for CSI-RS based candidate beam detection. 8.5.6.1 Minimum requirement. 8.5.6 Requirement for CSI-RS based candidate beam detection. 8.5.6 Requirements for CSI-RS based candidate beam detection. 8.5.6.1 Minimum requirement. 8.5.7 Scheduling availability of UE during beam failure detection with a same subcarrier as PISCH/PDCCH on FR1. 8.5.7.2 Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC. 8.5.8 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1. 8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier as PDSCH/PDCCH on FR1. 8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier as PDSCH/PDCCH on FR1. 8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1. 8.5.8.3 Introduction. 8.5.8.4 Introduction. 8.5.8.5 Introduction. 8.5.8.5 Introduction. 8.5.8.6 Introduction. 8.5.8.6 Introduction. 8.5.8.7 Introductio			
8.3A.3       SCell Deactivation Delay Requirement for Activated SCell.         8.4       UE UL carrier RC reconfiguration delay.         8.4.1       Introduction.         8.4.2       UE UL carrier configuration delay requirement.         8.4.3       UE UL carrier configuration delay requirement.         8.5       Link Recovery Procedures.         8.5.1       Introduction.         8.5.2.1       Requirements for SSB based beam failure detection         8.5.2.2       Minimum requirement         8.5.2.3       Requirements for CSI-RS based beam failure detection.         8.5.3.1       Requirements for CSI-RS based beam failure detection.         8.5.3.2       Minimum requirement         8.5.3.3       Measurement restrictions for CSI-RS beam failure detection.         8.5.3.4       Minimum requirement for L1 indication.         8.5.5.5       Requirements for SSB based candidate beam detection.         8.5.5.1       Minimum requirement         8.5.5.2       Measurement restriction for SSB based candidate beam detection.         8.5.5.3       Measurement restriction for CSI-RS based candidate beam detection.         8.5.6.1       Introduction.         8.5.6.2       Measurement restriction for CSI-RS based candidate beam detection with a same subcarrie as PDSCHPDCCH on FR1.         8.5.7.3 <t< td=""><td></td><td></td><td></td></t<>			
8.4.3 UE UL carrier RRC reconfiguration delay requirement.  8.4.1 UE UL carrier configuration delay requirement.  8.4.2 UE UL carrier deconfiguration delay requirement.  8.4.3 UE UL carrier deconfiguration delay requirement.  8.5.1 Link Recovery Procedures.  8.5.1 Introduction.  8.5.2 Requirements for SSB based beam failure detection.  8.5.2.1 Minimum requirement.  8.5.2.2 Minimum requirement.  8.5.3.1 Introduction.  8.5.3.2 Measurement restriction for SSB based beam failure detection.  8.5.3.3 Measurement restrictions for CSI-RS beam failure detection.  8.5.3.1 Minimum requirement.  8.5.3.2 Minimum requirement for L1 indication.  8.5.3.3 Measurement restriction for SSB based candidate beam detection.  8.5.4 Minimum requirement for L1 indication.  8.5.5.1 Introduction.  8.5.5.2 Minimum requirement for L3 indication.  8.5.5.3 Measurement restriction for SSB based candidate beam detection.  8.5.6 Requirements for CSI-RS based candidate beam detection.  8.5.6 Requirements for CSI-RS based candidate beam detection.  8.5.6 Measurement restriction for CSI-RS based candidate beam detection.  8.5.7 Scheduling availability of UE performing beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1.  8.5.7.1 Scheduling availability of UE performing beam failure detection with a different subcar spacing than PDSCH/PDCCH on FR1.  8.5.8.2 Scheduling availability of UE performing beam failure detection on FR2 of FR2 inter-band CA and NR DC.  8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1.  8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1.  8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1.  8.5.8.5 Scheduling availability of UE performing L1-RSRP measurement on FR2 Scheduling availability of UE performing L1-RSRP measurement on FR2.  8.5.9 Requirements for L1 ink Recovery with Link Recovery			
UE UL carrier RRC reconfiguration delay			
Section			
Section   Sect			
Section   Sect			
Link Recovery Procedures   St. 2			
S.5.1   Introduction.			
8.5.2 Requirements for SSB based beam failure detection 8.5.2.1 Introduction			
S.5.2.1   Introduction			
Minimum requirement			
Measurement restriction for SSB based beam failure detection			
8.5.3.1 Requirements for CSI-RS based beam failure detection 8.5.3.1 Minimum requirement 8.5.3.2 Minimum requirement 8.5.3.3 Minimum requirement 8.5.4 Minimum requirement for L1 indication 8.5.5 Requirements for SSB based candidate beam detection 8.5.5.1 Introduction 8.5.5.2 Minimum requirement 8.5.5.3 Measurement restriction for SSB based candidate beam detection 8.5.6.1 Measurement restriction for SSB based candidate beam detection 8.5.6.2 Minimum requirement 8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection 8.5.6.1 Introduction 8.5.6.2 Minimum requirement 8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection 8.5.6.1 Scheduling availability of UE performing beam failure detection 8.5.7.1 Scheduling availability of UE performing beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1 8.5.7.2 Scheduling availability of UE performing beam failure detection on FR2 8.5.7.3 Scheduling availability of UE performing beam failure detection on FR2 8.5.7.4 Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC 8.5.8 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1 8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subcarrie as PDSCH/PDCCH on FR1 8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement with a different subcarrie as PDSCH/PDCCH on FR1 8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.5 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.6 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.7 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.9 Requirement Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.9 Requirement Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.9 Requirement Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5			
Introduction   Ninimum requirement			
8.5.3.2 Minimum requirement 8.5.3.3 Measurement restrictions for CSI-RS beam failure detection 8.5.4 Minimum requirement for L1 indication 8.5.5 Requirements for SSB based candidate beam detection 8.5.5.1 Introduction 8.5.5.2 Minimum requirement 8.5.5.3 Measurement restriction for SSB based candidate beam detection 8.5.6.1 Measurement restriction for SSB based candidate beam detection 8.5.6.2 Minimum requirement 8.5.6.3 Requirements for CSI-RS based candidate beam detection 8.5.6.1 Introduction 8.5.6.2 Minimum requirement 8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection 8.5.6.1 Scheduling availability of UE during beam failure detection 8.5.7.1 Scheduling availability of UE performing beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1 8.5.7.2 Scheduling availability of UE performing beam failure detection with a different subcarrier spacing than PDSCH/PDCCH on FR1 8.5.7.3 Scheduling availability of UE performing beam failure detection on FR2 8.5.7.4 Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC 8.5.8 Scheduling availability of UE during candidate beam detection 8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1 8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1 8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.5 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.9 Requirements for Link Recovery with Link Recovery Request (LRR) 8.5.9.1 Introduction 8.5.9.2 Introduction 8.5.9		1	
Measurement restrictions for CSI-RS beam failure detection			
8.5.4 Minimum requirement for L1 indication 8.5.5 Requirements for SSB based candidate beam detection. 8.5.5.1 Introduction. 8.5.5.2 Minimum requirement 8.5.5.3 Measurement restriction for SSB based candidate beam detection 8.5.6.1 Introduction. 8.5.6.2 Minimum requirement 8.5.6.2 Minimum requirement 8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection. 8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection. 8.5.7 Scheduling availability of UE during beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1 8.5.7.1 Scheduling availability of UE performing beam failure detection with a different subcarr spacing than PDSCH/PDCCH on FR1 8.5.7.2 Scheduling availability of UE performing beam failure detection on FR2 8.5.7.3 Scheduling availability of UE performing beam failure detection on FR2 8.5.7.4 Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC 8.5.8 Scheduling availability of UE during candidate beam detection. 8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1 8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1 8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.5 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.6 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.1 Introduction 8.5.9.2 Requirements for Link Recovery with Link Recovery Request (LRR)  1. Introduction 8.5.9.2 Requirements for SSB based beam failure detection 8.5.9.2 Minimum requirement 8.5.9.2 Minimum requirement 8.5.9.2 Minimum requirement			
8.5.5 Requirements for SSB based candidate beam detection			
S.5.5.1			
8.5.5.2 Minimum requirement 8.5.6.3 Measurement restriction for SSB based candidate beam detection 8.5.6.1 Introduction 8.5.6.2 Minimum requirement 8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection 8.5.6.3 Minimum requirement 8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection 8.5.7 Scheduling availability of UE during beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1 8.5.7.1 Scheduling availability of UE performing beam failure detection with a different subcarrispacing than PDSCH/PDCCH on FR1 8.5.7.3 Scheduling availability of UE performing beam failure detection on FR2 8.5.7.4 Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC 8.5.8 Scheduling availability of UE during candidate beam detection 8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier as PDSCH/PDCCH on FR1 8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subca spacing than PDSCH/PDCCH on FR1 8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.5 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.5 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.5 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.6 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.5 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.6 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.6 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.3 Scheduling availability of UE performing L1-RSRP measur			
8.5.5.3 Measurement restriction for SSB based candidate beam detection 8.5.6.1 Requirements for CSI-RS based candidate beam detection 8.5.6.2 Minimum requirement 8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection 8.5.7 Scheduling availability of UE during beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1 8.5.7.1 Scheduling availability of UE performing beam failure detection with a different subcarr spacing than PDSCH/PDCCH on FR1 8.5.7.3 Scheduling availability of UE performing beam failure detection on FR2 8.5.7.4 Scheduling availability of UE performing beam failure detection on FR2 8.5.8.5 Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC 8.5.8 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier as PDSCH/PDCCH on FR1 8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subcaspacing than PDSCH/PDCCH on FR1 8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.5 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.6 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.7 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.1 Introduction 8.5.9.2 Requirements for Link Recovery with Link Recovery Request (LRR) 8.5.9.1 Introduction 8.5.9.2 Requirements 8.5.9.2 Link Recovery Procedures when CCA is used on target frequency 8.5.9.1 Introduction 8.5.9.2 Requirements for SSB based beam failure detection 8.5.9.2 Minimum requirement			
8.5.6.1 Requirements for CSI-RS based candidate beam detection 8.5.6.1 Introduction 8.5.6.2 Minimum requirement 8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection 8.5.7 Scheduling availability of UE during beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1 8.5.7.1 Scheduling availability of UE performing beam failure detection with a different subcarr spacing than PDSCH/PDCCH on FR1 8.5.7.2 Scheduling availability of UE performing beam failure detection on FR2 8.5.7.3 Scheduling availability of UE performing beam failure detection on FR2 or FR2 inter-band CA and NR DC 8.5.8 Scheduling availability of UE during candidate beam detection 8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1 8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1 8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.5 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.6 Requirements for Link Recovery with Link Recovery Request (LRR)  Introduction  Requirement  Link Recovery Procedures when CCA is used on target frequency  Introduction  Requirements for SSB based beam failure detection  Minimum requirement			
8.5.6.2 Minimum requirement 8.5.6.2 Minimum requirement 8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection 8.5.7 Scheduling availability of UE during beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1 8.5.7.2 Scheduling availability of UE performing beam failure detection with a different subcarr spacing than PDSCH/PDCCH on FR1 8.5.7.3 Scheduling availability of UE performing beam failure detection on FR2 8.5.7.4 Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC 8.5.8 Scheduling availability of UE during candidate beam detection 8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1 8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1 8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR2 8.5.8.5 Reduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case FR1-FR2 inter-band CA and NR-DC 8.5.9 Requirements for Link Recovery with Link Recovery Request (LRR)  Introduction Requirement 8.5.3.1 Introduction Requirements for SSB based beam failure detection  Requirements for SSB based beam failure detection  Introduction Minimum requirement	8.5.5.3		
8.5.6.2       Minimum requirement         8.5.6.3       Measurement restriction for CSI-RS based candidate beam detection         8.5.7       Scheduling availability of UE during beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1         8.5.7.2       Scheduling availability of UE performing beam failure detection with a different subcarrier as PDSCH/PDCCH on FR1         8.5.7.3       Scheduling availability of UE performing beam failure detection on FR2         8.5.7.4       Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC         8.5.8.1       Scheduling availability of UE during candidate beam detection         8.5.8.2       Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1         8.5.8.3       Scheduling availability of UE performing L1-RSRP measurement with a different subcarrie as PDSCH/PDCCH on FR1         8.5.8.4       Scheduling availability of UE performing L1-RSRP measurement on FR2         8.5.8.5       Scheduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case FR1-FR2 inter-band CA and NR-DC         8.5.9.1       Requirements for Link Recovery with Link Recovery Request (LRR)         8.5.9.2       Introduction         8.5.3.1       Introduction         8.5.3.2       Requirements for SSB based beam failure detection         8.5.3.2       Introduction			
8.5.6.3 Measurement restriction for CSI-RS based candidate beam detection	8.5.6.1		
8.5.7 Scheduling availability of UE during beam failure detection	8.5.6.2	Minimum requirement	
8.5.7.1 Scheduling availability of UE performing beam failure detection with a same subcarrier as PDSCH/PDCCH on FR1		Measurement restriction for CSI-RS based candidate beam detection	
as PDSCH/PDCCH on FR1  8.5.7.2 Scheduling availability of UE performing beam failure detection with a different subcarr spacing than PDSCH/PDCCH on FR1  8.5.7.3 Scheduling availability of UE performing beam failure detection on FR2  8.5.7.4 Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC  8.5.8 Scheduling availability of UE during candidate beam detection  8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1  8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subcar spacing than PDSCH/PDCCH on FR1  8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2  8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR2 in case FR1-FR2 inter-band CA and NR-DC  8.5.9 Requirements for Link Recovery with Link Recovery Request (LRR)  8.5.9.1 Introduction  8.5.0.1 Requirement  8.5.0.1 Requirement  8.5.0.2 Introduction  Requirements for SSB based beam failure detection  8.5.0.2 Minimum requirement  8.5.0.2 Minimum requirement	8.5.7	Scheduling availability of UE during beam failure detection	204
8.5.7.2 Scheduling availability of UE performing beam failure detection with a different subcarr spacing than PDSCH/PDCCH on FR1	8.5.7.1	Scheduling availability of UE performing beam failure detection with a same subcarrier spacing as PDSCH/PDCCH on FR1	204
8.5.7.3 Scheduling availability of UE performing beam failure detection on FR2	8.5.7.2	Scheduling availability of UE performing beam failure detection with a different subcarrier	
8.5.7.4 Scheduling availability of UE performing beam failure detection on FR1 or FR2 in case FR2 inter-band CA and NR DC.  8.5.8 Scheduling availability of UE during candidate beam detection.  8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1.  8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subcarpacing than PDSCH/PDCCH on FR1.  8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2.  8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case FR1-FR2 inter-band CA and NR-DC.  8.5.9 Requirements for Link Recovery with Link Recovery Request (LRR).  8.5.9.1 Introduction.  8.5.9.2 Requirement.  8.5.9.1 Link Recovery Procedures when CCA is used on target frequency.  8.5.9.1 Introduction.  8.5.9.2 Requirements for SSB based beam failure detection.  8.5.9.1 Introduction.  8.5.9.2 Introduction.  8.5.9.1 Introduction.  8.5.9.2 Requirements for SSB based beam failure detection.  8.5.9.1 Introduction.  8.5.9.2 Introduction.  8.5.9.2 Requirements for SSB based beam failure detection.  8.5.9.1 Introduction.  8.5.9.2 Minimum requirement.	0.5.7.2		
FR2 inter-band CA and NR DC			204
8.5.8.1 Scheduling availability of UE during candidate beam detection.  8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1.  8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subca spacing than PDSCH/PDCCH on FR1.  8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2.  8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case FR1-FR2 inter-band CA and NR-DC.  8.5.9 Requirements for Link Recovery with Link Recovery Request (LRR).  8.5.9.1 Introduction.  8.5.9.2 Requirement.  8.5.4 Link Recovery Procedures when CCA is used on target frequency.  8.5.5.1 Introduction.  8.5.5.2 Requirements for SSB based beam failure detection.  8.5.5.2 Introduction.  8.5.5.2 Minimum requirement.	8.3.7.4		205
8.5.8.1 Scheduling availability of UE performing L1-RSRP measurement with a same subcarrie as PDSCH/PDCCH on FR1  8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subca spacing than PDSCH/PDCCH on FR1  8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2  8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case FR1-FR2 inter-band CA and NR-DC  8.5.9 Requirements for Link Recovery with Link Recovery Request (LRR)  8.5.9.1 Introduction  8.5.9.2 Requirement  8.5.4 Link Recovery Procedures when CCA is used on target frequency  8.5.4 Introduction  8.5.5.2 Requirements for SSB based beam failure detection  8.5.5.2 Introduction  8.5.5.2 Minimum requirement	0.5.0		
as PDSCH/PDCCH on FR1  8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subca spacing than PDSCH/PDCCH on FR1  8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2  8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case FR1-FR2 inter-band CA and NR-DC  8.5.9 Requirements for Link Recovery with Link Recovery Request (LRR)  8.5.9.1 Introduction  8.5.9.2 Requirement  8.5.4 Link Recovery Procedures when CCA is used on target frequency  8.5.5 Introduction  8.5.6 Requirements for SSB based beam failure detection  8.5.7 Introduction  8.5.8 Introduction  8.5.8 Requirements for SSB based beam failure detection  8.5.8 Introduction			
8.5.8.2 Scheduling availability of UE performing L1-RSRP measurement with a different subcate spacing than PDSCH/PDCCH on FR1	8.5.8.1		
spacing than PDSCH/PDCCH on FR1  8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2			205
8.5.8.3 Scheduling availability of UE performing L1-RSRP measurement on FR2  8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case FR1-FR2 inter-band CA and NR-DC  8.5.9 Requirements for Link Recovery with Link Recovery Request (LRR)  8.5.9.1 Introduction  8.5.9.2 Requirement  8.5.9.1 Link Recovery Procedures when CCA is used on target frequency  8.5.1 Introduction  8.5.2 Requirements for SSB based beam failure detection  8.5.3.1 Introduction  8.5.3.2 Minimum requirement	8.5.8.2		
8.5.8.4 Scheduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case FR1-FR2 inter-band CA and NR-DC			
FR1-FR2 inter-band CA and NR-DC  8.5.9 Requirements for Link Recovery with Link Recovery Request (LRR)  8.5.9.1 Introduction  8.5.9.2 Requirement  8.5.4 Link Recovery Procedures when CCA is used on target frequency  8.5.3 Introduction  8.5.4 Requirements for SSB based beam failure detection  8.5.5.2 Introduction  8.5.3.1 Introduction  8.5.4.2 Minimum requirement			205
8.5.9 Requirements for Link Recovery with Link Recovery Request (LRR) 8.5.9.1 Introduction	8.5.8.4		
8.5.9.1 Introduction			
8.5.9.2       Requirement         8.5A       Link Recovery Procedures when CCA is used on target frequency         8.5A.1       Introduction         8.5A.2       Requirements for SSB based beam failure detection         8.5A.2.1       Introduction         8.5A.2.2       Minimum requirement	8.5.9		
8.5A Link Recovery Procedures when CCA is used on target frequency  8.5A.1 Introduction		Introduction	206
8.5A.1 Introduction	8.5.9.2	Requirement	
8.5A.2 Requirements for SSB based beam failure detection	8.5A	Link Recovery Procedures when CCA is used on target frequency	206
8.5A.2.1 Introduction	8.5A.1	Introduction	206
8.5A.2.1 Introduction	8.5A.2	Requirements for SSB based beam failure detection	
8.5A.2.2 Minimum requirement	8.5A.2.1	Introduction	
i	8.5A.2.2	Minimum requirement	
8.5A.2.3 Measurement restriction for SSB based beam failure detection	8.5A.2.3	Measurement restriction for SSB based beam failure detection	

8.5A.4	Minimum requirement for L1 indication	
8.5A.5	Requirements for SSB based candidate beam detection	209
8.5A.5.1	Introduction	209
8.5A.5.2	Minimum requirement	209
8.5A.5.3	Measurement restriction for SSB based candidate beam detection	209
8.5A.7	Scheduling availability of UE during beam failure detection	210
8.5A.7.1	Scheduling availability of UE performing beam failure detection with a same subcarrier spacing as PDSCH/PDCCH	210
8.5A.7.2	Scheduling availability of UE performing beam failure detection with a different subcarrier spacing than PDSCH/PDCCH	210
8.5A.8	Scheduling availability of UE during candidate beam detection	
8.5A.8.1	Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier spacing	
8.5A.8.2	as PDSCH/PDCCH	
0.6	spacing than PDSCH/PDCCH	
8.6	Active BWP switch delay	
8.6.1	Introduction	
8.6.2	DCI and timer based BWP switch delay on a single CC	
8.6.2A	DCI based BWP switch delay on multiple CCs	
8.6.2A.1	Simultaneous DCI based BWP switch delay on multiple CCs	
8.6.2A.2	Non-simultaneous DCI based BWP switch delay on multiple CCs	
8.6.2B	Timer based BWP switch delay on multiple CCs	
8.6.2B.1	Simultaneous timer based BWP switch delay on multiple CCs	
8.6.2B.2	Non-simultaneous timer based BWP switch delay on multiple CCs	
8.6.3	RRC based BWP switch delay on a single CC	
8.6.3A	RRC based BWP switch delay on multiple CCs	215
8.6.3A.1	Simultaneous RRC based BWP switch delay on multiple CCs	215
8.6.3A.2	Non-simultaneous RRC based BWP switch delay on multiple CCs	216
8.6.4	BWP switch delay on Consistent UL LBT recovery	216
8.7	Void	
8.8	NE-DC: E-UTRAN PSCell Addition and Release Delay	217
8.8.1	Introduction	
8.8.2	E-UTRAN PSCell Addition Delay Requirement	217
8.8.3	E-UTRAN PSCell Release Delay Requirement	
8.9	NR-DC: PSCell Addition and Release Delay	
8.9.1	Introduction	
8.9.2	PSCell Addition Delay Requirement	
8.9.3	PSCell Release Delay Requirement.	
8.10	Active TCI state switching delay	
8.10.4	DCI based TCI state switch delay	
8.10.5	RRC based TCI state switch delay	
8.10.6	Active TCI state list update delay	
8.10A	Active TCI state switching delay with CCA	
8.10A.1	Introduction	
8.10A.1	Known conditions for TCI state	
8.10A.2 8.10A.3	MAC-CE based TCI state switch delay	
	· · · · · · · · · · · · · · · · · · ·	
8.10A.4	DCI based TCI state switch delay	
8.10A.5	RRC based TCI state switch delay	
8.10A.6	Active TCI state list update delay	
8.11	PSCell Change	
8.11A	void	
8.11B	Conditional PSCell Change	
8.11B.1	Introduction	
8.11B.2	Conditional PSCell Change delay	
8.11B.2.1	Measurement time	
8.12	Uplink spatial relation switch delay	
8.12.1	Introduction	
8.12.2	Known conditions for spatial relation when associated with DL-RS	
8.12.3	MAC-CE based spatial relation switch delay	225
8.12.4	DCI based spatial relation switch delay	226
8.12.5	RRC based spatial relation switch delay	226
8.13	UE-specific CBW change	

8.13.1	Introduction	
8.13.2	UE-specific CBW change delay	
8.14	Pathloss reference signal switching delay	226
8.14.1	Introduction	226
8.14.2	Known conditions for pathloss reference signal	227
8.14.3	MAC-CE based pathloss reference signal switch delay	227
0 1/		225
	easurement Procedure	
9.1	General measurement requirement	
9.1.1	Introduction	
9.1.2	Measurement gap	
9.1.2.1	EN-DC: Measurement Gap Sharing	
9.1.2.1a	SA: Measurement Gap Sharing	
9.1.2.1b	NE-DC: Measurement Gap Sharing	
9.1.2.1c	NR-DC: Measurement Gap Sharing	
9.1.3	UE Measurement capability	
9.1.3.1	EN-DC: Monitoring of multiple layers using gaps	
9.1.3.1a	SA: Monitoring of multiple layers using gaps	
9.1.3.1b	NE-DC: Monitoring of multiple layers using gaps	
9.1.3.1c	NR-DC: Monitoring of multiple layers using gaps	
9.1.3.2	EN-DC: Maximum allowed layers for multiple monitoring	
9.1.3.2a	SA: Maximum allowed layers for multiple monitoring	
9.1.3.2b	NE-DC: Maximum allowed layers for multiple monitoring	
9.1.3.2c	NR-DC: Maximum allowed layers for multiple monitoring	
9.1A.3.2	Void	
9.1.3A	UE Measurement capability under operation mode with CCA	247
9.1.3A.1	EN-DC: Monitoring of multiple layers using gaps under CCA	247
9.1.3A.1 <i>A</i>		
9.1.3A.2	EN-DC: Maximum allowed layers for multiple monitoring under CCA	247
9.1A.3.2a	Void9.1.3A.2A SA: Maximum allowed layers for multiple monitoring under CCA	247
9.1.4	Capabilities for Support of Event Triggering and Reporting Criteria	248
9.1.4.1	Introduction	248
9.1.4.2	Requirements	248
9.1.5	Carrier-specific scaling factor	252
9.1.5.1	Monitoring of multiple layers outside gaps	252
9.1.5.1.1	EN-DC mode: carrier-specific scaling factor for SSB-based and CSI-RS based L3	
	measurements performed outside gaps	254
9.1.5.1.2	SA mode: carrier-specific scaling factor for SSB-based and CSI-RS based L3 measurements	
	performed outside gaps	254
9.1.5.1.3	NR-DC mode: carrier-specific scaling factor for SSB-based and CSI-RS based L3	
	measurements performed outside gaps	255
9.1.5.1.4	NE-DC mode: carrier-specific scaling factor for SSB-based and CSI-RS based measurements	
	performed outside gaps	256
9.1.5.2	Monitoring of multiple layers within gaps	257
9.1.5.2.1	EN-DC mode: carrier-specific scaling factor for SSB and CSI-RS-based L3 measurements	
	performed within gaps	258
9.1.5.2.2	SA mode: carrier-specific scaling factor for SSB and CSI-RS-based L3 measurements	
	performed within gaps	259
9.1.5.2.3	NE-DC: carrier-specific scaling factor for SSB-based and CSI-RS based L3 measurements	
	performed within gaps	261
9.1.5.2.4	NR-DC: carrier-specific scaling factor for SSB-based and CSI-RS-based L3 measurements	
	performed within gaps	262
9.1.5.2.5	SA mode: carrier-specific scaling factor for PRS-based measurements performed within gaps	
9.1.5.2.6	NE-DC: carrier-specific scaling factor for PRS-based measurements performed within gaps	
9.1.5.2.7	NR-DC: carrier-specific scaling factor for PRS-based measurements performed within gaps	
9.1.6	Minimum requirement at transitions	
9.2	NR intra-frequency measurements	
9.2.1	Introduction	
9.2.2	Requirements applicability	
9.2.3	Number of cells and number of SSB	
9.2.3.1	Requirements for FR1	
9.2.3.1	Requirements for FR?	205 265

9.2.4	Measurement Reporting Requirements	266
9.2.4.1	Periodic Reporting	
9.2.4.2	Event-triggered Periodic Reporting	266
9.2.4.3	Event Triggered Reporting	266
9.2.5	Intrafrequency measurements without measurement gaps	267
9.2.5.1	Intrafrequency cell identification	267
9.2.5.2	Measurement period	269
9.2.5.3	Scheduling availability of UE during intra-frequency measurements	270
9.2.5.3.1	Scheduling availability of UE performing measurements in TDD bands on FR1	
9.2.5.3.2	Scheduling availability of UE performing measurements with a different subcarrier spacing than PDSCH/PDCCH on FR1	
9.2.5.3.3	Scheduling availability of UE performing measurements on FR2	
9.2.5.3.4	Scheduling availability of UE performing measurements on FR1 or FR2 in case of FR1-FR2	
0254	inter-band CA	
9.2.5.4	SFTD Measurements between PCell and PSCell	
9.2.5.4.1	Introduction	
9.2.5.4.2	SFTD Measurement delay	
9.2.5.4.3	SFTD Measurement Reporting Delay	
9.2.6	Intra-frequency measurements with measurement gaps	
9.2.6.1	Void	
9.2.6.2	Intra-frequency cell identification	
9.2.6.3	Intrafrequency Measurement Period	
9.2A	NR intra-frequency measurements with CCA	
9.2A.1	Introduction	276
9.2A.2	Requirements applicability	
9.2A.3	Number of cells and number of SSB	277
9.2A.4	Measurement Reporting Requirements	277
9.2A.5	Intra-frequency measurements without measurement gaps	278
9.2A.5.2	Measurement period	
9.2A.5.3	Scheduling availability of UE during intra-frequency measurements	
9.2A.5.3.		
9.2A.5.3.		
	than PDSCH/PDCCH.	282
9.2A.6	Intra-frequency measurements with measurement gaps	
9.2A.6.1	Intra-frequency cell identification	
9.2A.6.2	Intra-frequency Measurement Period.	
9.2A.7	Intra-frequency RSSI and Channel occupancy measurements	
9.2A.7.1	Intra-frequency RSSI measurements	
9.2A.7.1 9.2A.7.2	Intra-frequency Channel occupancy measurements	
9.2A.7.3	Scheduling restriction during RSSI and Channel Occupancy measurements	
9.3	NR inter-frequency measurements	
9.3.1	Introduction	
9.3.2	Requirements applicability	
9.3.2.1	Void	
9.3.2.2	Void	
9.3.3	Number of cells and number of SSB	
9.3.3.1	Requirements for FR1	
9.3.3.2	Requirements for FR2	
9.3.4	Inter-frequency measurement with measurement gaps	287
9.3.4.1	Void	289
9.3.4.2	Void	289
9.3.5	Inter-frequency measurements	289
9.3.5.1	Void	289
9.3.5.2	Void	289
9.3.5.3	Void	289
9.3.6	Inter-frequency measurements reporting requirements	
9.3.6.1	Periodic Reporting	
9.3.6.2	Event-triggered Periodic Reporting	
9.3.6.3	Event-triggered Reporting.	
9.3.7	Void	
9.3.8	Inter-frequency SFTD measurement requirements	
9.3.8 9.3.8.1	Introduction	
7.J.O.I	111u Oquo (1011	∠フし

9.3.8.2	SFTD Measurement delay	290
9.3.8.3	SFTD Measurement reporting delay	291
9.3.9	Inter frequency measurements without measurement gaps	292
9.3.9.1	Inter frequency Cell identification	
9.3.9.2	Measurement period	
9.3.9.3	Scheduling availability of UE during inter-frequency measurements	294
9.3.9.3.1	Scheduling availability of UE performing measurements in TDD bands on FR1	
9.3.9.3.2	Scheduling availability of UE performing measurements with a different subcarrier spacing	
	than PDSCH/PDCCH on FR1	295
9.3.9.3.3	Scheduling availability of UE performing measurements on FR2	295
9.3.9.3.4	Scheduling availability of UE performing measurements on FR1 or FR2 in case of FR1-FR2	
	inter-band CA	295
9.3A	NR inter-frequency measurements in carrier frequencies with CCA	296
9.3A.1	Introduction	
9.3A.2	Requirements applicability	296
9.3A.3	Number of cells and number of SSB	
9.3A.3.1	Requirements	296
9.3A.4	Inter-frequency cell identification	
9.3A.5	Inter-frequency measurements	
9.3A.6	NR Inter-frequency measurements reporting requirements	
9.3A.6.1	Periodic Reporting	
9.3A.6.2	Event-triggered Periodic Reporting	
9.3A.6.3	Event-triggered Reporting	
9.3A.8	Inter-frequency RSSI measurements	
9.3A.9	Inter-frequency channel occupancy measurements	
9.4	Inter-RAT measurements	
9.4.1	Introduction	
9.4.2	NR – E-UTRAN FDD measurements	
9.4.2.1	Introduction	
9.4.2.2	Requirements when no DRX is used	
9.4.2.3	Requirements when DRX is used	
9.4.2.4	Measurement reporting requirements	
9.4.2.4.1	Periodic Reporting	
9.4.2.4.2	Event-Triggered Periodic Reporting	
9.4.2.4.3	Event-Triggered Reporting	
9.4.3	NR – E-UTRAN TDD measurements	
9.4.3.1	Introduction	
9.4.3.2	Requirements when no DRX is used	
9.4.3.3	Requirements when DRX is used	
9.4.3.4	Measurement reporting requirements	
9.4.3.4.1	Periodic Reporting	
9.4.3.4.2	Event-Triggered Periodic Reporting	
9.4.3.4.3	Event-Triggered Reporting	
9.4.4	Inter-RAT RSTD measurements	
9.4.4.1	NR – E-UTRAN FDD RSTD measurements	307
9.4.4.1.1	Introduction	307
9.4.4.1.2	Requirements	308
9.4.4.2	NR – E-UTRAN TDD RSTD measurements	
9.4.4.2.1	Introduction	311
9.4.4.2.2	Requirements	311
9.4.5	Inter-RAT E-CID measurements	
9.4.5.1	NR-E-UTRAN FDD E-CID RSRP and RSRQ measurements	315
9.4.5.1.1	Introduction	
9.4.5.1.2	Requirements	315
9.4.5.1.3	Measurement Reporting Delay	315
9.4.5.2	NR-E-UTRAN TDD E-CID RSRP and RSRQ measurements	
9.4.5.2.1	Introduction	
9.4.5.2.2	Requirements	315
9.4.5.2.3	Measurement Reporting Delay	
9.4.6	NR – UTRAN FDD measurements	
9.4.6.1	Introduction	315
9.4.6.2	Requirements when no DRX is used	316

9.4.6.3	Requirements when DRX is used	
9.4.7	NR – E-UTRAN measurements with autonomous gaps	.319
9.4.7.1	CGI identification of an E-UTRA cell with autonomous gaps	.319
9.4.7.2	CGI reporting delay	
9.5	L1-RSRP measurements for Reporting	
9.5.1	Introduction	.319
9.5.2	Requirements applicability	.319
9.5.3	Measurement Reporting Requirements	
9.5.3.1	Periodic Reporting	
9.5.3.2	Semi-Persistent Reporting	
9.5.3.3	Aperiodic Reporting	
9.5.4	L1-RSRP measurement requirements.	
9.5.4.1	SSB based L1-RSRP Reporting	
9.5.4.2	CSI-RS based L1-RSRP Reporting	
9.5.4A	Void	
9.5.4A.1	Void	
9.5.5	Measurement restriction for CSI-RS and SSB for L1-RSRP measurement	
9.5.5.1	Measurement restriction for SSB based L1-RSRP	
9.5.5.2	Measurement restriction for CSI-RS based L1-RSRP	
9.5.6	Scheduling availability of UE during L1-RSRP measurement	
9.5.6.1	Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier spacing	.520
7.5.0.1	as PDSCH/PDCCH on FR1	326
9.5.6.2	Scheduling availability of UE performing L1-RSRP measurement with a different subcarrier	.520
7.5.0.2	spacing than PDSCH/PDCCH on FR1	327
9.5.6.3	Scheduling availability of UE performing L1-RSRP measurement on FR2	
9.5.6.4	Scheduling availability of UE performing L1-RSRP measurement on FR1 or FR2 in case of	.521
7.5.0.4	FR1-FR2 inter-band CA	328
9.5A	L1-RSRP measurements for Reporting under CCA	
9.5A.1	Introduction	
9.5A.1 9.5A.2	Requirements applicability	
9.5A.2 9.5A.3	Measurement Reporting Requirements	
9.5A.3.1	Periodic Reporting	
9.5A.3.1 9.5A.3.2	Semi-Persistent Reporting.	
9.5A.3.2 9.5A.3.3		
	Aperiodic Reporting.	
9.5A.4	L1-RSRP measurement requirements.	
9.5A.4.1	SSB based L1-RSRP Reporting	
9.5A.5	Measurement restriction for L1-RSRP measurement  Measurement restriction for SSB based L1-RSRP	
9.5A.5.1		
9.5A.6	Scheduling availability of UE during L1-RSRP measurement	.331
9.5A.6.1	Scheduling availability of UE performing L1-RSRP measurement with a same subcarrier spacing	221
0.54.60	as PDSCH/PDCCH	.331
9.5A.6.2	Scheduling availability of UE performing L1-RSRP measurement with a different subcarrier	221
0.54.62	spacing than PDSCH/PDCCH	.331
9.5A.6.3	Scheduling availability of UE performing L1-RSRP measurement in case of FR1-FR2 inter-band	221
0.6	CA	
9.6	NE-DC: Measurements	
9.6.1	Introduction	
9.6.2	SFTD Measurements	
9.6.2.1	Introduction	
9.6.2.2	SFTD Measurement requirements	
9.7	Cross Link Interference measurements	
9.7.1	Introduction	
9.7.2	SRS-RSRP measurements	
9.7.2.1	Introduction	
9.7.2.2	Requirements applicability	
9.7.2.3	Measurement Reporting Requirements	
9.7.2.3.1	Periodic Reporting	
9.7.2.3.2	Event-triggered Periodic Reporting	
9.7.2.3.3	Event Triggered Reporting	
9.7.2.4	Measurement capability	
9.7.2.5	SRS-RSRP measurement period	
9.7.3	CLI-RSSI measurements	.334

9.7.3.1	Introduction	
9.7.3.2	Requirements applicability	
9.7.3.3	Measurement Reporting Requirements	
9.7.3.3.1	Periodic Reporting	
9.7.3.3.2	Event-triggered Periodic Reporting.	
9.7.3.3.3	Event Triggered Reporting	
9.7.3.4	Measurement capability	
9.7.3.5	CLI-RSSI measurement period	
9.7.4	Scheduling availability of UE during CLI measurements	
9.7.4.1	Scheduling availability of UE performing measurement on FR1	
9.7.4.2	Scheduling availability of UE performing measurement on FR2	
9.8	L1-SINR measurements for Reporting	
9.8.1	Introduction	
9.8.2	Requirements applicability	
9.8.3	Measurement Reporting Requirements	
9.8.3.1	Periodic Reporting	
9.8.3.2	Semi-Persistent Reporting	
9.8.4 9.8.4.1	L1-SINR measurement requirements	
9.8.4.1	L1-SINR reporting with CSI-RS based CMR and dedicated IMR configured	
9.8.5	Measurement restriction for L1-SINR measurement	
9.8.5.1	Measurement restriction if SSB configured for L1-SINR Measurement	
9.8.5.2	Measurement restriction if CSI-RS configured for L1-SINR measurement	
9.8.5.3	Measurement restriction if CSI-IM configured for L1-SINR measurement	
9.8.6	Scheduling availability of UE during L1-SINR measurement	
9.8.6.1	Scheduling availability of UE performing L1-SINR measurement with a same subcarrier spacing	575
7.0.0.1	as PDSCH/PDCCH on FR1	345
9.8.6.2	Scheduling availability of UE performing L1-SINR measurement with a different subcarrier	
	spacing than PDSCH/PDCCH on FR1	345
9.8.6.4	Scheduling availability of UE performing L1-SINR measurement on FR1 or FR2 in case of FR1-	
	FR2 inter-band CA	346
9.9	NR measurements for positioning	346
9.9.1	Introduction	346
9.9.2	RSTD measurements	
9.9.2.1	Introduction	
9.9.2.2	Requirements Applicability	
9.9.2.3	Measurement Capability	
9.9.2.4	Measurement Reporting Requirements	
9.9.2.4.1	Void	
9.9.2.4.2 9.9.2.4.3	Void	
9.9.2.4.3	Void	
9.9.2.5	Void	
9.9.2.0	PRS-RSRP measurements	
9.9.3.1	Introduction	
9.9.3.2	Requirements applicability	
9.9.3.3	Measurement Capability	
9.9.3.4	Measurement Reporting Requirements	
9.9.3.5	Measurement Period Requirements	
9.9.4	UE Rx-Tx time difference measurements	
9.9.4.1 In	troduction	351
9.9.4.2 R	equirements Applicability	351
9.9.4.3 M	leasurement Capability	351
	leasurement Reporting Requirements	
	leasurement Period Requirements	
9.9.5	NR E-CID measurements	
9.9.5.1	Introduction	
9.9.5.2	Measurement Requirements	
9.9.5.2.1	Intra-frequency Measurement Requirements	
9.9.5.2.2	Inter-frequency Measurement Requirements	
9.9.5.2.3	Measurement Reporting Delay	
9.10	CSI-RS based L3 measurements	> > 4

9.10.1	Introduction	
9.10.2	CSI-RS based intra-frequency measurements	354
9.10.2.1	Introduction	354
9.10.2.2	Requirements applicability	355
9.10.2.3	Number of cells and number of CSI-RS	355
9.10.2.3.	Requirements for FR1	355
9.10.2.3.2	2 Requirements for FR2	356
9.10.2.4	Measurement Reporting Requirements	
9.10.2.4.		
9.10.2.4.2		
9.10.2.4.3		
9.10.2.5	Intra-frequency measurements without measurement gaps	
9.10.2.6	Scheduling availability of UE during CSI-RS based intra-frequency measurements	
9.10.2.6.1		
9.10.2.6.2		250
9.10.2.0.2 9.10.3	CSI-RS based Inter-frequency measurements	
9.10.3	Introduction	
9.10.3.2	Requirements applicability	
9.10.3.3	Number of cells and number of CSI-RS resources	
9.10.3.3.	1	
9.10.3.3.2	1	
9.10.3.4	Measurements reporting requirements	
9.10.3.4.	1 6	
9.10.3.4.2		
9.10.3.4.3		
9.10.3.5	Inter frequency measurements with measurement gaps	
9.11	NR measurements with autonomous gaps	361
9.11.1	Introduction	361
9.11.2	CGI identification of an NR cell with autonomous gaps	361
9.11.3	CGI reporting delay	
10 14		
	easurement Performance requirements	
10.1	NR measurements	
10.1.1	Introduction	
10.1.2	Intra-frequency RSRP accuracy requirements for FR1	
10.1.2.1	Intra-frequency SS-RSRP accuracy requirements	363
10.1.2.1.	Absolute SS-RSRP Accuracy	363
10.1.2.1.2	Relative SS-RSRP Accuracy	364
10.1.2.2	Void	365
10.1.3	Intra-frequency RSRP accuracy requirements for FR2	365
10.1.3.1	Intra-frequency SS-RSRP accuracy requirements	
10.1.3.1.		
10.1.3.1.2	•	
10.1.3.2	Void	
10.1.3.2	Inter-frequency RSRP accuracy requirements for FR1	
10.1.4.1	Inter-frequency SS-RSRP accuracy requirements	
10.1.4.1.		
10.1.4.1.2		
10.1.4.2	Void	
10.1.5	Inter-frequency RSRP accuracy requirements for FR2	
10.1.5.1	Inter-frequency SS-RSRP accuracy requirements	
10.1.5.1.	•	
10.1.5.1.2	•	
10.1.5.2	Void	
	SRP Measurement Report Mapping	
10.1.7	Intra-frequency RSRQ accuracy requirements for FR1	
10.1.7.1	Intra-frequency SS-RSRQ accuracy requirements in FR1	372
10.1.7.1.	Absolute SS-RSRQ Accuracy in FR1	372
10.1.8	Intra-frequency RSRQ accuracy requirements for FR2	373
10.1.8.1	Intra-frequency SS-RSRQ accuracy requirements in FR2	
10.1.8.1.		
10 1 9	Inter-frequency RSRO accuracy requirements for FR1	374

10.1.9.1	Inter-frequency SS-RSRQ accuracy requirements in FR1	
10.1.9.1.1	Aboslute Accuracy of SS-RSRQ in FR1	374
10.1.9.1.2	Relative Accuracy of SS-RSRQ in FR1	
10.1.10	Inter-frequency RSRQ accuracy requirements for FR2	
10.1.11	RSRQ report mapping	
10.1.12	Intra-frequency SINR accuracy requirements for FR1	
10.1.13	Intra-frequency SINR accuracy requirements for FR2	
10.1.14	Inter-frequency SINR accuracy requirements for FR1	
10.1.15	Inter-frequency SINR accuracy requirements for FR2	
10.1.16	SINR report mapping	
10.1.17	Power Headroom	
10.1.18	P <sub>CMAX,c,f</sub>	
10.1.19	L1-RSRP accuracy requirements for FR1	
10.1.20	L1-RSRP accuracy requirements for FR2	
10.1.21	SFTD accuracy requirements	
10.1.22	CLI measurement accuracy requirements	
10.1.24.3.1	Absolute PRS-RSRP Measurement Report Mapping	
10.1.24.3.2	Differential Report Mapping for PRS-RSRP Measurement	
10.1.23	RSTD Measurements	
10.1.23.1	Introduction	
10.1.23.2	Measurement Accuracy Requirements	
10.1.23.3	Report mapping	
10.1.23.3.1	Absolute DL RSTD Measurement Reporting	
10.1.23.3.2	Differential Reporting for DL RSTD Measurement	
10.1.23.3.3	Additional Path Report Mapping for DL RSTD	
10.1.24 10.1.24.1	PRS-RSRP Measurements  Introduction	
10.1.24.1		
10.1.24.2	Measurement Accuracy Requirements  Report mapping	
10.1.24.3	Absolute PRS-RSRP Measurement Report Mapping	
10.1.24.3.1	Differential Report Mapping for PRS-RSRP Measurement	
10.1.25	UE Rx-Tx Time Difference Measurements	
10.1.25.1	Introduction	
10.1.25.2	Measurement Accuracy Requirements	
10.1.25.3	Report mapping	
10.1.25.3.1	Absolute UE Rx-Tx Measurement Report Mapping	
10.1.25.3.2	Differential UE Rx-Tx Measurement Report Mapping	
10.1.25.3.3	Additional Path Report Mapping for UE Rx-Tx Time Difference	
10.1.26	FR2 P-MPR report	
10.1.26.1	Report mapping	
10.1.27	L1-SINR accuracy requirements for FR1	
10.1.27.1	L1-SINR accuracy requirements with CSI-RS based CMR and no dedicated IMR configured	
10.1.27.1.1	Absolute Accuracy	419
10.1.27.1.2	Relative Accuracy	420
10.1.27.2	L1-SINR accuracy requirements with SSB based CMR and dedicated IMR configured	421
10.1.27.2.1	Absolute Accuracy	421
10.1.27.2.2	Relative Accuracy	
10.1.27.3	L1-SINR accuracy requirements with CSI-RS based CMR and dedicated IMR configured	
10.1.27.3.1	Absolute Accuracy	
10.1.27.3.2	Relative Accuracy	
10.1.28	L1-SINR accuracy requirements for FR2	
10.1.28.1	L1-SINR accuracy requirements with CSI-RS based CMR and no dedicated IMR configured	
10.1.28.1.1	Absolute Accuracy	
10.1.28.1.2	Relative Accuracy	
10.1.28.2	L1-SINR accuracy requirements with SSB based CMR and dedicated IMR configured	
10.1.28.2.1	Absolute Accuracy	
10.1.28.2.2	Relative Accuracy	
10.1.28.3	L1-SINR accuracy requirements with CSI-RS based CMR and dedicated IMR configured	
10.1.28.3.1	Absolute Accuracy	
10.1.28.3.2 10.2 E-	Relative Accuracy UTRAN measurements	
10.2 E-	Introduction	
10.2.1	HII OUG VIOII	+∪+

10.2.2	E-UTRAN RSRP measurements	434
10.2.3	E-UTRAN RSRQ measurements	
10.2.4	E-UTRAN RSTD measurements	434
10.2.5	E-UTRAN RS-SINR measurements.	435
10.3	UTRAN FDD Measurements	
10.3.1	UTRAN FDD CPICH RSCP	
10.3.2	UTRAN FDD CPICH Ec/No	
10.4	V2X measurements	
10.4.1	Introduction	
10.4.2	Intra-frequency PSBCH-RSRP accuracy requirements for FR1	
10.4.2.	J	
10.4.2.		
10.4.3	Intra-Frequency SL-RSSI Measurement Accuracy Requirements for FR1	
10.4.3.		438
10.4.4	Intra-Frequency L1 SL-RSRP Measurement Accuracy Requirements for FR1	
10.4.4.	1 Absolute L1 SL-RSRP Accuracy	438
11	Void	439
12	V2X Requirements	
12.1	Introduction	
12.2	UE Transmit Timing	
12.2.1	Introduction	
12.2.2	GNSS as synchronization reference source	439
12.2.3	NR Cell as synchronization reference source	
12.2.4	E-URTAN Cell as synchronization reference source	
12.2.5	SyncRef UE as synchronization reference source	
12.3	Initiation/Cease of SLSS Transmissions	
12.3.1	Introduction	
12.3.1.	<b>J</b>	
12.3.1.		
12.3.1.		
12.3.1.		
12.4	Selection / Reselection of V2X Synchronization Reference Source	
12.5	L1 SL-RSRP measurements	
12.5.1	Introduction	
12.5.2	SL-RSRP measurements	
12.6	Congestion Control measurements	
12.7	Interruption	
12.7.1	Interruptions to WAN due to V2X Sidelink Communication	
12.7.2	V2X Sidelink Communication Dropping due to synchronization source change	
12.7.3	Interruptions to WAN due to switching between E-UTRA V2X Sidelink and NR V2X Sidelink	
12.8	Reliability of GNSS signal	
12.9	Scheduling availability	
12.9.1	Scheduling availability of UE switching between E-UTRA sidelink and NR sidelink	448
13	Measurement Performance Requirements for NR gNB	448
13.1	UL-RTOA	
13.1.1	Report mapping	
13.2	gNB Rx-Tx time difference	
13.2.1	Report mapping	
13.3	UL SRS RSRP measurement	
13.3.1	Report mapping	
13.4	AoA/ZoA	
13.4.1	Report mapping	
	x A (normative): Test Cases	
	Purpose of annex	
A.2	Requirement classification for statistical testing	422
A.2.1 A.2.1.1	Types of requirements in TS 38.133	
A.2.1.2		
A.Z.I.2	ivicasurchichts of power ievers, tefative powers and time	4∠3

A.2.1.3	Implementation requirements	
A.2.1.4	Physical layer timing requirements	424
4.2 DI	DM 4 4 C 4	125
	RM test configurations	
A.3.1	Reference measurement channels	
A.3.1.1	PDSCH	
A.3.1.1.1	FDD	
A.3.1.1.2		
A.3.1.2	CORESET for RMSI scheduling	
A.3.1.2.1	FDD	
A.3.1.2.2	TDD	
A.3.1.3	CORESET for RMC scheduling	
A.3.1.3.1	FDD	
A.3.1.3.2	TDD	
A.3.1.4	TDD UL/DL configuration	
A.3.2	OFDMA channel noise generator (OCNG)	
A.3.2.1	Generic OFDMA Channel Noise Generator (OCNG)	
A.3.2.1.1	OCNG pattern 1: Generic OCNG pattern for all unused REs	
A.3.2.1.2	OCNG pattern 2: Generic OCNG pattern for all unused REs for 2AoA setup	
A.3.2.1.3	OCNG pattern 3: Generic OCNG pattern for unused REs in the same bandwidth as CORESET	
A.3.2.1.4	OCNG pattern 4: Generic OCNG pattern for all unused REs outside SSB slot(s)	440
A.3.2.2	Void	441
A.3.3	Reference DRX configurations	441
A.3.3.1	DRX Configuration 1: DRX cycle = 40 ms and TAT = 500 ms	441
A.3.3.2	DRX Configuration 2: DRX cycle = 640 ms and TAT = 500 ms	441
A.3.3.3	DRX Configuration 3: DRX cycle = 40 ms and TAT = Infinity	
A.3.3.4	DRX Configuration 4: DRX cycle = 160 ms and TAT = Infinity	
A.3.3.5	DRX Configuration 5: DRX cycle = 320 ms and TAT = Infinity	
A.3.3.6	DRX Configuration 6: DRX cycle = 320 ms and TAT = 500 ms	
A.3.3.7	DRX Configuration 7: DRX cycle = 640 ms and TAT = Infinity	
A.3.3.8	DRX Configuration 8: DRX cycle = 320 ms and TAT = Infinity	
A.3.3.9	DRX Configuration 9: DRX cycle = 40 ms and TAT = 500 ms	
A.3.3.10	DRX Configuration 10: DRX cycle = 640 ms.	
A.3.3.11	DRX Configuration 11: DRX cycle = 20 ms and TAT = Infinity	
A.3.3.11	Test Cases with Different Channel Bandwidths	
A.3.4.1	Test Cases with Different E-UTRA Channel Bandwidths	
A.3.4.1 A.3.4.1.1	Introduction	
A.3.4.1.1 A.3.4.1.2	Principle of testing	
A.3.4.1.2 A.3.5		
	Test Cases for Synchronous and Asynchronous DC Operations	
A.3.5.1	EN-DC Test Cases for Synchronous and Asynchronous EN-DC Operations	
A.3.5.1.1	Introduction	
A.3.5.1.2	Principle of Testing	
A.3.6	Antenna configurations	
A.3.6.1	Antenna configurations for FR1	
A.3.6.1.1	Antenna connection for 4 Rx capable UEs	
A.3.6.1.1		
A.3.6.1.1		
A.3.6.2	Antenna configurations for FR2	448
A.3.7	EN-DC test setup	448
A.3.7.1	Introduction	448
A.3.7.2	E-UTRAN Serving Cell Parameters	448
A.3.7.2.1	E-UTRAN Serving Cell Parameters for Tests with NR Cell(s) in FR1	448
A.3.7.2.2	E-UTRAN Serving Cell Parameters for Tests with NR Cell(s) in FR2	
A.3.7A	NR FR1-FR2 test setup	
A.3.8	PRACH configurations	
A.3.8.1	Introduction	
A.3.8.2	PRACH configurations in FR1	
A.3.8.2.1	FR1 PRACH configuration 1	
A.3.8.2.2	FR1 PRACH configuration 2	
A.3.8.2.3	FR1 PRACH configuration 3	
A.3.8.2.4	FR1 PRACH configuration 4	
A.3.8.3	PRACH configurations in FR2	
11.0.0.0	1121011 0011116919410110 111 112	i∋-r

A.3.8.3.1 FR2 PRACH configuration 1	
A.3.8.3.2 FR2 PRACH configuration 2	
A.3.8.3.3 FR2 PRACH configuration 3	
A.3.8.3.4 FR2 PRACH configuration 4	
A.3.9 BWP configurations	
A.3.9.1 Introduction	
A.3.9.2 Downlink BWP configurations	
A.3.9.2.1 Initial BWP	
A.3.9.2.2 Dedicated BWP	
A.3.9.3 Uplink BWP configurations	
A.3.9.3.1 Initial BWP	
A.3.9.3.2 Dedicated BWP	
A.3.10 SSB Configurations	
A.3.10.1 SSB Configurations for FR1	
A.3.10.1.1 SSB pattern 1 in FR1: SSB allocation for SSB SCS=15 kHz in 10 MHz	
A.3.10.1.5 SSB pattern 5 in FR1: SSB allocation for SSB SCS=15 kHz starting from odd SFN in 10 MF	
A.3.11 SMTC Configurations	
A.3.11.1 SMTC pattern 1: SMTC period = 20 ms with SMTC duration = 1 ms	
A.3.11.2 SMTC pattern 2: SMTC period = 20 ms with SMTC duration = 5 ms	
A.3.11.3 SMTC pattern 3: SMTC period = 160 ms with SMTC duration = 1 ms	
A.3.11.4 SMTC pattern 4: SMTC period = 20 ms with SMTC duration = 1 ms	
A.3.11.5 SMTC pattern 5: SMTC period = 20 ms with SMTC duration = 5 ms	
A.3.12 Test Cases with Different CC Configurations	
A.3.12.1 EN-DC Test Cases with Different EN-DC Configurations	
A.3.12.1.1 Introduction	
A.3.12.1.2 Principle of testing	
A.3.12.2 Carrier Aggregation Test Cases with Different CA Configurations	
A.3.12.2.1 Introduction	
A.3.12.2.2 Principle of testing	
A.3.13 Test Cases in SA and EN-DC Operations	
A.3.13.1 Introduction	
A.3.13.2 Principle of Testing	
A.3.14 CSI-RS configurations	
A.3.14.1 FDD	
A.3.14.2 TDD	
A.3.15 Angle of Arrival (AoA) for FR2 RRM test cases	
A.3.15.1 Setup 1: Single AoA in Rx beam peak direction	
A.3.15.2 Setup 2: Single AoA in non Rx beam peak direction	
A.3.15.2.1 Setup 2a: Single AoA in non Rx beam peak direction without change in direction	
A.3.15.2.2 Setup 2b: Single AoA in non Rx beam peak direction with change in direction	
	4// 477
A.3.15.4.1 Setup 4a: 2 AoAs, 1 AoA in Rx beam peak direction, 1 in non Rx beam peak without change direction	
A.3.15.4.2 Setup 4b: 2 AoAs, 1 AoA in Rx beam peak direction, 1 in non Rx beam peak with change in	
direction	
A.3.16 TCI State Configuration	
A.3.16.1 Introduction	
A.3.16.2 TCI states	
A.3.17 Configurations of CSI-RS for tracking	
A.3.17.1 Configuration of CSI-RS for tracking for FR1	
A.3.17.1.1 FDD	
A.3.17.1.2 TDD	
A.3.17.2 Configuration of CSI-RS for tracking for FR2	
A.3.17.2.1 TDD	
A.3.18 Additional definitions related to OTA testing for FR2 RRM test cases	
A.3.18.1 Introduction	
A.3.18.2 PRACH Power Measurement	
A.3.19 Test applicability for DAPS handover	
A.3.19.1 Introduction	
A.3.19.2 Principle of testing	
A.3.20 MsgA configurations	

	duction	
	A configurations in FR1	
	R1 MsgA configuration 1	
	R1 MsgA configuration 2	
	A configurations in FR2	.485
A.3.20.3.1 F	R2 MsgA configuration 1	.485
A.3.20.3.2 F	R2 MsgA configuration 2	486
A.3.21 V2X side	elink communication	488
	duction	
A.3.21.2 Refer	rence resource pool configurations for V2X Sidelink Communication	488
	rence measurement channels for V2X Sidelink Communication	
A.3.22 CSI-IM	configurations	495
A.3.22.1 FDD		495
A.3.22.2 TDD		496
A.3.23 Spatial R	lelation Configuration	498
	duction	
A.3.23.2 Spati	al Relation	.498
	figuration	
	bandwidth (CBW) configurations	
	JE specific CBW	
	IE specific CBW	
	•	
	ts with all NR cells in FR1	
	DNNECTED state mobility	
A.4.3.2 RRC	Connection Mobility Control	502
	oid	
A.4.3.2.2 R	andom Access	.502
A.4.3.2.2.1	4-step RA type contention based random access test in FR1 for PSCell in EN-DC	
A.4.3.2.2.2	4-step RA type non-contention based random access test in FR1 for PSCell in EN-DC	505
A.4.3.2.2.3	2-step RA type contention based random access test in FR1 for PSCell in EN-DC	
A.4.3.2.2.4	2-step RA type non-contention based random access test in FR1 for PSCell in EN-DC	512
A.4.3.2.3 V	oid	516
A.4.4 Timing		516
A.4.4.1 UE tr	ansmit timing	516
A.4.4.1.1 N	R UE Transmit Timing Test for FR1	516
A.4.4.1.1.1	Test Purpose and environment	516
A.4.4.1.1.2	Test requirements	520
A.4.4.2 UE ti	mer accuracy	520
A.4.4.3 Timis	ng advance	520
	N-DC FR1 timing advance adjustment accuracy	
A.4.4.3.1.1	Test Purpose and Environment	
A.4.4.3.1.2	Test Parameters	
A.4.4.3.1.3	Test Requirements	
A.4.5 Signaling	g characteristics	
	o link Monitoring	
	adio Link Monitoring Out-of-sync Test for FR1 PSCell configured with SSB-based RLM RS in	
	on-DRX mode	525
A.4.5.1.1.1	Test Purpose and Environment	
A.4.5.1.1.2	Test Requirements	
-	adio Link Monitoring In-sync Test for FR1 PSCell configured with SSB-based RLM RS in	,
	on-DRX mode	529
A.4.5.1.2.1	Test Purpose and Environment	
A.4.5.1.2.2	Test Requirements	
	adio Link Monitoring Out-of-sync Test for FR1 PSCell configured with SSB-based RLM RS in	
	RX mode	535
A.4.5.1.3.1	Test Purpose and Environment	
A.4.5.1.3.2	Test Requirements	
	adio Link Monitoring In-sync Test for FR1 PSCell configured with SSB-based RLM RS in	1
	RX mode	5⊿1
D	101 111000	

A.4.5.1.4.1	Test Purpose and Environment	541
A.4.5.1.4.2	Test Requirements	547
A.4.5.1.5	EN-DC Radio Link Monitoring Out-of-sync Test for FR1 PSCell configured with CSI-RS-based	
	RLM in non-DRX mode	547
A.4.5.1.5.1	Test Purpose and Environment	
A.4.5.1.5.2	Test Requirements	553
A.4.5.1.6	EN-DC Radio Link Monitoring In-sync Test for FR1 PSCell configured with CSI-RS-based	
	RLM in non-DRX mode	553
A.4.5.1.6.1	Test Purpose and Environment	
A.4.5.1.6.2	Test Requirements	
A.4.5.1.7	EN-DC Radio Link Monitoring Out-of-sync Test for FR1 PSCell configured with CSI-RS-based	
	RLM in DRX mode	559
A.4.5.1.7.1	Test Purpose and Environment	
A.4.5.1.7.2	Test Requirements	
A.4.5.1.8	EN-DC Radio Link Monitoring In-sync Test for FR1 PSCell configured with CSI-RS-based	
	RLM in DRX mode	565
A.4.5.1.8.1	Test Purpose and Environment	
A.4.5.1.8.2	Test Requirements	
A.4.5.2	Interruption	
A.4.5.2.1	E-UTRAN – NR FR1 interruptions at transitions between active and non-active during DRX in	
-	synchronous EN-DC	570
A.4.5.2.1.1	Test Purpose and Environment	
A.4.5.2.1.2	Test Requirements	
A.4.5.2.2	E-UTRAN – NR FR1 interruptions at transitions between active and non-active during DRX in	
	asynchronous EN-DC	.574
A.4.5.2.2.1	Test Purpose and Environment.	
A.4.5.2.2.2	Test Requirements	
A.4.5.2.3	E-UTRAN – NR FR1 interruptions during measurements on deactivated NR SCC in	
11.1.5.2.5	synchronous EN-DC	578
A.4.5.2.3.1	Test Purpose and Environment	
A.4.5.2.3.2	Test Requirements	
A.4.5.2.4	E-UTRAN – NR FR1 interruptions during measurements on deactivated NR SCC in	
-	asynchronous EN-DC	582
A.4.5.2.4.1	Test Purpose and Environment	
A.4.5.2.4.2	Test Requirements	
A.4.5.2.5	E-UTRAN – NR FR1 interruptions during measurements on deactivated E-UTRAN SCC in	
	synchronous EN-DC	586
A.4.5.2.5.1	Test Purpose and Environment.	
A.4.5.2.5.2	Test Requirements	
A.4.5.2.6	E-UTRAN – NR FR1 interruptions during measurements on deactivated E-UTRAN SCC in	
	asynchronous EN-DC	590
A.4.5.2.6.1	Test Purpose and Environment	
A.4.5.2.6.2	Test Requirements	
A.4.5.2.7	Void	
A.4.5.2.8	E-UTRAN - NR FR1 interruptions at NR SRS carrier based switching in asynchronous EN-DC	
A.4.5.2.8.1	Test Purpose and Environment	
A.4.5.2.8.2	Test Requirements	
A.4.5.2.9	E-UTRAN – NR interruptions at E-UTRA SRS carrier based switching	
A.4.5.2.9.1	Test Purpose and Environment	
A.4.5.2.9.2	Test Requirements	
A.4.5.3	SCell Activation and Deactivation Delay	
A.4.5.3.1	SCell Activation and deactivation of known SCell in FR1 for 160ms SCell measurement cycle	
A.4.5.3.1.1	Test Purpose and Environment	
A.4.5.3.1.2	Test Requirements	
A.4.5.3.2	SCell Activation and deactivation of known SCell in FR1 for 320 ms SCell measurement cycle	
A.4.5.3.2.1	Test Purpose and Environment	
A.4.5.3.2.2	Test Requirements	
A.4.5.3.3	SCell Activation and deactivation of unknown SCell in FR1	
A.4.5.3.3.1	Test Purpose and Environment	
A.4.5.3.3.2	Test Requirements	
A.4.5.3.4	SCell Activation and deactivation of multiple unknown SCells in FR1 with single	-
	activation/deactivation command	610

A.4.5.3.4.1	Test Purpose and Environment	610
A.4.5.3.4.2	Test Requirements	614
A.5.5.3.6	Multiple SCell Activation and deactivation of one unknown SCell and one known SCell in FR2	614
A.5.5.3.6.1	Test Purpose and Environment	
A.5.5.3.6.2	Test Requirements	
A.4.5.4	UE UL carrier RRC reconfiguration Delay	
A.4.5.4.1	UE UL carrier RRC reconfiguration Delay	
-		
	Test Purpose and Environment	
A.4.5.4.1.2	Test Requirements	
A.4.5.5	Beam Failure Detection and Link recovery procedures	626
A.4.5.5.1	EN-DC Beam Failure Detection and Link Recovery Test for FR1 PSCell configured with SSB-	
	based BFD and LR in non-DRX mode	
A.4.5.5.1.1	Test Purpose and Environment	
A.4.5.5.1.2	Test Requirements	632
A.4.5.5.2	EN-DC Beam Failure Detection and Link Recovery Test for FR1 PSCell configured with SSB-	
	based BFD and LR in DRX mode	632
A.4.5.5.2.1	Test Purpose and Environment	632
A.4.5.5.2.2	Test Requirements	
A.4.5.5.3	EN-DC Beam Failure Detection and Link Recovery Test for FR1 PSCell configured with CSI-	
	RS-based BFD and LR in non-DRX mode	638
A.4.5.5.3.1	Test Purpose and Environment	
A.4.5.5.3.2	Test Requirements	
A.4.5.5.4	EN-DC Beam Failure Detection and Link Recovery Test for FR1 PSCell configured with CSI-	044
A.4.3.3.4		(11
	RS-based BFD and LR in DRX mode	
A.4.5.5.4.1	Test Purpose and Environment	
A.4.5.5.4.2	Test Requirements	650
A.4.5.5.5	EN-DC Beam Failure Detection and Link Recovery Test for FR1 SCell configured with CSI-RS-	
	based BFD and SSB-based LR in non-DRX mode	
A.4.5.5.5.1	Test Purpose and Environment.	650
A.4.5.5.5.2	Test Requirements	656
A.4.5.5.6	EN-DC Beam Failure Detection and Link Recovery Test for FR1 SCell configured with CSI-RS-	
	based BFD and SSB-based LR in DRX mode	656
A.4.5.5.6.1	Test Purpose and Environment	
A.4.5.5.6.2	Test Requirements	
A.4.5.6	Active BWP switch.	
A.4.5.6.1	DCI-based and Timer-based Active BWP Switch	
A.4.5.6.1.1	E-UTRAN – NR PSCell FR1 DL active BWP switch in non-DRX in synchronous EN-DC	
A.4.5.6.1.2	E-UTRAN – NR PSCell FR1 DL active BWP switch with FR1 SCell in non-DRX in	004
A.4.3.0.1.2		((0
	synchronous EN-DC	669
A.4.5.6.2	RRC-based Active BWP Switch	
A.4.5.6.3	Simultaneous DCI-based and Timer-based Active BWP Switch on multiple CCs	678
A.4.5.6.3.1	Simultaneous E-UTRAN – NR PSCell FR1 DL active BWP switch in non-DRX in EN-DC	
	on multiple CCs	
A.4.5.6.3.1.1	Test Purpose and Environment	678
A.4.5.6.3.1.2	Test Requirements	683
A.4.5.7	PSCell addition and release delay	684
A.4.5.7.1	Addition and Release Delay of known NR PSCell	
A.4.5.7.1.1	Test purpose and environment	
A.4.5.7.1.2	Test Requirements	
A.4.5.8	DL Interruptions at switching between two uplink carriers	
A.4.5.8.1	Test Purpose and Environment	
A.4.5.8.2	Test Requirements	
A.4.5.9		
	UE specific CBW change on EP1 NP PSCall with non DPV in symphronous EN DC	
A.4.5.9.1	UE specific CBW change on FR1 NR PSCell with non-DRX in synchronous EN- DC	
A.4.5.9.1.1	Test Purpose and Environment.	
A.4.5.9.1.2	Test Requirements	
	easurement procedure	
A.4.6.1	Intra-frequency Measurements	
A.4.6.1.1	EN-DC event triggered reporting tests without gap under non-DRX	
A.4.6.1.1.1	Test purpose and Environment	695
A.4.6.1.1.2	Test parameters	
A.4.6.1.1.3	Test Requirements	699

A.4.6.1.2	EN-DC event triggered reporting tests without gap under DRX	
A.4.6.1.2.1	Test purpose and Environment	
A.4.6.1.2.2	Test parameters	
A.4.6.1.2.2	Test Requirements	703
A.4.6.1.3	EN-DC event triggered reporting tests with per-UE gaps under non-DRX	703
A.4.6.1.3.1	Test purpose and Environment	703
A.4.6.1.3.2	Test parameters	703
A.4.6.1.3.3	Test Requirements	707
A.4.6.1.4	EN-DC event triggered reporting tests with per-UE gaps under DRX	707
A.4.6.1.4.1	Test purpose and Environment	
A.4.6.1.4.2	Test parameters	707
A.4.6.1.4.3	Test Requirements	711
A.4.6.1.5	EN-DC event triggered reporting tests without gap under non-DRX with SSB index reading	
A.4.6.1.5.1	Test purpose and Environment	711
A.4.6.1.5.2	Test parameters	
A.4.6.1.5.3	Test Requirements	
A.4.6.1.6	EN-DC event triggered reporting tests with SSB index reading with per-UE gaps	
A.4.6.1.6.1	Test purpose and Environment	
A.4.6.1.6.2	Test parameters	
A.4.6.1.6.3	Test Requirements	
A.4.6.1.7	EN-DC event triggered reporting tests under DRX for UE configured with highSpeedMeasFlag-	
	r16	717
A.4.6.1.7.1	Test purpose and Environment	
A.4.6.1.7.2	Test parameters	
A.4.6.1.7.3	Test Requirements	
A.4.6.2	Inter-frequency Measurements	
A.4.6.2.1	EN-DC event triggered reporting tests for FR1 cell without SSB time index detection when DRX	
	is not used.	721
A.4.6.2.1.1	Test Purpose and Environment	
A.4.6.2.1.2	Test Requirements	
A.4.6.2.2	EN-DC event triggered reporting tests for FR1 cell without SSB time index detection when DRX	
	is used.	
A.4.6.2.2.1	Test Purpose and Environment	
A.4.6.2.2.2	Test Requirements	
A.4.6.2.3	Void	
A.4.6.2.4	Void	
A.4.6.2.5	EN-DC event triggered reporting tests for FR1 cell with SSB time index detection when DRX is	,
	not used	730
A.4.6.2.5.1	Test Purpose and Environment	
A.4.6.2.5.2	Test Requirements	
A.4.6.2.6	EN-DC event triggered reporting tests for FR1 cell with SSB time index detection when DRX is	, c
	used	734
A.4.6.2.6.1	Test Purpose and Environment	
A.4.6.2.6.2	Test Requirements	
A.4.6.2.7	Void	
A.4.6.2.8	Void	
A.4.6.3	Void	
A.4.6.4	L1-RSRP measurement for beam reporting	
A.4.6.4.1	SSB based L1-RSRP measurement when DRX is not used	
A.4.6.4.1.1	Test Purpose and Environment.	
A.4.6.4.1.2	Test parameters	
A.4.6.4.1.3	Test Requirements	
A.4.6.4.2	SSB based L1-RSRP measurement when DRX is used	
A.4.6.4.2.1	Test Purpose and Environment.	
A.4.6.4.2.2	Test 1 dipose and Environment.  Test parameters	
A.4.6.4.2.3	Test Requirements	
A.4.6.4.3	CSI-RS based L1-RSRP measurement when DRX is not used	
A.4.6.4.3.1	Test Purpose and Environment.	
A.4.6.4.3.1 A.4.6.4.3.2	Test parameters	
A.4.6.4.3.3	Test Requirements	
A.4.6.4.4	CSI-RS based L1-RSRP measurement when DRX is used	
A.4.6.4.4 A.4.6.4.4.1	Test Purpose and Environment	
A.4.U.4.4.1	rest ruipose and Environment	13

A.4.6.4.4.2	Test parameters	
A.4.6.4.4.3	Test Requirements	754
A.4.6.4.5	SSB based L1-RSRP measurement when DRX is used for UE configured with	
	highSpeedMeasFlag-r16	754
A.4.6.4.5.1	Test Purpose and Environment	
A.4.6.4.5.2	Test parameters	
A.4.6.4.2.3	Test Requirements	758
A.4.6.5	CLI measurements	
A.4.6.5.1	SRS-RSRP measurement with non-DRX	
A.4.6.5.1.1	Test Purpose and Environment	
A.4.6.5.1.2	Test Parameters	
A.4.6.5.1.3	Test Requirements	
A.4.6.5.2	CLI-RSSI measurement with non-DRX	
A.4.6.5.2.1	Test Purpose and Environment	
A.4.6.5.2.2	Test Parameters	
A.4.6.5.2.3	Test Requirements	
A.4.6.6	Measurements with autonomous gaps	765
A.4.6.6.1	EN-DC-intra-frequency CGI identification of NR FR1 cell with autonomous gaps in	
	synchronous EN-DC	
A.4.6.6.1.1	Test Purpose and Environment	
A.4.6.6.1.2	Test Requirements	
A.4.6.7	L1-SINR measurement for beam reporting	
A.4.6.7.1	L1-SINR measurement with CSI-RS based CMR and no dedicated IMR when DRX is not used	
A.4.6.7.1.1	Test Purpose and Environment	
A.4.6.7.1.2	Test parameters	
A.4.6.7.1.3	Test Requirements	
A.4.6.7.2	L1-SINR measurement with SSB based CMR and dedicated IMR when DRX is used	
A.4.6.7.2.1	Test Purpose and Environment	
A.4.6.7.2.2	Test parameters	
A.4.6.7.2.3	Test Requirements	777
A.4.6.7.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR configured when DRX is	
	used	
A.4.6.7.3.1	Test Purpose and Environment	
A.4.6.7.3.2	Test parameters	
A.4.6.7.3.3	Test Requirements	
	easurement Performance requirements	
A.4.7.1	SS-RSRP	
A.4.7.1.1	EN-DC Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.1.1.1	Test Purpose and Environment	
A.4.7.1.1.2	Test parameters	
A.4.7.1.1.3	Test Requirements	
A.4.7.1.2	EN-DC inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.1.2.1	Test Purpose and Environment	
A.4.7.1.2.2	Test parameters	
A.4.7.1.2.3	Test Requirements	
A.4.7.1.3	Void	
A.4.7.2	SS-RSRQ	
A.4.7.2.1	EN-DC Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.2.1.1	Test Purpose and Environment	
A.4.7.2.1.2	Test Parameters	
A.4.7.2.1.3	Test Requirements	
A.4.7.2.2 A.4.7.2.2.1	EN-DC Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.2.2.1 A.4.7.2.2.2	Test Purpose and Environment	
A.4.7.2.2.2 A.4.7.2.2.3		
A.4.7.2.2.3 A.4.7.3	Test Requirements	
A.4.7.3 A.4.7.3.1	SS-SINREN-DC Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.3.1 A.4.7.3.1.1		
A.4.7.3.1.1 A.4.7.3.1.2	Test Purpose and Environment	
A.4.7.3.1.2 A.4.7.3.1.3	Test Requirements	
A.4.7.3.1.3 A.4.7.3.2	EN-DC Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.4.7.3.2 A.4.7.3.2.1	Test Purpose and Environment	
41.7./.2.4.1	1 cot 1 ut pose una mittationical	500

A.4.7.3.2.2	Test Parameters	
A.4.7.3.2.3	Test Requirements	811
A.4.7.4	L1-RSRP measurement for beam reporting	811
A.4.7.4.1	SSB based L1-RSRP measurement	811
A.4.7.4.1.1	Test Purpose and Environment	
A.4.7.4.1.2	Test parameters	
A.4.7.4.1.3	Test Requirements	
A.4.7.4.2	CSI-RS based L1-RSRP measurement on resource set with repetition off	
A.4.7.4.2.1	Test Purpose and Environment	815
A.4.7.4.2.2	Test parameters	816
A.4.7.4.2.3	Test Requirements	819
A.4.7.5	SFTD accuracy	819
A.4.7.5.1	SFTD accuracy	819
A.4.7.5.1.1	Test Purpose and Environment	819
A.4.7.5.1.2	Test Parameters	819
A.4.7.5.1.3	Test Requirements	824
A.4.7.5.2	Void	824
A.4.7.5.3	Void	824
A.4.7.6	CLI measurements	824
A.4.7.6.1	EN-DC SRS-RSRP measurement accuracy with FR1 serving cell	824
A.4.7.6.1.1	Test Purpose and Environment	824
A.4.7.6.1.2	Test parameters	825
A.4.7.6.1.3	Test Requirements	830
A.4.7.6.2	EN-DC CLI-RSSI measurement accuracy with FR1 serving cell	830
A.4.7.6.2.1	Test Purpose and Environment	830
A.4.7.6.2.2	Test parameters	831
A.4.7.6.2.3	Test Requirements	834
A.4.7.7	L1-SINR measurement for beam reporting	834
A.4.7.7.1	L1-SINR measurement with CSI-RS based CMR and no dedicated IMR configured and CSI-RS	
	resource set with repetition off	834
A.4.7.7.1.1	Test Purpose and Environment	
A.4.7.7.1.2	Test parameters	
A.4.7.7.1.3	Test Requirements	
A.4.7.7.2	L1-SINR measurement with SSB based CMR and dedicated IMR	839
A.4.7.7.2.1	Test Purpose and Environment	839
A.4.7.7.2.2	Test parameters	840
A.4.7.7.2.3	Test Requirements	
A.4.7.7.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR	
A.4.7.7.3.1	Test Purpose and Environment	844
A.4.7.7.3.2	Test parameters	
A.4.7.7.3.3	Test Requirements	848
A.4.8 Voi	d	848
4.5 EN D	N. (1) 11 ' FD2	0.46
	tests with one or more NR cells in FR2	
	d	
	d	
	C_CONNECTED state mobility	
	Void	
	RRC Connection Mobility Control	
A.5.3.2.1	Void	
A.5.3.2.2	Random Access	
A.5.3.2.2.1	4-step RA type contention based random access test in FR2 for PSCell/SCell in EN-DC	
A.5.3.2.2.2	4-step RA type non-contention based random access test in FR2 for PSCell/SCell in EN-DC.	
A.5.3.2.2.3	2-step RA type contention based random access test in FR2 for PSCell/SCell in EN-DC	857
A.5.3.2.2.4	2-step RA type non-contention based random access test in FR2 for PSCell/SCell in EN-DC.	
A.5.3.2.3	Void	
	ing	
	UE transmit timing	
A.5.4.1.1	NR UE Transmit Timing Test for FR2	
A.5.4.1.1.1	Test Purpose and environment	
A.5.4.1.1.2	Test requirements	
A 5 4 2 1	IF timer accuracy	860

A.5.4.3	Timing advance	
	-DC FR2 timing advance adjustment accuracy	
A.5.4.3.1.1 T	est Purpose and Environment	869
A.5.4.3.1.2 T	est Parameters	869
A.5.4.3.1.3	Test Requirements	872
A.5.5 Sig	gnaling characteristics	872
A.5.5.1	Radio link Monitoring	
A.5.5.1.1	Radio Link Monitoring Out-of-sync Test for FR2 PSCell configured with SSB-based RLM RS in	
	non-DRX mode	
A.5.5.1.1.1	Test Purpose and Environment.	
A.5.5.1.1.2	Test Requirements	
A.5.5.1.2	Radio Link Monitoring In-sync Test for FR2 PSCell configured with SSB-based RLM RS in	075
11.3.3.1.2	non-DRX mode	876
A.5.5.1.2.1	Test Purpose and Environment.	
A.5.5.1.2.1 A.5.5.1.2.2	Test Requirements	
A.5.5.1.2.2 A.5.5.1.3	Radio Link Monitoring Out-of-sync Test for FR2 PSCell configured with SSB-based RLM RS in	
A.J.J.1.3		
A 5 5 1 2 1	DRX mode	
A.5.5.1.3.1	Test Purpose and Environment.	
A.5.5.1.3.2	Test Requirements	883
A.5.5.1.4	Radio Link Monitoring In-sync Test for FR2 PSCell configured with SSB-based RLM RS in	003
	DRX mode	
A.5.5.1.4.1	Test Purpose and Environment	
A.5.5.1.4.2	Test Requirements	888
A.5.5.1.5	EN-DC Radio Link Monitoring Out-of-sync Test for FR2 PSCell configured with CSI-RS-based	
	RLM in non-DRX mode	888
A.5.5.1.6	EN-DC Radio Link Monitoring In-sync Test for FR2 PSCell configured with CSI-RS-based	
	RLM in non-DRX mode	894
A.5.5.1.7	EN-DC Radio Link Monitoring Out-of-sync Test for FR2 PSCell configured with CSI-RS-based	
	RLM in DRX mode	899
A.5.5.1.8	EN-DC Radio Link Monitoring In-sync Test for FR2 PSCell configured with CSI-RS-based	
	RLM in DRX mode	905
A.5.5.1.8.2	Test Requirements	911
A.5.5.1.9	EN-DC Radio Link Monitoring UE Scheduling Restrictions on FR2	912
A.5.5.1.9.1	Test Purpose and Environment	
A.5.5.1.9.2	Test Requirements	
A.5.5.2	Interruption	
A.5.5.2.1	E-UTRAN – NR FR2 interruptions at transitions between active and non-active during DRX in	
	synchronous EN-DC	913
A.5.5.2.1.1	Test Purpose and Environment.	
A.5.5.2.1.2	Test Requirements	
A.5.5.2.2	E-UTRAN – NR FR2 interruptions at transitions between active and non-active during DRX in	) 10
A.J.J.L.2	asynchronous EN-DC	016
A.5.5.2.2.1	Test Purpose and Environment.	
A.5.5.2.2.1 A.5.5.2.2.2	Test Requirements	
A.5.5.2.2 A.5.5.2.3		717
A.3.3.2.3	E-UTRAN – NR FR2 interruptions during measurements on deactivated NR SCC in synchronous EN-DC	010
A 5 5 2 2 1	·	
A.5.5.2.3.1	Test Purpose and Environment.	
A.5.5.2.3.2	Test Requirements.	923
A.5.5.2.4	E-UTRAN – NR FR2 interruptions during measurements on deactivated NR SCC in	000
	asynchronous EN-DC	
A.5.5.2.4.1	Test Purpose and Environment	
A.5.5.2.4.2	Test Requirements	926
A.5.5.2.5	E-UTRAN – NR FR2 interruptions during measurements on deactivated E-UTRAN SCC in	
	synchronous EN-DC	
A.5.5.2.5.1	Test Purpose and Environment	
A.5.5.2.5.2	Test Requirements	930
A.5.5.2.6	E-UTRAN – NR FR2 interruptions during measurements on deactivated E-UTRAN SCC in	
	asynchronous EN-DC	
A.5.5.2.6.1	Test Purpose and Environment.	
A.5.5.2.6.2	Test Requirements	933
A.5.5.2.7	E-UTRAN – NR FR2 interruptions at E-UTRA SRS carrier based switching	934
A.5.5.2.7.1	Test Purpose and Environment	934

A.5.5.2.7.2	Test Requirements	937
	JTRAN – NR FR2 interruptions at NR SRS carrier based switching	
	est Purpose and Environment	
A.5.5.2.8.3	Test Requirements	
A.5.5.3	SCell Activation and Deactivation Delay	
A.5.5.3.1	SCell Activation and deactivation of SCell in FR2 intra-band	941
A.5.5.3.1.1	Test Purpose and Environment	941
A.5.5.3.1.2	Test Requirements	943
A.5.5.3.2	SCell Activation and deactivation of known SCell in FR1 for 160ms SCell measurement cycle	
A.5.5.3.2.1	Test Purpose and Environment.	943
A.5.5.3.2.2	Test Requirements	946
A.5.5.3.3	Void	946
A.5.5.3.4	Void	
A.5.5.3.5	SCell Activation and deactivation of SCell in FR2	946
A.5.5.3.5.1	Test Purpose and Environment	946
A.5.5.3.5.2	Test Requirements	
A.5.5.4	Void	
A.5.5.5	Beam Failure Detection and Link recovery procedures	951
A.5.5.5.1	EN-DC Beam Failure Detection and Link Recovery Test for FR2 PSCell configured with SSB-	
	based BFD and LR in non-DRX mode	
A.5.5.5.1.1	Test Purpose and Environment	
A.5.5.5.1.2	Test Requirements	957
A.5.5.5.2	EN-DC Beam Failure Detection and Link Recovery Test for FR2 PSCell configured with SSB-	
	based BFD and LR in DRX mode	
A.5.5.5.2.1	Test Purpose and Environment.	
A.5.5.5.2.2	Test Requirements	963
A.5.5.5.3	EN-DC Beam Failure Detection and Link Recovery Test for FR2 PSCell configured with CSI-	
	RS-based BFD and LR in non-DRX mode	
A.5.5.5.3.1	Test Purpose and Environment	
A.5.5.5.3.2	Test Requirements	969
A.5.5.5.4	EN-DC Beam Failure Detection and Link Recovery Test for FR2 PSCell configured with CSI-	
	RS-based BFD and LR in DRX mode	
A.5.5.5.4.1	Test Purpose and Environment	
A.5.5.5.4.2	Test Requirements	975
A.5.5.5.5	EN-DC scheduling availability restriction during Beam Failure Detection and Link Recovery for	
	FR2 PSCell configured with SSB-based BFD and LR in non-DRX mode	
A.5.5.5.5.1	Test Purpose and Environment	
A.5.5.5.5.2	Test Requirements	981
A.5.5.5.6	EN-DC Beam Failure Detection and Link Recovery Test for FR2 SCell configured with CSI-RS-	
	based BFD and LR in non-DRX mode	
A.5.5.5.6.1	Test Purpose and Environment	
A.5.5.5.6.2	Test Requirements	986
A.5.5.5.7	EN-DC Beam Failure Detection and Link Recovery Test for FR2 SCell configured with CSI-RS-	007
	based BFD and LR in DRX mode	
A.5.5.5.7.1	Test Purpose and Environment	
A.5.5.5.7.2	Test Requirements	
A.5.5.6	Active BWP switch	
A.5.5.6.1	DCI-based and Timer-based Active BWP Switch	
A.5.5.6.1.1	E-UTRAN – NR PSCell FR2 DL active BWP switch with non-DRX in synchronous EN-DC.	
A.5.5.6.1.1.1	Test Purpose and Environment	
A.5.5.6.1.1.2 A.5.5.6.1.2	Test Requirements	990
A.3.3.6.1.2		007
15560	synchronous EN-DCRRC-based Active BWP Switch	
A.5.5.6.2		
A.5.5.6.3.1	nultaneous DCI-based and Timer-based Active BWP Switch on multiple CCs	1003
A.J.J.0.3.1	synchronous EN-DC	1005
A.5.5.6.3.1.1	Test Purpose and Environment	
A.5.5.6.3.1.1 A.5.5.6.3.1.2		
A.5.5.7	PSCell addition and release delay	
A.5.5.7.1	Addition and Release Delay of NR PSCell	
A.5.5.7.1 A.5.5.7.1.1	Test purpose and environment	
11.0.0.1.1.1	1 co purpose and environment	1010

A.5.5.7.1.2	Test Requirements	.1013
A.5.5.8	Active TCI state switch delay	.1014
A.5.5.8.1	MAC-CE based active TCI state switch	.1014
A.5.5.8.1.1	E-UTRAN – NR PSCell FR2 active TCI state switch for a known TCI state	
A.5.5.8.1.1.1	Test Purpose and Environment	
A.5.5.8.1.1.2	Test Requirements	
A.5.5.8.2	RRC based active TCI state switch	
A.5.5.8.2.1	E-UTRAN – NR PSCell FR2 active TCI state switch for a known TCI state	
A.5.5.8.2.1.1	Test Purpose and Environment	
A.5.5.8.2.1.2	Test Requirements	
A.5.5.9	Uplink spatial relation switch delay	
A.5.5.9.1	MAC-CE based uplink spatial relation switch	
A.5.5.9.1.1	E-UTRAN – NR PSCell FR2 uplink spatial relation switch for a known spatial relation	.1019
A.5.5.9.1.1.1	Test Purpose and Environment	.1019
A.5.5.9.1.1.2	Test Requirements	1022
A.5.5.9.2	RRC based spatial relation switch	
A.5.5.9.2.1	E-UTRAN – NR PSCell FR2 spatial relation switch associated with a known DL-RS	
A.5.5.9.2.1.1	Test Purpose and Environment	
A.5.5.9.2.1.2	Test Requirements	
A.5.5.10	UE specific CBW change	
A.5.5.10.1	UE specific CBW change on FR2 NR PSCell	
A.5.5.10.1.1	Test Purpose and Environment	
A.5.5.10.1.2	Test Requirements	.1028
A.5.6 Me	easurement procedure	.1029
A.5.6.1	Intra-frequency Measurements	
A.5.6.1.1	EN-DC event triggered reporting test without gap under non-DRX	
A.5.6.1.1.1	Test purpose and Environment	
A.5.6.1.1.2	Test Requirements	
A.5.6.1.2	EN-DC event triggered reporting test without gap under DRX	
A.5.6.1.2.1	Test purpose and Environment	
A.5.6.1.2.2	Test Requirements	1034
A.5.6.1.3	EN-DC event triggered reporting test with per-UE gaps under non-DRX	
A.5.6.1.3.1	Test purpose and Environment	
A.5.6.1.3.2	Test Requirements	
A.5.6.1.4	EN-DC event triggered reporting test with per-UE gaps under DRX	.1038
A.5.6.1.4.1	Test purpose and Environment	.1038
A.5.6.1.4.2	Test Requirements	
A.5.6.2	Inter-frequency Measurements	
A.5.6.2.1	EN-DC event triggered reporting tests for FR2 cell without SSB time index detection when DRX	
	is not used	
A.5.6.2.1.1	Test Purpose and Environment.	
A.5.6.2.1.1 A.5.6.2.1.2	Test Requirements	
A.5.6.2.2	EN-DC event triggered reporting tests for FR2 cell without SSB time index detection when DRX	
	is used	
A.5.6.2.2.1	Test Purpose and Environment.	
A.5.6.2.2.2	Test Requirements	.1050
A.5.6.2.3	EN-DC event triggered reporting tests for FR2 cell with SSB time index detection when DRX is	
	not used	1050
A.5.6.2.3.1	Test Purpose and Environment	.1050
A.5.6.2.3.2	Test Requirements	
A.5.6.2.4	EN-DC event triggered reporting tests for FR2 cell with SSB time index detection when DRX is	100.
11.3.0.2.1	used	1054
A 5 6 2 A 1		
A.5.6.2.4.1	Test Pagyiroments	
A.5.6.2.4.2	Test Requirements.	
A.5.6.2.5	EN-DC event triggered reporting tests for FR2 cell without SSB time index detection when DRX	
	is not used	
A.5.6.2.5.1	Test Purpose and Environment	
A.5.6.2.5.2	Test Requirements	1062
A.5.6.2.6	EN-DC event triggered reporting tests for FR2 cell without SSB time index detection when DRX	
	is used	
A.5.6.2.6.1	Test Purpose and Environment	
A.5.6.2.6.2	Test Requirements	
11.5.0.2.0.2	requirement	1000

A.5.6.2.7	EN-DC event triggered reporting tests for FR2 cell with SSB time index detection when DRX is	
	not used	
A.5.6.2.7.1	Test Purpose and Environment.	
A.5.6.2.7.2	Test Requirements	1071
A.5.6.2.8	EN-DC event triggered reporting tests for FR2 cell with SSB time index detection when DRX is	
	used	
A.5.6.2.8.1	Test Purpose and Environment	1071
A.5.6.2.8.2	Test Requirements	1075
A.5.6.3	L1-RSRP measurement for beam reporting	
A.5.6.3.1	SSB based L1-RSRP measurement when DRX is not used	
A.5.6.3.1.1	Test Purpose and Environment.	1076
A.5.6.3.1.2	Test parameters	
A.5.6.3.1.3	Test Requirements	
A.5.6.3.2	SSB based L1-RSRP measurement when DRX is used	1078
A.5.6.3.2.1	Test Purpose and Environment	
A.5.6.3.2.2	Test parameters	
A.5.6.3.2.3	Test Requirements	
A.5.6.3.3	CSI-RS based L1-RSRP measurement when DRX is not used	
A.5.6.3.3.1	Test Purpose and Environment.	
A.5.6.3.3.2	Test parameters	
A.5.6.3.3.3	Test Requirements	1002
A.5.6.3.4		
A.5.6.3.4.1	CSI-RS based L1-RSRP measurement when DRX is used	
	Test Purpose and Environment.	
A.5.6.3.4.2	Test parameters	
A.5.6.3.4.3	Test Requirements	
A.5.6.4	CLI measurements	
A.5.6.4.1	SRS-RSRP measurement with DRX	
A.5.6.4.1.1	Test Purpose and Environment.	
A.5.6.4.1.2	Test Parameters	
A.5.6.4.1.3	Test Requirements	
A.5.6.4.2	CLI-RSSI measurement with DRX	
A.5.6.4.2.1	Test Purpose and Environment	
A.5.6.4.2.2	Test Parameters	
A.5.6.4.2.3	Test Requirements	
A.5.6.4	Measurements with autonomous gaps	
A.5.6.4.1	EN-DC inter-frequency CGI identification of NR neighbor cell in FR2	
A.5.6.4.1.1	Test Purpose and Environment.	
A.5.6.4.1.2	Test Requirements	
A.5.6.5	L1-SINR measurement for beam reporting	1097
A.5.6.5.1	L1-SINR measurement with CSI-RS based CMR and no dedicated IMR configured when DRX	
	is used	1097
A.5.6.5.1.1	Test Purpose and Environment	1097
A.5.6.5.1.2	Test parameters	1097
A.5.6.5.1.3	Test Requirements	
A.5.6.5.2	L1-SINR measurement with SSB based CMR and dedicated IMR when DRX is not used	1099
A.5.6.5.2.1	Test Purpose and Environment.	1099
A.5.6.5.2.2	Test parameters	
A.5.6.5.2.3	Test Requirements	
A.5.6.5.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR configured when DRX is	
1110101010	not used	1103
A.5.6.5.3.1	Test Purpose and Environment.	
A.5.6.5.3.2	Test parameters	
A.5.6.5.3.3	Test Requirements	
	Measurement Performance requirements	
A.5.7.1	SS-RSRP	
A.5.7.1 A.5.7.1.1		
	EN-DC intra-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	
A.5.7.1.1.1	Test Purpose and Environment.	
A.5.7.1.1.2	Test parameters	
A.5.7.1.1.3	Test Requirements	
A.5.7.1.2	EN-DC inter-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	
A.5.7.1.2.1	Test Purpose and Environment	
A.5.7.1.2.2	Test parameters	1109

A.5.7.1.2.3	Test Requirements	.1113
A.5.7.1.3	EN-DC inter-frequency measurement accuracy with FR1 serving cell and FR2 target cell	.1114
A.5.7.1.3.1	Test Purpose and Environment	
A.5.7.1.3.2	Test parameters	
A.5.7.1.3.3	Test Requirements	
A.5.7.2	SS-RSRQ	
A.5.7.2.1	EN-DC Intra-frequency measurement accuracy with FR2 serving cell and FR2 TDD target	,
A.J. / .2.1	cell	1117
A 5 7 2 1 1	Test Purpose and Environment	
A.5.7.2.1.1		
A.5.7.2.1.2	Test Parameters	
A.5.7.2.1.3	Test Requirements	
A.5.7.2.2	EN-DC Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	
A.5.7.2.2.1	Test Purpose and Environment	
A.5.7.2.2.2	Test Parameters	
A.5.7.2.2.3	Test Requirements	.1125
A.5.7.3	SS-SINR	.1125
A.5.7.3.1	EN-DC Intra-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	.1125
A.5.7.3.1.1	Test Purpose and Environment	
A.5.7.3.1.2	Test Parameters	
A.5.7.3.1.3	Test Requirements	
A.5.7.3.2	EN-DC Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	
A.5.7.3.2.1	Test Purpose and Environment	
A.5.7.3.2.1 A.5.7.3.2.2	Test Parameters	
A.5.7.3.2.3	Test Requirements	
A.5.7.4	L1-RSRP measurement for beam reporting	
A.5.7.4.1	SSB based L1-RSRP measurement	
A.5.7.4.1.1	Test Purpose and Environment	
A.5.7.4.1.2	Test parameters	
A.5.7.4.1.3	Test Requirements	
A.5.7.4.2	CSI-RS based L1-RSRP measurement on resource set with repetition off	.1134
A.5.7.4.2.1	Test Purpose and Environment	.1134
A.5.7.4.2.2	Test parameters	.1134
A.5.7.4.2.3	Test Requirements	
A.5.7.5	CLI measurements	
A.5.7.5.1	EN-DC SRS-RSRP measurement accuracy with FR2 serving cell	
A.5.7.5.1.1	Test Purpose and Environment	
A.5.7.5.1.2	Test parameters	
A.5.7.5.1.2 A.5.7.5.1.3	Test Requirements	
A.5.7.5.2	EN-DC CLI-RSSI measurement accuracy with FR2 serving cell	
A.5.7.5.2.1	Test Purpose and Environment	
A.5.7.5.2.2	Test parameters	
A.5.7.5.2.3	Test Requirements	
A.5.7.6	L1-SINR measurement for beam reporting	.1144
A.5.7.6.1	L1-SINR measurement with CSI-RS based CMR and no dedicated IMR configured and CSI-RS	
	resource set with repetition off	.1144
A.5.7.6.1.1	Test Purpose and Environment	.1144
A.5.7.6.1.2	Test parameters	
A.5.7.6.1.3	Test Requirements	
A.5.7.6.2	L1-SINR measurement with SSB based CMR and dedicated IMR	
A.5.7.6.2.1	Test Purpose and Environment	
A.5.7.6.2.2	Test parameters	
A.5.7.6.2.3	Test Requirements	
A.5.7.6.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR	
A.5.7.6.3.1	Test Purpose and Environment	
A.5.7.6.3.2	Test parameters	
A.5.7.6.3.3	Test Requirements	
A.5.8 Vo	oid	.1152
A.6 NR s	tandalone tests with all NR cells in FR1	1011
	A: RRC_IDLE state mobility	
A.6.1.1	Cell re-selection to NR	
A.6.1.1.1	Cell reselection to FR1 intra-frequency NR case	.1011

A.6.1.1.1.1	Test Purpose and Environment	
A.6.1.1.1.2	Test Parameters	
A.6.1.1.1.3	1	
A.6.1.1.2	Cell reselection to FR1 inter-frequency NR case	
A.6.1.1.2.1	Test Purpose and Environment	
A.6.1.1.2.2		
A.6.1.1.2.3	Test Requirements	1019
A.6.1.1.3	Cell reselection to FR1 intra-frequency NR case for UE fulfilling low mobility relaxed	
	measurement criterion	
A.6.1.1.3.1	Test Purpose and Environment	1019
A.6.1.1.3.2	Test Parameters	1019
A.6.1.1.3.3	Test Requirements	1024
A.6.1.1.4	Cell reselection to FR1 intra-frequency NR case for UE fulfilling not-at-cell edge relaxed	
	measurement criterion	1024
A.6.1.1.4.1	Test Purpose and Environment	1024
A.6.1.1.4.2	Test Parameters	1024
A.6.1.1.4.3	Test Requirements	1028
A.6.1.1.5	Cell reselection to FR1 inter-frequency NR case for UE fulfilling low mobility relaxed	
	measurement criterion	1028
A.6.1.1.5.1	Test Purpose and Environment	
A.6.1.1.5.2	Test Parameters	
A.6.1.1.5.3	Test Requirements	
A.6.1.1.6	Cell reselection to FR1 inter-frequency NR case for UE fulfilling not-at-cell edge relaxed	
	measurement criterion	1032
A.6.1.1.6.1	Test Purpose and Environment.	
A.6.1.1.6.2	Test Parameters	
A.6.1.1.6.3	Test Requirements	
A.6.1.1.7	Cell reselection to FR1 intra-frequency NR case for UE configured with highSpeedMeasFlag	
11.0.1.1.7	r16	
A.6.1.1.7.1	Test Purpose and Environment.	
A.6.1.1.7.2	Test Parameters	
A.6.1.1.7.3	Test Requirements	
A.6.1.2	Inter-RAT E-UTRAN cell re-selection	
A.6.1.2.1	Cell reselection to higher priority E-UTRAN	
A.6.1.2.1 A.6.1.2.1.1	Test Purpose and Environment	
A.6.1.2.1.2	Test Parameters	
A.6.1.2.1.3	Test Parallecers	
A.6.1.2.1.3 A.6.1.2.2	Cell reselection to lower priority E-UTRAN	1046
A.6.1.2.2 A.6.1.2.2.1	Test Purpose and Environment	
A.6.1.2.2.1 A.6.1.2.2.2		
	Test Parameters	
A.6.1.2.2.3	Test Requirements	
A.6.1.2.3	Cell reselection to lower priority E-UTRAN for UE fulfilling low mobility relaxed measuren	
. (1001	criterion	
A.6.1.2.3.1	Test Purpose and Environment	
A.6.1.2.3.2	Test Parameters	
A.6.1.2.3.3	Test Requirements	1053
A.6.1.2.4	Cell reselection to lower priority E-UTRAN for UE fulfilling not-at-cell edge relaxed	40=4
	measurement criterion	
A.6.1.2.4.1	Test Purpose and Environment	
A.6.1.2.4.2	Test Parameters	
A.6.1.2.4.3	Test Requirements	
	SA: RRC_INACTIVE state mobility	
	RRC_CONNECTED state mobility	
A.6.3.1	Handover	
A.6.3.1.1	Intra-frequency handover from FR1 to FR1; known target cell	
A.6.3.1.1.1	Test Purpose and Environment.	
A.6.3.1.1.2	Test Parameters	
A.6.3.1.1.3	Test Requirements	1065
A.6.3.1.2	Intra-frequency handover from FR1 to FR1; unknown target cell	1065
A.6.3.1.2.1	Test Purpose and Environment	
A.6.3.1.2.2	Test Parameters	
A.6.3.1.2.3		

A.6.3.1.3	Inter-frequency handover from FR1 to FR1; unknown target cell	1069
A.6.3.1.3.1	Test Purpose and Environment	1069
A.6.3.1.3.2	Test Parameters	1069
A.6.3.1.3.3 T	est Requirements	
A.6.3.1.4	SA NR - E-UTRAN handover	
A.6.3.1.4.1	Test Purpose and Environment	
A.6.3.1.4.2	Test Requirements	
A.6.3.1.5	SA NR - E-UTRAN handover with unknown target cell	
A.6.3.1.5.1	Test Purpose and Environment	1079
A.6.3.1.5.2	Test Requirements	
A.6.3.1.6	SA NR - UTRAN FDD handover	
A.6.3.1.6.1	Test Purpose and Environment	
A.6.3.1.6.2	Test Requirements	1089
A.6.3.1.7	Intra-frequency handover in FR1; synchronous scenario	
A.6.3.1.7.1	Test Purpose and Environment	1089
A.6.3.1.7.2	Test Parameters	1089
A.6.3.1.7.3 T	est Requirements	
A.6.3.1.8	Intra-frequency handover in FR1; asynchronous scenario	
A.6.3.1.8.1	Test Purpose and Environment	1094
A.6.3.1.8.2	Test Parameters	1094
A.6.3.1.8.3 T	est Requirements	1098
A.6.3.1.9	Intra-band inter-frequency synchronous DAPS handover test in SA for FR1	1099
A.6.3.1.9.1	Test Purpose and Environment	1099
A.6.3.1.9.2	Test Parameters	1099
A.6.3.1.9.3 T	est Requirements	1103
A.6.3.1.10	Intra-band inter-frequency asynchronous DAPS handover test in SA for FR1	1103
A.6.3.1.10.1	Test Purpose and Environment	1103
A.6.3.1.10.2	Test Parameters	1103
A.6.3.1.10.3	Test Requirements	
A.6.3.1.11	Inter-band inter-frequency synchronous DAPS handover from FR1 to FR1	1107
A.6.3.1.11.1	Test Purpose and Environment	1107
A.6.3.1.11.2	Test Parameters	1107
A.6.3.1.11.3	Test Requirements	1114
A.6.3.1.12	Inter-band inter-frequency asynchronous DAPS handover from FR1 to FR1	1114
A.6.3.1.12.1	Test Purpose and Environment	1114
A.6.3.1.12.2	Test Parameters	1114
A.6.3.1.12.3	Test Requirements	1121
A.6.3.2	RRC Connection Mobility Control	1121
A.6.3.2.1	SA: RRC Re-establishment	1121
A.6.3.2.1.1	Intra-frequency RRC Re-establishment in FR1	1121
A.6.3.2.1.2	Inter-frequency RRC Re-establishment in FR1	1125
A.6.3.2.1.3	Intra-frequency RRC Re-establishment in FR1 without serving cell timing	1129
A.6.3.2.2	Random Access	1132
A.6.3.2.2.1	4-step RA type contention based random access test in FR1 for NR standalone	1132
A.6.3.2.2.2	4-step RA type non-contention based random access test in FR1 for NR standalone	1136
A.6.3.2.2.3	2-step RA type contention based random access test in FR1 for NR standalone	1141
A.6.3.2.2.4	2-step RA type non-contention based test in FR1 for NR standalone	1146
A.6.3.2.3	SA: RRC Connection Release with Redirection	1150
A.6.3.2.3.1	Redirection from NR in FR1 to NR in FR1	1150
A.6.3.2.3.2	Redirection from NR in FR1 to E-UTRAN	1154
A.6.3.3 Cond	itional handover	1161
A.6.3.3.1	Intra-frequency conditional handover from FR1 to FR1	1161
A.6.3.3.1.1	Test Purpose and Environment	
A.6.3.3.1.2	Test Parameters	1161
A.6.3.3.1.3 T	est Requirements	1165
A.6.3.3.2	Inter-frequency conditional handover from FR1 to FR1	
A.6.3.3.2.1	Test Purpose and Environment	
A.6.3.3.2.2	Test Parameters	
	est Requirements	
	ning	
A.6.4.1	UE transmit timing	
A.6.4.1.1	NR UE Transmit Timing Test for FR1	

A.6.4.1.1.1	Test Purpose and environment	
A.6.4.1.1.2	Test requirements	
A.6.4.2	UE timer accuracy	1173
A.6.4.3	Timing advance	
A.6.4.3.1	SA FR1 timing advance adjustment accuracy	1173
A.6.4.3.1.1	Test Purpose and Environment	1173
A.6.4.3.1.2	Test Parameters	1173
A.6.4.3.1.3	Test Requirements	1177
A.6.5 S:	ignalling characteristics	1177
A.6.5.1	Radio link Monitoring	1177
A.6.5.1.1	Radio Link Monitoring Out-of-sync Test for FR1 PCell configured with SSB-based RLM RS i	n
	non-DRX mode	1178
A.6.5.1.1.1	Test Purpose and Environment	1178
A.6.5.1.1.2	Test Requirements	1183
A.6.5.1.2	Radio Link Monitoring In-sync Test for FR1 PCell configured with SSB-based RLM RS in no	n-
	DRX mode	
A.6.5.1.2.1	Test Purpose and Environment	1183
A.6.5.1.2.2	Test Requirements	1189
A.6.5.1.3	Radio Link Monitoring Out-of-sync Test for FR1 PCell configured with SSB-based RLM RS i	
	DRX mode	
A.6.5.1.3.1	Test Purpose and Environment	
A.6.5.1.3.2	Test Requirements	1195
A.6.5.1.4	Radio Link Monitoring In-sync Test for FR1 PCell configured with SSB-based RLM RS in DI	
	mode	
A.6.5.1.4.1	Test Purpose and Environment	
A.6.5.1.4.2	Test Requirements	
A.6.5.1.5	Radio Link Monitoring Out-of-sync Test for FR1 PCell configured with CSI-RS-based RLM is	
	non-DRX mode	
A.6.5.1.5.1	Test Purpose and Environment	
A.6.5.1.5.2	Test Requirements	
A.6.5.1.6	Radio Link Monitoring In-sync Test for FR1 PCell configured with CSI-RS-based RLM in nor	
	DRX mode	
A.6.5.1.6.1	Test Purpose and Environment	
A.6.5.1.6.2	Test Requirements	
A.6.5.1.7	Radio Link Monitoring Out-of-sync Test for FR1 PCell configured with CSI-RS-based RLM is	
	DRX mode	
A.6.5.1.7.1	Test Purpose and Environment	
A.6.5.1.7.2	Test Requirements	
A.6.5.1.8	Radio Link Monitoring In-sync Test for FR1 PCell configured with CSI-RS-based RLM in DR	
	mode	
A.6.5.1.8.1	Test Purpose and Environment	
A.6.5.1.8.2	Test Requirements	
A.6.5.2	Interruption	
A.6.5.2.1	Interruptions during measurements on deactivated NR SCC in FR1	
A.6.5.2.1.2	Test Requirements	
A.6.5.2.2	SA interruptions at NR SRS carrier based switching	
A.6.5.2.2.1	Test Purpose and Environment	
A.6.5.2.2.2	Test Parameters	
A.6.5.2.2.3	Test Requirements	
A.6.5.3	SCell Activation and Deactivation Delay	1230
A.6.5.3.1	SCell Activation and deactivation of known SCell in FR1 in non-DRX for 160ms SCell	
	measurement cycle	
A.6.5.3.1.1	Test Purpose and Environment	
A.6.5.3.1.2	Test Requirements	1235
A.6.5.3.2	SCell Activation and deactivation of known SCell in FR1 in non-DRX for 320ms SCell	
	measurement cycle	
A.6.5.3.2.1	Test Purpose and Environment	1235
A.6.5.3.2.2	Test Requirements	1236
A.6.5.3.3	SCell Activation and deactivation of unknown SCell in FR1 in non-DRX	1236
A.6.5.3.3.1	Test Purpose and Environment	1236
A.6.5.3.3.2	Test Requirements	1237
A.6.5.4	UE UL carrier RRC reconfiguration Delay	

A.6.5.4.1	UE UL carrier RRC reconfiguration Delay	.1237
A.6.5.4.1.1	Test Purpose and Environment	.1237
A.6.5.4.1.2	Test Requirements	.1246
A.6.5.4.2	Void	
A.6.5.5	Beam Failure Detection and Link recovery procedures	
A.6.5.5.1	Beam Failure Detection and Link Recovery Test for FR1 PCell configured with SSB-based BFD	
	and LR in non-DRX mode	
A.6.5.5.1.1	Test Purpose and Environment	
A.6.5.5.2	Beam Failure Detection and Link Recovery Test for FR1 PCell configured with SSB-based BFD	1270
A.0.3.3.2	and LR in DRX mode	1252
A.6.5.5.2.1	Test Purpose and Environment	
A.6.5.5.2.2	Test Requirements	.1239
A.6.5.5.3	Beam Failure Detection and Link Recovery Test for FR1 PCell configured with CSI-RS-based	1050
	BFD and LR in non-DRX mode	
A.6.5.5.3.1	Test Purpose and Environment	
A.6.5.5.3.2	Test Requirements	.1265
A.6.5.5.4	Beam Failure Detection and Link Recovery Test for FR1 PCell configured with CSI-RS-based	
	BFD and LR in DRX mode	
A.6.5.5.4.1	Test Purpose and Environment	.1265
A.6.5.5.4.2	Test Requirements	.1271
A.6.5.5.5	Beam Failure Detection and Link Recovery Test for FR1 SCell configured with CSI-RS-based	
	BFD and SSB-based LR in non-DRX mode	.1271
A.6.5.5.5.1	Test Purpose and Environment	
A.6.5.5.5.2	Test Requirements	
A.6.5.5.6	Beam Failure Detection and Link Recovery Test for FR1 SCell configured with CSI-RS-based	12,0
11.0.3.3.0	BFD and SSB-based LR in DRX mode	1276
A.6.5.5.6.1	Test Purpose and Environment	
A.6.5.5.6.2	Test Requirements	
	1	
A.6.5.6	Active BWP switch	
A.6.5.6.1	DCI-based and Timer-based Active BWP Switch	
A.6.5.6.1.1	NR FR1- NR FR1 DL active BWP switch of PCell with non-DRX in SA	
A.6.5.6.1.2	NR FR1 DL active BWP switch with non-DRX in SA	
A.6.5.6.2	RRC-based Active BWP Switch	
A.6.5.6.2.1	NR FR1 DL active BWP switch of Cell with non-DRX in SA	
A.6.5.6.3	Simultaneous DCI-based and Timer-based Active BWP Switch on multiple CCs	
A.6.5.6.3.1	NR FR1- NR FR1 DL active BWP switch on multiple CCs with non-DRX in SA	
A.6.5.6.3.1.1		
A.6.5.6.3.1.2		
A.6.5.7	DL interruptions at switching between two uplink carriers	.1300
A.6.5.7.1	DL interruptions at switching between two uplink carriers in FDD-TDD CA	.1300
A.6.5.7.1.1	Test Purpose and Environment	
A.6.5.7.1.2	Test Requirements	
A.6.5.7.2	DL interruptions at switching between two uplink carriers in TDD-TDD CA	
A.6.5.7.2.1	Test Purpose and Environment	
A.6.5.7.2.2	Test Requirements	
A.6.5.8	UE specific CBW change	
A.6.5.8.1	UE specific CBW change on PCell in FR1 in non-DRX	
A.6.5.8.1.1	Test Purpose and Environment	
A.6.5.8.1.2	Test Requirements	
	easurement procedure	
A.6.6.1		
	Intra-frequency Measurements	
A.6.6.1.1	SA event triggered reporting tests without gap under non-DRX	
A.6.6.1.1.1	Test purpose and Environment	
A.6.6.1.1.2	Test parameters	
A.6.6.1.1.3	Test Requirements	
A.6.6.1.2	SA event triggered reporting tests without gap under DRX	
A.6.6.1.2.1	Test purpose and Environment	
A.6.6.1.2.2	Test parameters	
A.6.6.1.2.3	Test Requirements	
A.6.6.1.3	SA event triggered reporting tests with per-UE gaps under non-DRX	
A.6.6.1.3.1	Test purpose and Environment	
A.6.6.1.3.2	Test parameters	.1320

A.6.6.1.3.3	Test Requirements	. 1324
A.6.6.1.4	SA event triggered reporting tests with per-UE gaps under DRX	.1324
A.6.6.1.4.1	Test purpose and Environment	
A.6.6.1.4.2	Test parameters	
A.6.6.1.4.3	Test Requirements	
A.6.6.1.5	SA event triggered reporting tests without gap under non-DRX with SSB index reading	
A.6.6.1.5.1	Test purpose and Environment	.1328
A.6.6.1.5.2	Test parameters	.1328
A.6.6.1.5.3	Test Requirements	
A.6.6.1.6	SA event triggered reporting tests with per-UE gaps under non-DRX with SSB index reading	
A.6.6.1.6.1	Test purpose and Environment	
A.6.6.1.6.2	Test parameters	
A.6.6.1.6.3	•	
	Test Requirements	
A.6.6.1.7	SA event triggered reporting tests under DRX for UE configured with highSpeedMeasFlag-r16	
A.6.6.1.7.1	Test purpose and Environment	
A.6.6.1.7.2	Test parameters	
A.6.6.1.7.3	Test Requirements	
A.6.6.2	Inter-frequency Measurements	.1337
A.6.6.2.1	SA event triggered reporting tests for FR1 without SSB time index detection when DRX is not	
	used	.1337
A.6.6.2.1.1	Test Purpose and Environment.	
A.6.6.2.1.2	Test Requirements	
A.6.6.2.2	SA event triggered reporting tests for FR1 without SSB time index detection when DRX is used	12/11
	SA event triggered reporting tests for FK1 without 35b time index detection when DKA is used	1241
A.6.6.2.2.1	Test Purpose and Environment	
A.6.6.2.2.2	Test Requirements	
A.6.6.2.3	Void	
A.6.6.2.4	Void	
A.6.6.2.5	SA event triggered reporting tests for FR1 with SSB time index detection when DRX is not used.	
A.6.6.2.5.1	Test Purpose and Environment	.1346
A.6.6.2.5.2	Test Requirements	.1350
A.6.6.2.6	SA event triggered reporting tests for FR1 with SSB time index detection when DRX is used	.1350
A.6.6.2.6.1	Test Purpose and Environment	.1350
A.6.6.2.6.2	Test Requirements	
A.6.6.2.7	Void	
A.6.6.2.8	Void	
A.6.6.2.9	SA event triggered reporting tests with additional mandatory gap pattern	
A.6.6.2.9.1	Test Purpose and Environment.	
A.6.6.2.9.2	Test Requirements	
A.6.6.2.10	SA event triggered reporting tests for FR1 when DRX is used	
A.6.6.2.10.1	Test Purpose and Environment.	
A.6.6.2.10.2	Test Requirements	
A.6.6.2.11	SA event triggered reporting tests for FR1 without gap when DRX is not used	
A.6.6.2.11.1	Test Purpose and Environment	.1363
A.6.6.2.11.2	Test Requirements	.1366
A.6.6.3	Inter-RAT Measurements	.1366
A.6.6.3.1	SA NR - E-UTRAN event-triggered reporting in non-DRX in FR1	
A.6.6.3.1.1	Test Purpose and Environment	
A.6.6.3.1.2	Test Requirements	
A.6.6.3.2	SA NR - E-UTRAN event-triggered reporting in DRX in FR1	
A.6.6.3.2.1		
	Test Purpose and Environment.	
A.6.6.3.2.2	Test Requirements	13/9
A.6.6.3.3	SA NR - E-UTRAN event-triggered reporting in DRX in FR1 for UE configured with	1270
	highSpeedMeasFlag-r16	
A.6.6.3.3.1	Test Purpose and Environment	
A.6.6.3.3.2	Test Requirements	
A.6.6.4	L1-RSRP measurement for beam reporting	
A.6.6.4.1	SSB based L1-RSRP measurement when DRX is not used	
A.6.6.4.1.1	Test Purpose and Environment	.1386
A.6.6.4.1.2	Test parameters	
A.6.6.4.1.3	Test Requirements	
A.6.6.4.2	SSB based L1-RSRP measurement when DRX is used	
A.6.6.4.2.1	Test Purpose and Environment.	
	1	

A.6.6.4.2.2	Test parameters	.1390
A.6.6.4.2.3	Test Requirements	1393
A.6.6.4.3	CSI-RS based L1-RSRP measurement when DRX is not used	.1393
A.6.6.4.3.1	Test Purpose and Environment	
A.6.6.4.3.2	Test parameters	
A.6.6.4.3.3	Test Requirements	
A.6.6.4.4	CSI-RS based L1-RSRP measurement when DRX is used	1397
A.6.6.4.4.1		
	Test Purpose and Environment.	
A.6.6.4.4.2	Test parameters	
A.6.6.4.4.3	Test Requirements	.1401
A.6.6.4.5	SSB based L1-RSRP measurement when DRX is used for UE configured with	
	highSpeedMeasFlag-r16	
A.6.6.4.5.1	Test Purpose and Environment	.1401
A.6.6.4.5.2	Test parameters	.1402
A.6.6.4.5.3	Test Requirements	1405
A.6.6.5	1405	
A.6.6.5.1	SA NR - UTRAN FDD event-triggered reporting in non-DRX in FR1	.1405
A.6.6.5.1.1	Test Purpose and Environment	
A.6.6.5.1.2	Test Requirements	
A.6.6.6	CLI measurements	
A.6.6.6.1		
	SRS-RSRP measurement with DRX	
A.6.6.6.1.1	Test Purpose and Environment	
A.6.6.6.1.2	Test Parameters	
A.6.6.6.1.3	Test Requirements	
A.6.6.6.2	CLI-RSSI measurement with DRX	
A.6.6.6.2.1	Test Purpose and Environment	.1413
A.6.6.6.2.2	Test Parameters	
A.6.6.6.2.3	Test Requirements	
A.6.6.7	NR measurements with autonomous gaps	
A.6.6.7.1	SA intra-frequency CGI identification of NR neighbor cell in FR1	
A.6.6.7.1.1	Test Purpose and Environment	
A.6.6.7.1.2	Test Parameters	
A.6.6.7.1.3		
	Test Requirements	
A.6.6.7.2	Identification of a new CGI of inter-RAT E-UTRA cell using autonomous gaps in NR SA	
A.6.6.7.2.1	Test Purpose and Environment	
A.6.6.7.2.2	Test Requirements	
A.6.6.8	L1-SINR measurement for beam reporting	.1423
A.6.6.8.1	L1-SINR measurement with CSI-RS based CMR and no dedicated IMR configured when DRX	
	is used	
A.6.6.8.1.1	Test Purpose and Environment	.1423
A.6.6.8.2	L1-SINR measurement with SSB based CMR and dedicated IMR when DRX is not used	
A.6.6.8.2.1	Test Purpose and Environment	
A.6.6.8.2.2	Test parameters	
A.6.6.8.2.3	Test Requirements	
A.6.6.8.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR configured when DRX is	.1731
A.0.0.6.3		1 42 1
A ( ( 0 2 1	not used	
A.6.6.8.3.1	Test Purpose and Environment	
A.6.6.8.3.2	Test parameters	
A.6.6.8.3.3	Test Requirements	
A.6.7 M	easurement Performance requirements	
A.6.7.1	SS-RSRP	.1436
A.6.7.1.1	SA: intra-frequency case measurement accuracy with FR1 serving cell and FR1 target cell	1436
A.6.7.1.1.1	Test Purpose and Environment	.1436
A.6.7.1.1.2	Test parameters	
A.6.7.1.1.3	Test Requirements	
A.6.7.1.2	SA inter-frequency case measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.1.2.1	Test Purpose and Environment	
A.6.7.1.2.1 A.6.7.1.2.2	Test parameters	
A.6.7.1.2.2 A.6.7.1.2.3	Test Requirements	
	<u> </u>	
A.6.7.1.3	Void	
A.6.7.2	SS-RSRQ	
A.6.7.2.1	SA: Intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	.1445

A.6.7.2.1.1	Test Purpose and Environment	1445
A.6.7.2.1.2	Test Parameters	1446
A.6.7.2.1.3	Test Requirements	1451
A.6.7.2.2	SA Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	1451
A.6.7.2.2.1	Test Purpose and Environment	
A.6.7.2.2.2	Test Parameters	
A.6.7.2.2.3	Test Requirements	
A.6.7.3	SS-SINR	
A.6.7.3.1	SA intra-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.3.1.1	Test Purpose and Environment	
A.6.7.3.1.2	Test Parameters	
A.6.7.3.1.3	Test Requirements	
A.6.7.3.2	SA Inter-frequency measurement accuracy with FR1 serving cell and FR1 target cell	
A.6.7.3.2.1	Test Purpose and Environment	
A.6.7.3.2.2	Test Parameters	
A.6.7.3.2.3	Test Requirements	
A.6.7.4	L1-RSRP measurement for beam reporting	
A.6.7.4.1	SSB based L1-RSRP measurement	
A.6.7.4.1.1	Test Purpose and Environment	
A.6.7.4.1.2	Test parameters	
A.6.7.4.1.3	Test Requirements	
A.6.7.4.2	CSI-RS based L1-RSRP measurement on resource set with repetition off	
A.6.7.4.2.1	Test Purpose and Environment	
A.6.7.4.2.2	Test parameters	
A.6.7.4.2.3	Test Requirements	
A.6.7.5	E-UTRAN RSRP	
A.6.7.5.1	SA: inter-RAT measurement accuracy with FR1 serving cell	
A.6.7.5.1.1	Test Purpose and Environment	
A.6.7.5.1.2	Test parameters	
A.6.7.5.1.3	Test Requirements	
A.6.7.6	E-UTRAN RSRQ	
A.6.7.6.1	SA: inter-RAT measurement accuracy with FR1 serving cell	
A.6.7.6.1.1	Test Purpose and Environment	
A.6.7.6.1.2	Test parameters	
A.6.7.6.1.3	Test Requirements	
A.6.7.7	E-UTRAN RS-SINR	
A.6.7.7.1	SA: inter-RAT measurement accuracy with FR1 serving cell	
A.6.7.7.1.1	Test Purpose and Environment.	
A.6.7.7.1.2	Test parameters	
A.6.7.7.1.3	Test Requirements	
A.6.7.8	CLI measurements	
A.6.7.8.1	SA SRS-RSRP measurement accuracy with FR1 serving cell	
A.6.7.8.1.1	Test Purpose and Environment	
A.6.7.8.1.2	Test parameters	
A.6.7.8.1.3	Test Requirements	
A.6.7.8.2	SA CLI-RSSI measurement accuracy with FR1 serving cell	
A.6.7.8.2.1	Test Purpose and Environment	
A.6.7.8.2.2	Test parameters	
A.6.7.8.2.3	Test Requirements	
A.6.7.9	L1-SINR measurement for beam reporting	
A.6.7.9.1	L1-SINR measurement with CSI-RS based CMR and no dedicated IMR configured and CS	
- · · · · ·	resource set with repetition off	
A.6.7.9.1.1	Test Purpose and Environment	
A.6.7.9.1.2	Test parameters	
A.6.7.9.1.3	Test Requirements	
A.6.7.9.2	L1-SINR measurement with SSB based CMR and dedicated IMR	
A.6.7.9.2.1	Test Purpose and Environment	
A.6.7.9.2.2	Test parameters	
A.6.7.9.2.3	Test Requirements	
A.6.7.9.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR	
A.6.7.9.3.1	Test Purpose and Environment	
A.6.7.9.3.2	Test parameters	
	1	- '

A.6.7.9.3.3	Test Requirements	1523
The L1-SIN	R measurement accuracy for CSI-RS#0+CSI-IM#0 and CSI-RS#1+CSI-IM# of Cell 1 shall	1
	the requirements in clause 10.1.27.3	
A.7 NR st	andalone tests with one or more NR cells in FR2	1523
	: RRC IDLE state mobility	
A.7.1.1	Cell re-selection to NR	
A.7.1.1.1	Cell reselection to FR2 intra-frequency NR case	
A.7.1.1.1.1	Test Purpose and Environment.	
A.7.1.1.1.2	Test Parameters	
A.7.1.1.3	Test Requirements	1527
A.7.1.1.2	Cell reselection to FR2 inter-frequency NR case	1527
A.7.1.1.2.1	Test Purpose and Environment.	
A.7.1.1.2.2	Test Parameters	
A.7.1.1.2.3	Test Requirements	1531
A.7.1.1.3	Cell reselection to FR2 intra-frequency NR case for UE fulfilling low mobility relaxed	
	measurement criterion	
A.7.1.1.3.1	Test Purpose and Environment.	
A.7.1.1.3.2 A.7.1.1.3.3	Test Pagningments	
A.7.1.1.3.3 A.7.1.1.4	Test Requirements	1334
A./.1.1.4	measurement criterion	153/
A.7.1.1.4.1	Test Purpose and Environment.	
A.7.1.1.4.2	Test Parameters	
A.7.1.1.4.3	Test Requirements	
A.7.1.1.5	Cell reselection to FR2 inter-frequency NR case for UE fulfilling low mobility relaxed	1007
,	measurement criterion.	1537
A.7.1.1.5.1	Test Purpose and Environment	
A.7.1.1.5.2	Test Parameters	
A.7.1.1.5.3	Test Requirements	1541
A.7.1.1.6	Cell reselection to FR2 inter-frequency NR case for UE fulfilling not-at-cell edge relaxed	
	measurement criterion.	
A.7.1.1.6.1	Test Purpose and Environment	
A.7.1.1.6.2	Test Parameters	
A.7.1.1.6.3	Test Requirements	
	A: RRC_INACTIVE state mobility	
A.7.3 RR A.7.3.1	CC_CONNECTED state mobility	
A.7.3.1 A.7.3.1.1	Inter-frequency handover from FR1 to FR2; unknown target cell	1544 1544
A.7.3.1.1 A.7.3.1.1.1	Test Purpose and Environment.	
A.7.3.1.1.2	Test Parameters	
A.7.3.1.1.3	Test Requirements	
A.7.3.1.2	Intra-frequency handover from FR2 to FR2; unknown target cell	
A.7.3.1.2.1	Test Purpose and Environment.	
A.7.3.1.2.2	Test Parameters	
A.7.3.1.2.3	Test Requirements	
A.7.3.1.3	Inter-frequency handover from FR2 to FR2; unknown target cell	1551
A.7.3.1.3.1	Test Purpose and Environment	1551
A.7.3.1.3.2	Test Parameters	
	est Requirements	
A.7.3.1.4	Inter-band inter-frequency synchronous DAPS handover from FR1 to FR2	
A.7.3.1.4.1	Test Purpose and Environment	
A.7.3.1.4.2	Test Parameters	
	est Requirements	
A.7.3.1.5 A.7.3.1.5.1	Inter-band inter-frequency asynchronous DAPS handover from FR1 to FR2	
A.7.3.1.5.1 A.7.3.1.5.2	Test Purpose and Environment Test Parameters	
	est Requirements	
A.7.3.1.3.3 1 A.7.3.2	RRC Connection Mobility Control	
A.7.3.2.1	SA: RRC Re-establishment.	
A 7 3 2 1 1	Intra-frequency RRC Re-establishment in FR?	1566

A.7.3.2.1.2	Inter-frequency RRC Re-establishment in FR2	
A.7.3.2.1.3	Intra-frequency RRC Re-establishment in FR2 without serving cell timing	1572
A.7.3.2.1.3.1	Test Purpose and Environment	1572
A.7.3.2.1.3.2	Test Requirements	1574
A.7.3.2.2	Random Access	1575
A.7.3.2.2.1	4-step RA type contention based random access test in FR2 for NR Standalone	1575
A.7.3.2.2.2	4-step RA type non-contention based random access test in FR2 for NR Standalone	1579
A.7.3.2.2.3	2-step RA type contention based random access test in FR2 for NR Standalone	
A.7.3.2.2.4	2-step RA type non-contention based random access test in FR2 for NR Standalone	
A.7.3.2.3	SA: RRC Connection Release with Redirection	
A.7.3.2.3.1	Redirection from NR in FR2 to NR in FR2	
	ional Handover	
A.7.3.3.1	Intra-frequency conditional handover from FR2 to FR2	
A.7.3.3.1.1	Test Purpose and Environment.	
A.7.3.3.1.2	Test Parameters	
A.7.3.3.1.2.3	Test Requirements	
A.7.3.3.2	Inter-frequency handover from FR2 to FR2; unknown target cell	
A.7.3.3.2.1	Test Purpose and Environment.	
A.7.3.3.2.2	Test Parameters	
	st Requirements	
	ing	
	JE transmit timing	
A.7.4.1.1		
A.7.4.1.1 A.7.4.1.1.1	NR UE Transmit Timing Test for FR2	
	Test Purpose and environment	
A.7.4.1.1.2	Test requirements	
	JE timer accuracy	
	Fiming advance	
A.7.4.3.1	SA FR2 timing advance adjustment accuracy	
A.7.4.3.1.1	Test Purpose and Environment	
A.7.4.3.1.2	Test Parameters	
	st Requirements	
	aling characteristics	
	Radio link Monitoring	
A.7.5.1.1	Radio Link Monitoring Out-of-sync Test for FR2 PCell configured with SSB-based RLM RS	
	non-DRX mode	
A.7.5.1.1.1	Test Purpose and Environment	
A.7.5.1.1.2	Test Requirements	
A.7.5.1.2	Radio Link Monitoring In-sync Test for FR2 PCell configured with SSB-based RLM RS in n	
	DRX mode	
A.7.5.1.2.1	Test Purpose and Environment	1608
A.7.5.1.2.2	Test Requirements	
A.7.5.1.3	Radio Link Monitoring Out-of-sync Test for FR2 PCell configured with SSB-based RLM RS	in
	DRX mode	1613
A.7.5.1.3.1	Test Purpose and Environment	1613
A.7.5.1.3.2	Test Requirements	
A.7.5.1.4	Radio Link Monitoring In-sync Test for FR2 PCell configured with SSB-based RLM RS in D	
	mode	
A.7.5.1.4.1	Test Purpose and Environment.	
A.7.5.1.4.2	Test Requirements	
A.7.5.1.5	Radio Link Monitoring Out-of-sync Test for FR2 PCell configured with CSI-RS-based RLM	
11.7.3.1.3	non-DRX mode	
A.7.5.1.5.1	Test Purpose and Environment.	
A.7.5.1.5.1 A.7.5.1.5.2	Test Requirements	
A.7.5.1.6	Radio Link Monitoring In-sync Test for FR2 PCell configured with CSI-RS-based RLM in no	
Λ./.3.1.0	DRX mode	
A 75161		
A.7.5.1.6.1	Test Purpose and Environment.	
A.7.5.1.6.2	Test Requirements	
A.7.5.1.7	Radio Link Monitoring Out-of-sync Test for FR2 PCell configured with CSI-RS-based RLM	
A 7 5 1 7 1	DRX mode	
A.7.5.1.7.1	Test Purpose and Environment.	
A 7 5 1 7 2	Test Requirements	1632

A.7.5.1.8	Radio Link Monitoring In-sync Test for FR2 PCell configured with CSI-RS-based RLM in DRX	
. = - 1 0 1	mode	
A.7.5.1.8.1	Test Purpose and Environment	
A.7.5.1.8.2	Test Requirements	
A.7.5.1.9	UE Radio Link Monitoring Scheduling Restrictions on FR2	
A.7.5.1.9.1	Test Purpose and Environment	
A.7.5.1.9.2	Test Requirements	
A.7.5.2	Interruption	
A.7.5.2.1	Interruptions during measurements on deactivated NR SCC in FR2	
A.7.5.2.2	SA interruptions at NR SRS carrier-based switching	
A.7.5.2.2.1	Test Purpose and Environment	
A.7.5.2.2.2	Test Parameters	1642
A.7.5.2.2.3	Test Requirements	1644
A.7.5.3	SCell Activation and Deactivation Delay	1644
A.7.5.3.1	SCell Activation and deactivation for SCell in FR2 intra-band in non-DRX	1644
A.7.5.3.1.1	Test Purpose and Environment	1644
A.7.5.3.1.2	Test Requirements	
A.7.5.3.2	SCell Activation and deactivation for FR1+FR2 inter-band with target SCell in FR2	
A.7.5.3.2.1	Test Purpose and Environment	
A.7.5.3.2.2	Test Requirements	
A.7.5.3.3	SCell Activation and deactivation for SCell in FR2 inter-band in non-DRX	
A.7.5.3.3.1	Test Purpose and Environment.	
A.7.5.3.3.2	Test Requirements	
A.7.5.4	Void	
A.7.5.5	Beam Failure Detection and Link recovery procedures	
A.7.5.5.1	Beam Failure Detection and Link Recovery Test for FR2 PCell configured with SSB-based BFD	1050
A.7.3.3.1	and LR in non-DRX mode	1656
A.7.5.5.1.1	Test Purpose and Environment.	
A.7.5.5.1.1 A.7.5.5.1.2	Test Requirements	
A.7.5.5.1.2 A.7.5.5.2	Beam Failure Detection and Link Recovery Test for FR2 PCell configured with SSB-based BFD	1001
A.7.3.3.2		1661
A 7 5 5 0 1	and LR in DRX mode	
A.7.5.5.2.1	Test Purpose and Environment	
A.7.5.5.2.2	Test Requirements.	1000
A.7.5.5.3	Beam Failure Detection and Link Recovery Test for FR2 PCell configured with CSI-RS-based	1///
	BFD and LR in non-DRX mode	
A.7.5.5.3.1	Test Purpose and Environment	
A.7.5.5.3.2	Test Requirements	1672
A.7.5.5.4	Beam Failure Detection and Link Recovery Test for FR2 PCell configured with CSI-RS-based	
	BFD and LR in DRX mode	
A.7.5.5.4.1	Test Purpose and Environment	
A.7.5.5.4.2	Test Requirements	1678
A.7.5.5.5	Scheduling availability restriction during Beam Failure Detection and Link Recovery for FR2	
	PCell configured with SSB-based BFD and LR in non-DRX mode	1678
A.7.5.5.5.1	Test Purpose and Environment	1678
A.7.5.5.5.2	Test Requirements	1683
A.7.5.5.6	Beam Failure Detection and Link Recovery Test for FR2 SCell configured with CSI-RS-based	
	BFD and LR in non-DRX mode	1683
A.7.5.5.6.1	Test Purpose and Environment	1683
A.7.5.5.6.2	Test Requirements	
A.7.5.5.7	Beam Failure Detection and Link Recovery Test for FR2 SCell configured with CSI-RS-based	
	BFD and LR in DRX mode	1687
A.7.5.5.7.1	Test Purpose and Environment.	
A.7.5.5.7.2	Test Requirements	
A.7.5.6	Active BWP switch	
A.7.5.6.1	DCI-based and Timer-based Active BWP Switch	
A.7.5.6.1.1	NR FR2- NR FR2 DL active BWP switch of PCell with non-DRX in SA	
A.7.5.6.1.1 A.7.5.6.1.2	NR FR1- NR FR2 DL active BWP switch of PCell with non-DRX in SA	
A.7.5.6.1.3	NR FR2 DL active BWP switch with non-DRX in SA	
A.7.5.6.1.3 A.7.5.6.1.3.1	Test Purpose and Environment	
A.7.5.6.1.3.1 A.7.5.6.1.3.2		
A.7.5.6.1.3.2 A.7.5.6.2	Test Requirements	
	RRC-based Active BWP Switch	
A.7.5.6.3	Simultaneous DCI-based and Timer-based Active BWP Switch on multiple CCs	1/09

A.7.5.6.3.1	Active BWP switch on multiple SCells with non-DRX in SA	
A.7.5.6.3.1.1	Test Purpose and Environment	1709
A.7.5.6.3.1.2	Test Requirements	1712
A.7.5.7	PSCell addition and release delay	1712
A.7.5.7.1	Addition and Release Delay of known NR PSCell	
A.7.5.7.1.1	Test Purpose and Environment	
A.7.5.7.2	Addition and Release Delay of unknown NR PSCell	1716
A.7.5.7.2.1	Test Purpose and Environment	
A.7.5.7.2.2	Test Requirements	
A.7.5.8	Active TCI state switch delay	
A.7.5.8.1	MAC-CE based active TCI state switch	
A.7.5.8.2	RRC based active TCI state switch	
A.7.5.9	Uplink spatial relation switch delay	
A.7.5.9.1	MAC-CE based Spatial Relation switch	
A.7.5.9.1.1	NR PCell FR2 spatial relation associated with known DL-RS	
A.7.5.9.1.1.2	Test Requirements	
A.7.5.9.2	RRC based spatial relation switch	
A.7.5.9.2.1	NR PCell FR2 spatial relation switch associated with a known DL-RS	
A.7.5.9.2.1.1	Test Purpose and Environment	
A.7.5.9.2.1.2	Test Requirements	
A.7.5.10	UE specific CBW change	
A.7.5.10.1	NR FR2 UE specific CBW change of PCell with non-DRX in SA	
A.7.5.10.1.1	Test Purpose and Environment	
A.7.5.10.1.2	Test Requirements	
	easurement procedure	
A.7.6.1	Intra-frequency Measurements	
A.7.6.1.1	SA event triggered reporting test without gap under non-DRX	
A.7.6.1.1	Test purpose and Environment	
A.7.6.1.1.1 A.7.6.1.1.2		
A.7.6.1.1.2 A.7.6.1.2	Test Requirements	
A.7.6.1.2 A.7.6.1.2.1		
A.7.6.1.2.1 A.7.6.1.2.2	Test Possionents	
	Test Requirements	
A.7.6.1.3	SA event triggered reporting test with per-UE gaps under non-DRX	
A.7.6.1.3.1	Test purpose and Environment	
A.7.6.1.3.2	Test Requirements	
A.7.6.1.4	SA event triggered reporting test with per-UE gaps under DRX	
A.7.6.1.4.1	Test purpose and Environment	
A.7.6.1.4.2	Test Requirements	
A.7.6.2	Inter-frequency Measurements	1/4/
A.7.6.2.1	SA event triggered reporting tests For FR2 without SSB time index detection when DRX is not used (PCell in FR2)	1747
A.7.6.2.1.1	Test Purpose and Environment	
A.7.6.2.1.2	Test Requirements	
A.7.6.2.2	SA event triggered reporting tests For FR2 without SSB time index detection when DRX is used	
	(PCell in FR2)	1750
A.7.6.2.2.1	Test Purpose and Environment	
A.7.6.2.2.2	Test Requirements	
A.7.6.2.3	SA event triggered reporting tests For FR2 with SSB time index detection when DRX is not used	1,0.
111,101210	(PCell in FR2)	1754
A.7.6.2.3.1	Test Purpose and Environment	
A.7.6.2.3.2	Test Requirements	
A.7.6.2.4	SA event triggered reporting tests For FR2 with SSB time index detection when DRX is used	1/30
A.7.0.2.4	(PCell in FR2)	1758
A.7.6.2.4.1	Test Purpose and Environment.	
A.7.6.2.4.1 A.7.6.2.4.2	Test Requirements	
A.7.6.2.4.2 A.7.6.2.5	SA event triggered reporting tests for FR2 without SSB time index detection when DRX is not	1/02
Λ. / .0.2.3	used (PCell in FR1)	1762
A 76251		
A.7.6.2.5.1	Test Possingments	
A.7.6.2.5.2	Test Requirements	1/0/
A.7.6.2.6	SA event triggered reporting tests for FR2 without SSB time index detection when DRX is used	1770
A 7 6 2 6 1	(PCell in FR1)	
A.7.6.2.6.1	Test Purpose and Environment.	1/68

A.7.6.2.6.2	Test Requirements	
A.7.6.2.7	SA event triggered reporting tests for FR2 with SSB time index detection when DRX is not use	
	(PCell in FR1)	1773
A.7.6.2.7.1	Test Purpose and Environment	1773
A.7.6.2.7.2	Test Requirements	1777
A.7.6.2.8	SA event triggered reporting tests for FR2 with SSB time index detection when DRX is used	
	(PCell in FR1)	1778
A.7.6.2.8.1	Test Purpose and Environment	1778
A.7.6.2.8.2	Test Requirements	
A.7.6.2.9	SA event triggered reporting tests For FR2 without SSB time index detection when DRX is not	
	used (PCell in FR2) (rel16 additional mandatory gap pattern 17)	1783
A.7.6.2.9.1	Test Purpose and Environment	1783
A.7.6.2.9.2	Test Requirements	1786
A.7.6.2.10	SA event triggered reporting test without gap under non-DRX	1786
A.7.6.2.10.1	Test Purpose and Environment	1786
A.7.6.2.10.2	Test Requirements	
A.7.6.2.11	SA event triggered reporting test without gap under DRX	1788
A.7.6.2.11.1	Test Purpose and Environment	1788
A.7.6.2.11.2	Test Requirements	1791
A.7.6.3	L1-RSRP measurement for beam reporting	
A.7.6.3.1	SSB based L1-RSRP measurement when DRX is not used	
A.7.6.3.1	SSB based L1-RSRP measurement when DRX is not used	1792
A.7.6.3.1.1	Test Purpose and Environment	1792
A.7.6.3.1.2	Test parameters	1792
A.7.6.3.1.3	Test Requirements	
A.7.6.3.2	SSB based L1-RSRP measurement when DRX is used	1794
A.7.6.3.2.1	Test Purpose and Environment	1794
A.7.6.3.2.2	Test parameters	1795
A.7.6.3.2.3	Test Requirements	
A.7.6.3.3	CSI-RS based L1-RSRP measurement when DRX is not used	1797
A.7.6.3.3.1	Test Purpose and Environment	
A.7.6.3.3.2	Test parameters	1798
A.7.6.3.3.3	Test Requirements	
A.7.6.3.4	CSI-RS based L1-RSRP measurement when DRX is used	
A.7.6.3.4.1	Test Purpose and Environment.	
A.7.6.3.4.2	Test parameters	
A.7.6.3.3.3	Test Requirements	1803
A.7.6.4	CLI measurements	
A.7.6.4.1	SRS-RSRP measurement with non-DRX	
A.7.6.4.1.1	Test Purpose and Environment	
A.7.6.4.1.2	Test Parameters	
A.7.6.4.1.3	Test Requirements	
A.7.6.4.2	CLI-RSSI measurement with non-DRX	
A.7.6.4.2.1	Test Purpose and Environment	
A.7.6.4.2.2	Test Parameters	
A.7.6.4.2.3	Test Requirements	
A.7.6.5	NR Measurements with autonomous gaps	
A.7.6.5.1	SA interfrequency CGI reporting in autonomous gaps test (PCell in FR2)	
A.7.6.5.1.1	Test Purpose and Environment	
A.7.6.5.1.2	Test Requirements	
A.7.6.6	L1-SINR measurement for beam reporting	1812
A.7.6.6.1	L1-SINR measurement with CSI-RS based CMR and no dedicated IMR configured when DRX	
A 7 C C 1 1	is not used.	
A.7.6.6.1.1	Test Purpose and Environment	
A.7.6.6.1.2	Test parameters	
A.7.6.6.1.3	Test Requirements	
A.7.6.6.2	L1-SINR measurement with SSB based CMR and dedicated IMR when DRX is used	
A.7.6.6.2.1	Test Purpose and Environment	
A.7.6.6.2.2	Test parameters	
A.7.6.6.2.3	Test Requirements.	1817
A.7.6.6.3	L1-SINR measurement with CSI-RS based CMR and dedicated IMR configured when DRX is	

A.7.6.6.3.1	Test Purpose and Environment	1817
A.7.6.6.3.2	Test parameters	1818
A.7.6.6.3.3	Test Requirements	1820
A.7.7 M	leasurement Performance requirements	1820
A.7.7.1	SS-RSRP	
A.7.7.1.1	SA intra-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	
A.7.7.1.1.1	Test Purpose and Environment.	
A.7.7.1.1.2	Test parameters	
A.7.7.1.1.2 A.7.7.1.1.3	Test Requirements	
A.7.7.1.2		
	SA inter-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	
A.7.7.1.2.1	Test Purpose and Environment	
A.7.7.1.2.2	Test parameters	
A.7.7.1.2.3	Test Requirements	
A.7.7.1.3	SA inter-frequency measurement accuracy with FR1 serving cell and FR2 target cell	1830
A.7.7.1.3.1	Test Purpose and Environment	1830
A.7.7.1.3.2	Test parameters	1830
A.7.7.1.3.3	Test Requirements	1833
A.7.7.2	SS-RSRQ	
A.7.7.2.1	SA intra-frequency measurement accuracy with FR2 serving cell and FR2 target cell	
A.7.7.2.1.1	Test Purpose and Environment	
A.7.7.2.1.2	Test Parameters	
A.7.7.2.1.2 A.7.7.2.1.3		
A.7.7.2.1.3 A.7.7.2.2	Test Requirements	
	SA Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	
A.7.7.2.2.1	Test Purpose and Environment	
A.7.7.2.2.2	Test Parameters	
A.7.7.2.2.3	Test Requirements	
A.7.7.3	SS-SINR	1838
A.7.7.3.1	SA intra-frequency case measurement accuracy with FR2 serving cell and FR2 target cell	1838
A.7.7.3.1.1	Test Purpose and Environment	1838
A.7.7.3.1.2	Test Parameters	1838
A.7.7.3.1.3	Test Requirements	
A.7.7.3.2	SA Inter-frequency measurement accuracy with FR2 serving cell and FR2 TDD target cell	
A.7.7.3.2.1	Test Purpose and Environment.	
A.7.7.3.2.1 A.7.7.3.2.2	Test Parameters	
A.7.7.3.2.2 A.7.7.3.2.3	Test 1 araneters	
A.7.7.4	L1-RSRP measurement for beam reporting	
A.7.7.4.1	SSB based L1-RSRP measurement	
A.7.7.4.1.1	Test Purpose and Environment	
A.7.7.4.1.2	Test parameters	
A.7.7.4.1.3	Test Requirements	1846
A.7.7.4.2	CSI-RS based L1-RSRP measurement on resource set with repetition off	1847
A.7.7.4.2.1	Test Purpose and Environment	1847
A.7.7.4.2.2	Test parameters	
A.7.7.4.2.3	Test Requirements	
A.7.7.5	CLI measurements	
A.7.7.5.1	SA SRS-RSRP measurement accuracy with FR2 serving cell	
A.7.7.5.1.1	Test Purpose and Environment	
A.7.7.5.1.2	Test parameters	
A.7.7.5.1.3	Test Requirements	
A.7.7.5.2	SA CLI-RSSI measurement accuracy with FR2 serving cell	
A.7.7.5.2.1	Test Purpose and Environment	
A.7.7.5.2.2	Test parameters	1854
A.7.7.5.2.3	Test Requirements	1856
A.7.7.6	L1-SINR measurement for beam reporting	
A.7.7.6.1	L1-SINR measurement with CSI-RS based CMR and no dedicated IMR configured and CSI-RS	
	resource set with repetition off	
A.7.7.6.1.1	Test Purpose and Environment	
A.7.7.6.1.2	Test parameters	
A.7.7.6.1.3		
	Test Requirements	
A.7.7.6.2	L1-SINR measurement with SSB based CMR and dedicated IMR	
A.7.7.6.2.1	Test Purpose and Environment	
A.7.7.6.2.2	Test parameters	1860

A.7.7.6.2.3	Test Requirements	1862
A.7.7.6.3 L	1-SINR measurement with CSI-RS based CMR and dedicated IMR	1862
A.7.7.6.3.1	Test Purpose and Environment.	
A.7.7.6.3.2	Test parameters.	
A.7.7.6.3.3	Test Requirements	
A.7.7.0.3.3	10st requirements	1005
A.8 E-UTRA st	andalone tests for NR RRM	1865
A.8.1 Void		1866
	LE state mobility	
_	RAT NR Cell re-selection	
	-UTRA Cell reselection to higher priority NR target Cell in FR1	
A.8.2.1.1.1	Test Purpose and Environment	
A.8.2.1.1.2	Test Requirements	
	-UTRA Cell reselection to lower priority NR target Cell in FR1 for UE configured with	10/1
		1073
	ghSpeedInterRAT-NR-r16	
A.8.2.1.2.1	Test Purpose and Environment	
A.8.2.1.2.2	Test Requirements	
_	NNECTED state mobility	
	over	
	-UTRAN - NR handover in FR1	
A.8.3.1.1.1	Test Purpose and Environment	
A.8.3.1.1.2	Test Requirements	
	ment procedure	
	RA – NR Inter-RAT SFTD Measurement Delay	
A.8.4.1.1 E-	-UTRA – NR Inter-RAT SFTD Measurement Delay in non-DRX	
A.8.4.1.1.1	Test Purpose and Environment	1883
A.8.4.1.1.2	Test Requirements	1885
A.8.4.1.2 E-	-UTRA – NR Inter-RAT SFTD Measurement Delay in DRX	
A.8.4.1.2.1	Test Purpose and Environment	
A.8.4.1.2.2	Test Requirements	
A.8.4.2 E-UT	RA – NR Inter-RAT Measurements	
	R Inter-RAT event triggered reporting tests for FR1 without SSB time index detection when	
	RX is not used	1887
A.8.4.2.1.1	Test Purpose and Environment.	
A.8.4.2.1.2	Test Requirements	
	R Inter-RAT event triggered reporting tests for FR1 without SSB time index detection when	1072
	RX is used	1802
A.8.4.2.2.1	Test Purpose and Environment.	
A.8.4.2.2.1 A.8.4.2.2.2	Test Requirements	
		1090
	R Inter-RAT event triggered reporting tests for FR1 with SSB time index detection when DRX	1007
	not used	
A.8.4.2.3.1	Test Purpose and Environment	
A.8.4.2.3.2	Test Requirements	1901
	R Inter-RAT event triggered reporting tests for FR1 with SSB time index detection when DRX	
	used	
A.8.4.2.4.1	Test Purpose and Environment	
A.8.4.2.4.2	Test Requirements	1905
	R Inter-RAT event triggered reporting tests for FR2 without SSB time index detection when	
D	RX is not used	1905
A.8.4.2.5.1	Test Purpose and Environment	1905
A.8.4.2.5.2	Test Requirements	1907
A.8.4.2.6 N	R Inter-RAT event triggered reporting tests for FR2 without SSB time index detection when	
	RX is used	1908
A.8.4.2.6.1	Test Purpose and Environment	
A.8.4.2.6.2	Test Requirements	
	R Inter-RAT event triggered reporting tests for FR2 with SSB time index detection when DRX	3
	not used	1911
A.8.4.2.7.1	Test Purpose and Environment	
A.8.4.2.7.2	Test Requirements	
	R Inter-RAT event triggered reporting tests for FR2 with SSB time index detection when DRX	1713
	used	1014
A.8.4.2.8.1		
1.0.4.2.0.1	Test Purpose and Environment.	1714

A.8.4.2.8.2	Test Requirements	.1916
A.8.4.2.9	NR Inter-RAT event triggered reporting tests for FR1 with SSB time index detection in DRX for	
	UE configured with highSpeedInterRAT-NR-r16	.1917
A.8.4.2.9.1	Test Purpose and Environment	
A.8.4.2.9.2	Test Requirements	
	easurement performance	
A.8.5.1	SFTD accuracy	
A.8.5.1.1		
	SFTD accuracy	
A.8.5.1.1.1	Test Purpose	
A.8.5.1.1.2	Test Environment	
A.8.5.1.1.3	Test Requirements	
A.8.5.2	E-UTRA – NR Inter-RAT Measurement Performance requirements	
A.8.5.2.1.1	E-UTRAN – NR inter-RAT measurements with FR1 target cell	.1929
A.8.5.2.1.2	E-UTRAN – NR inter-RAT measurements with FR2 target cell	.1934
A.8.5.2.1.2.1	Test Purpose and Environment	.1934
A.8.5.2.1.2.2	<u>.</u>	
A.8.5.2.1.2.3		
A.8.5.2.2	SS-RSRQ	
A.8.5.2.2.1	E-UTRAN – NR inter-RAT measurements with FR1 target cell	
A.8.5.2.2.2	E-UTRAN – NR inter-RAT measurements with FR2 target cell	
A.8.5.2.2.2.1	±	
A.8.5.2.2.2.2		
A.8.5.2.2.2.3	Test Requirements	.1943
A.8.5.2.3	SS-SINR	.1943
A.8.5.2.3.1	E-UTRAN – NR inter-RAT measurements with FR1 target cell	.1943
A.8.5.2.3.2	E-UTRAN – NR inter-RAT measurements with FR2 target cell	
A.8.5.2.3.2.1		
A.8.5.2.3.2.2	<u>.</u>	
A.8.5.2.3.2.3 A.8.5.2.3.2.3		
A.o.J.Z.J.Z.J	Test Requirements	.1949
A.9 V2X	Tests	1950
	2X Tests in FR1	
A.9.1.1	Test for V2X UE Transmit Timing	
A.9.1.1 A.9.1.1.1		
	Test for GNSS as Synchronization Reference Source	
A.9.1.1.1.1	Test Purpose and Environment	
A.9.1.1.1.2	Test requirements	
A.9.1.1.2	Test for SyncRef UE as Synchronization Reference Source	
A.9.1.1.2.1	Test Purpose and Environment	
A.9.1.1.2.2	Test requirements	.1951
A.9.1.1.3	Test for FR1 NR Cell as Synchronization Reference Source	.1951
A.9.1.1.3.1	Test Purpose and Environment	.1951
A.9.1.1.3.2	Test requirements	
A.9.1.2	Test for Initiation/Cease of SLSS Transmission with V2X Sidelink Communication	
A.9.1.2.1	Test for FR1 NR Cell as synchronization reference source without gap under non-DRX	
	,	
A.9.1.2.1.1	Test Purpose and Environment	
A.9.1.2.1.2	Test Requirements	
A.9.1.2.2	Test for SyncRef UE as synchronization reference source	
A.9.1.2.2.1	Test Purpose and Environment	.1958
A.9.1.2.2.2	Test Requirements	.1959
A.9.1.3	Test for V2X Synchronization Reference Selection/Reselection	.1960
A.9.1.3.1	Test for GNSS configured as the highest priority	.1960
A.9.1.3.1.1	Test Purpose and Environment	
A.9.1.3.1.2	Test Requirements	
A.9.1.3.2	Test for FR1 NR Cell configured as the highest priority	
A.9.1.3.2.1	Test Purpose and Environment	
A.9.1.3.2.2	Test Requirements	
A.9.1.4	Test for L1 SL-RSRP Measurement	
A.9.1.4.1	Test for V2X UE Autonomous Resource Selection/Reselection	
A.9.1.4.1.1	Test Purpose and Environment	
A.9.1.4.1.2	Test Requirements	.1969
A.9.1.4.2	Test for V2X UE Resource Pre-emption	
A.9.1.4.2.1	Test Purpose and Environment.	
	<u> •</u>	

A.9.1.4.2	=	
A.9.1.4.3	Test for V2X UE Resource Re-evaluation	1973
A.9.1.4.3	1	
A.9.1.4.3		
A.9.1.5	Test for Congestion Control Measurement	
A.9.1.5.1	Test Purpose and Environment	
A.9.1.5.2	1	
A.9.1.6	Test for Interruption	
A.9.1.6.1	Test for Interruption to WAN due to V2X Sidelink Communication	
A.9.1.6.1	1	
A.9.1.6.1	.2 Test Requirements	1985
Annex I	3 (normative): Conditions for RRM requirements applicability for operating bands	1818
B.1 Co	onditions for NR RRC_IDLE state mobility	
B.1.1	Introduction	
B.1.2	Conditions for measurements on NR intra-frequency cells for cell re-selection	
B.1.3	Conditions for measurements on NR inter-frequency cells for cell re-selection	1819
B.2 Co	onditions for UE measurements procedures and performance requirements in	
	RC CONNECTED state	1820
B.2.1	Introduction	
B.2.1.1	General	
B.2.1.2	Derivation of Minimum SSB RP values for FR1	
B.2.1.3	Derivation of Minimum SSB RP values for FR2	
B.2.1.3.1	Minimum SSB RP values for Rx Beam Peak angle of arrival	
B.2.1.3.2	Minimum SSB RP values for angle of arrival within Spherical coverage	
B.2.1.4	Gain to SS-RSRP measurement point for FR1	
B.2.1.5	Gain to SS-RSRP measurement point for FR2	
B.2.1.5.1	Gain to SS-RSRP measurement point for Rx Beam Peak angle of arrival	
B.2.2	Conditions for NR intra-frequency measurements	
B.2.3	Conditions for NR inter-frequency measurements	
B.2.4	Conditions for NR L1-RSRP reporting	
B.2.4.1	Conditions for SSB based L1-RSRP reporting	
B.2.4.2	Conditions for CSI-RS based L1-RSRP reporting	
B.2.5	Conditions for RRC connection release with redirection to NR	1827
B.2.6	Void	
B.2.6.1	Void	1829
B.2.6.2	Void	1829
B.3 RI	RM Requirements Exceptions	1830
B.3.1	Introduction	
B.3.2	Receiver sensitivity relaxation for CA	
B.3.2.1	Receiver sensitivity relaxation for UE supporting CA in FR1	1830
B.3.2.2	Receiver sensitivity relaxation for UE configured with CA in FR1	
B.3.2.2.1	Inter-band carrier aggregation	
B.3.2.2.2	Reference sensitivity exceptions due to UL harmonic interference for CA	
B.3.2.2.3	Reference sensitivity exceptions due to intermodulation interference due to 2UL CA	
B.3.2.3	Receiver sensitivity relaxation for UE supporting CA in FR2	
B.3.2.4	Receiver sensitivity relaxation for UE configured with CA in FR2	
B.3.2.4.1	Intra-band contiguous carrier aggregation	
B.3.2.4.2	Intra-band non-contiguous carrier aggregation	
B.3.3	Receiver sensitivity relaxation for DC	
B.3.3.1	Receiver sensitivity relaxation for EN-DC	
B.3.3.2	Receiver sensitivity relaxation for NE-DC	
B.3.4	Receiver sensitivity relaxation for SUL	
B.3.4.1	Receiver sensitivity relaxation for UE supporting SUL in FR1	
B.3.4.2	Receiver sensitivity relaxation for UE configured with SUL in FR1	
B.3.4.2.1	Reference sensitivity exceptions due to UL harmonic interference for SUL	
B.4 Co	onditions for V2X	
B.4.1	Test parameters for GNSS signals	
B.4.1	Conditions for PSRCH-RSRP Accuracy Requirements	

Annex (	C (informative): Change history	1834
	Conditions for L1 SL-RSRP Accuracy Requirements	
B.4.3	Conditions for Selection/Reselection to Intra-frequency SyncRef UE	1833