



V-1230
Permanent Instructions

1. Milling


(i) Plunge
(ii) Travel
(iii) Out






Recommended Settings
Depth: 12.5mm, +/- 0.5mm
Travel Centre to Centre: 20.5mm (min) - 20.7mm
Rotation Speed: CNC speeds vary with different materials. Maximum cutter rotation: 18,000

Recommended Spacing
(a): 35mm to 80mm
(b): 150mm to 350mm




2. Housing

Push into place




Scan for animation

3. Assembly - Simply push into place to connect




How it works





OVVO® V Connection System
Important! Make a test


IMPORTANT! MAKE A TEST
WICHTIG! MACHEN SIE EINEN TEST
IMPORTANT! FAIRE UN TEST
IMPORTANTE! FARE UN TEST
IMPORTANTE! HACER UNA PRUEBA

RECOMMENDED DEPTH TOLERANCES	
V-1230	12.5mm, +/- 0.5mm












INSTRUCTIONS
V-1230PC


1. Connector V-1230PC





2. Milling Examples






Recommended Settings


Plunge Depth: 12mm +/- 0.3mm

Feed speeds vary with different materials.

Tip: Plunge, Travel, Back Travel to clear excess milling dust

3. Assembly







Can be used with glue