

TASKS

Question: 1

Install a CPU and a RAM stick onto a motherboard, then apply thermal paste using the pea-sized dot technique before mounting the CPU cooler.

Hint: Take a clear photo of each step as you complete it for your documentation.

Answer: 1. Install the CPU: Open the CPU socket on the motherboard and carefully place the CPU into the socket, aligning the marked corner. Lock the socket securely.

2. Install the RAM: Open the RAM slot clips and align the notch on the RAM stick with the slot. Press it down firmly until the clips lock into place.

Apply Thermal Paste: Put a pea-sized dot of thermal paste in the center of the CPU.

3. Mount the CPU Cooler: Place the CPU cooler evenly over the CPU and secure it firmly according to the cooler mounting mechanism.

4. Documentation: Take a clear photo of each step for documentation.

Question: 2

Mount the motherboard inside a PC case and connect both the 24-pin ATX and 8-pin CPU power connectors from the power supply, making sure each connector clicks into place?

Answer: 1. Physical Installation: Securely mounting the motherboard prevents electrical shorts against the metal tray of the chassis. Always ensure the case standoffs are properly aligned with the first.

2. 24 - Pin ATX Connector: This is the primary power supply connection for the motherboard. It powers components like the RAM, PCIe slots, and chipset.

3. 8 - Pin CPU Connector: Also known as the delivers dedicated, stable power directly to the processor.

4. The "Click": Both cables use plastic retention clips. Pushing until they click ensures a complete electrical connection and prevents the cables from loosening.

Question: 3

Install a storage drive (SSD or HDD) and a GPU (graphics card) into the appropriate slots, then connect all necessary data and power cables to each device?

Answer: 1. Install the SSD/HDD in the appropriate drive bay or M.2 slot and secure it properly.

2. Install the GPU into the PCIe x16 slot on the motherboard and secure it to the case.

3. Connect the required SATA data and power cables for an SSD/HDD, if applicable.

4. Connect the required PCIe power cable from the power supply to the GPU.

5. Ensure all connections are secure and properly fitted.

Question: 4

Organize and secure all cables inside the case using zip ties or Velcro straps to ensure good airflow and a tidy appearance.

Hint: Take a photo showing your final cable management from both the front and back of the case.

Answer: 1. Organize all cables neatly inside the case.

2. Route the cables through the cable-management openings.

3. Secure the cables using zip ties or Velcro straps.

4. Keep cables away from fans and other moving parts.

5. Ensure good airflow and a clean, tidy appearance.

6. Take photos of the final cable management from both the front and back of the case.

Question: 5

Perform a final verification: check for any loose screws, confirm all power/data connections are firmly attached, and document your completed build with a series of labeled photos showing each major component installed?

- Answer:
1. Check for any loose screws and tighten them properly.
 2. Confirm that all power and data cables are firmly connected.
 3. Check that all major components are properly installed and secured.
 4. Take clear, labeled photos showing each major component installed.
 5. Verify that the completed PC build is ready for use.