PRODUCT QUALITY DEFICIENCY REPORT (PQDR)

CATEGORY	REPORT CONTROL NUMBER (RCN)	DATE
☐ I ☐ II	CLM-FT26-019	2026-11-09

1a. FROM *(Original Office Mailing Address - include DoDAAC)*	1b. ORIGINATOR NAME, PHONE NUMBER & E-MAIL ADDRESS
대경산업 / 품질관리팀 사업장 주소: 고객사 등록 정보 참조	고객 품질관리팀 / 연락처: 접수대장 참조
2a. TO *(PQDR Screening Point)*	**2b. SCREENING POINT NAME, TELEPHONE NUMBER & E-MAIL ADDRESS**
동진테크 / 품질보증팀	공급사 품질보증팀 / 연락처: 거래처 등록부 참조

3. DESCRIPTION OF DEFICIENCY (*Describe in detail what is wrong, circumstances prior to the difficulty, probable cause, any action taken, and recommendations. Attach copy of supporting documents. Continue on separate sheet if necessary. Ensure that the description answers the questions listed in the instructions on the back of this form.)*

고객 클레임 접수. 사건 ID: CLM-FT26-019

품번: SD-7119 / 대상 로트: LOT-FT-019 / 증상: 접합부 누설

입고 중 발견. 신고 수량 3개. 이번 조치 ID: ACT-FT-019.

원인과 효과는 첨부 조치 기록 및 조치 후 검사 원문으로 확인한다.

접수 파일: 이공공사출생자들_5유형_FT19.pdf

4. DATE DEFICIENCY WAS DISCOVERED

2026-11-08

5. DEFICIENT ITEM NATIONAL STOCK NUMBER (NSN)	6. DEFICIENT ITEM NOMENCLATURE	7. OPERATING TIME AT FAILURE
N/A	유체 퀵커플링	☐ Initial Hours: Days: Rounds: Cycles: Miles: Other:

8. DEFICIENT ITEM PART NUMBER	9a. MANUFACTURER'S CAGE CODE	9b. MANUFACTURER / CITY / STATE
SD-7119	N/A	동진테크 / 생산사업장

10. QUANTITY	11. SERIAL, LOT, OR BATCH NUMBER	12a. ITEM	12b. DATE MANUFACTURED, REPAIRED, OR OVERHAULED	12c. LAST REPAIR FACILITY
a. RECEIVED: 100 b. INSPECTED: 100 c. DEFICIENT: 3 d. IN STOCK: 97	SERIAL #: ☐ Unknown LOT #: LOT-FT-019 BATCH #: N/A ☐	☐ New ☐ Repaired ☐ Overhauled ☐ Unknown	Manufactured: Repaired: Overhauled:	CAGE: DODAAC: REPAIR DEPOT / CITY / STATE

13a. CONTRACT NUMBER	13b. REQUISITION / DOCUMENT NUMBER	13c. PURCHASE ORDER NUMBER
	DOC-FT19	PO-FT-019

14. GOVERNMENT FURNISHED MATERIAL	15a. ITEM UNDER WARRANTY	15b. WARRANTY EXPIRATION DATE	16. END ITEM EIC/WUC/TAMCN
☐ YES ☐ NO ☐ UNKNOWN	☐ YES ☐ NO ☐ UNKNOWN		

17. NEXT HIGHER ASSEMBLY

a. NSN	b. NOMENCLATURE	c. PART NUMBER	d. SERIAL NUMBER

18. END ITEM

a. NSN	b. NOMENCLATURE	c. TYPE/MODEL	d. SERIAL NUMBER

19. CURRENT DISPOSITION OF DEFICIENT ITEM (the Exhibit) *(Select only one value)*

☐ HOLDING EXHIBIT ☐ DISPOSED OF / DESTROYED ☐ REPAIRED ☐ OTHER *(Explain in Block 3)*

20. LOCATION OF DEFICIENT MATERIAL (e.g. Base, Camp, Station)

고객 품질관리팀 보관. 관련 검사 기록과 함께 관리.

21. ACTION REQUESTED *(Select only one value)* ☐ REPLACEMENT ☐ REPAIR ☐ CREDIT ☐ OTHER *(Explain in Block 3)*

고객 요청: 첨부 자료를 대조하여 원인 관계와 조치 효과를 검토해 주세요.

제품 식별 라벨

사건 ID	CLM-FT26-019
품번 / 대상 로트	SD-7119 / LOT-FT-019
제품명	유체 퀵커플링
제조 로트	LOT-FT-019
출하일 / 수량	2026-11-07 / 100개
라벨 상태	품번과 로트를 현물 표기로 확인
발행 부서	동진테크 생산관리팀

과거 8D 리포트

과거 사건 ID	HIS-FT-019
과거 품번 / 로트	SD-7119 / OLD-019
D2 문제 정의	접합부 누설
D3 임시 봉쇄	대상 로트 격리 및 전수 선별
D4 확정 원인	씰 안착부 가공 편차
D5 영구 조치	씰 안착부 보수 및 씰 교체
D6 검증 결과서	RES-HIS-FT-019 별첨
D7 재발 방지	정기 점검 및 교육 기록 유지
D8 종결 기록	과거 조치 당시 품질 담당 검토 완료
원인 확인 근거	분해 관찰 및 공정 비교로 해당 원인 확정

과거 조치 결과서

관련 과거 사건	HIS-FT-019
결과서 ID	RES-HIS-FT-019
과거 품번 / 로트	SD-7119 / OLD-019
조치 항목	과거 8D D5 기재 조치 이행
완료일 / 검사일	2026-09-15 09:00 / 2026-09-15 11:00
검사 범위	과거 사건의 신고 불량 계열
표본 수 / 불량 수	40개 / 0개
기준 / 실측	과거 전용 기준: 불량 수 0개 이하. 실측 0개.
유효 범위	위 과거 사건에 한함. 이번 조치 후 검사 기록을 대체하지 않음.

이번 조치 결과서

사건 ID	CLM-FT26-019
품번 / 대상 로트	SD-7119 / LOT-FT-019
이번 조치 ID	ACT-FT-019
현상 / 확정 원인	접합부 누설 / 씰 안착부 가공 편차
원인 확인 방법	공정 기록, 현품 관찰 및 원인 재현 시험으로 확인
조치 내용	씰 안착부 보수 및 씰 교체
조치 완료 시각	2026-11-09T09:00:00+09:00
효과 확인 연결	INS-FT-019
완료 범위	현장 조치 이행 완료. 효과는 별첨 검사 성적서 수치로 확인.
작성 부서	동진테크 품질보증팀

검사 기준서

검사 기준 ID / 개정	QS-FT-019 / R1
적용 대상	SD-7119 전체 로트의 이번 조치 후 검사
유효일	2026-01-01부터 유효
검사 항목	누설량
합격 조건	누설량 최댓값 <= 2.00 QS
최소 표본 수	5개
경계값 처리	<= 이므로 상한과 같은 실측값도 허용. 반올림 판정 금지.
시점 조건	이번 조치 완료 후 실시한 검사만 유효
단위 정의	QS의 물리적 정의 및 mL/min 환산 관계가 등록되어 있지 않음.

조치 후 검사 성적서

사건 ID	CLM-FT26-019
품번 / 대상 로트	SD-7119 / LOT-FT-019
이번 조치 ID	ACT-FT-019
검사 ID / 개정	INS-FT-019 / R1
검사 시각	2026-11-09T11:00:00+09:00
적용 기준	QS-FT-019 R1
검사 항목	누설량
표본 수	5개
검사 실측	최댓값 1.90 mL/min
실측 내역	표본 1-4: 1.80, 1.82, 1.84, 1.86 mL/min / 표본 5: 1.90 mL/min