## Left Coast Llama 2K board to connector wiring



## The connector at the end of the NMEA2k wire.

Looking at the end you are soldering into. Notice the key (behind) is now on your left.

