

## Fusion 360 – One-Page Hotkey Cheat Sheet

### General / Navigation

| Key          | Action                  |
|--------------|-------------------------|
| S            | Toolbox / Shortcut menu |
| Ctrl + S     | Save                    |
| Ctrl + Z / Y | Undo / Redo             |
| F6 / F7 / F8 | Orbit / Pan / Zoom      |
| Middle Mouse | Zoom / Orbit            |
| Esc          | Cancel command          |

### Sketch Mode

| Key | Action       |
|-----|--------------|
| L   | Line         |
| R   | Rectangle    |
| C   | Circle       |
| A   | Arc          |
| D   | Dimension    |
| X   | Construction |
| T   | Trim         |
| P   | Project      |
| O   | Offset       |

### Solid Modeling

| Key | Action      |
|-----|-------------|
| E   | Extrude     |
| Q   | Press Pull  |
| F   | Fillet      |
| H   | Hole        |
| M   | Move / Copy |
| C   | Combine     |
| R   | Revolve     |

### Assembly / Components

| Key      | Action         |
|----------|----------------|
| J        | Joint          |
| Ctrl + G | New Component  |
| M        | Move Component |
| Ground   | Fix component  |

### Inspect / Analyze

| Key              | Action            |
|------------------|-------------------|
| I                | Measure / Inspect |
| Ctrl + I         | Interference      |
| Section Analysis | Cutaway view      |