## $R_I E_X$





max 7,5A














## wood chipboard







OSB


plastic

















13x -> T = 25 mm14x -> T = 40 mm