Would-be PDM



Quick guide

Would-be PDM requires:

- Tortoisesvn (<u>http://tortoisesvn.net/</u>)
- CATIA
- A svn server (https://www.visualsvn.com/ or other). Tortoisesvn can be a server for himself but in this case you cannot use the svn tools made for the shared works

Why Would-be PDM?

I was looking for some tool to link CATIA with svn. I didn't find any. With my collegues we wrote some macros.

Now I found that I needed a form to control and a database to describe and group CAD files...

I couldn't find so I decided to write myself what I needed.

Steps to play

- 1 Download and install tortoisesvn (http://tortoisesvn.net/support.html)
- 2 Create a snv repository in your svn server (we propose you to create a "CAD_001" project) (https://www.visualsvn.com/server/getting-started/)
- 3 Download the tool (https://github.com/robertobartola/WouldBePDM) and unzip it in your favorite folder
- 4 Add a Woulb-be PDM toolbar in CATIA
 - 4.1 add the macros in CATIA
 - 4.1.1 Tools\Macro\Macros (Alt + F8)
 - 4.1.2 Click «Macro libraries»
 - 4.1.3 Choose «Vba Projects»
 - 4.1.4 Clck «Add existing library» and browse the unzipped file WouldBePDM.catvba
 - 4.1.5 Hit Close

- 4.1.6 Click «Macro libraries»
- 4.1.7 Choose «Directories»
- 4.1.8 Clck «Add existing library» and browse adding the folder which contains «SVN Commit Active Document.catvbs», «SVN Lock Active Document_4_0.catvbs», «SVN Status Active Document.catvbs», «SVN UnLock Active Document_3_0.catvbs», «SVN Update Active Document_4_0.catvbs»
- 4.2 Add the toolbars:
 - 4.2.1 You have 2 methods:
 - 4.2.1.1 Replace your DefaultAttributesRepository.CATSettings; FrameConfig.CATSettings; FrameGeneral.CATSettings (you can find them in your CATIA settings folder – i.e. C:\ProgramData\DassaultSystemes\CATEnv) with the ones in my CATSEttings folder. ATTENTION. This method will delete your settings!!!
 - 4.2.1.2 Create a new toolbar (Tools\Customize → toolbars\New) and add the buttons:
 - 4.2.1.2.1 «SVN Commit Active Document.catvbs», «SVN Lock Active Document_4_0.catvbs», «SVN Status Active Document.catvbs», «SVN UnLock Active Document_3_0.catvbs», «SVN Update Active Document_4_0.catvbs» taken from the fodler
 - 4.2.1.2.2 Open The Macro menu (Alt + F8) and choose The library «WouldBePDM.catvba»
 - 4.2.1.2.3 Add «Begin» and «Export_attributes_job» taken from WouldBePDM.catvba
 - 4.2.1.2.4 Choose some icons to identify the different commands
- 5 Make the firts checkout of the repository
 - 5.1 Create a folder named «CAD_001» in «documents\WORK»
 - 5.2 rightclick on the folder CAD_001 and click on «Svn Checkout» Checking out the URL of your svn server and the repository you created in step 2
- 6 Edit the project list (PRJList.xml)
 - 6.1 You can edit the file throught your preferred editor or you can use the excel tool «PDM_XML_IO_new.xlsm»
- 7 Place the CAD files in the folder ...\CAD 001\File CAD\
- 8 Enjoy Would-be PDM

Ancona 07/09/2015 robertobartola@gmail.com