




NOTE: production schematic must replace graphical blocks with real symbols, footprints, netclasses, connector part numbers, fuses and protection devices.