FLIGHT LOG								
TIME			DISTANCE	FUEL				
TAKE OFF 1600 €	LANDING		TOTAL 228	REQUIRED 51 g	jal	AVAILABLE 87	Gal	
ROUTE (Check Point)	IDENT FREQ	MAG CRSE	LEG REMAINING	ETE ATE	ETE ATE	ALTITUDE GND SPD	REMARKS	
Brookwood	0KW 111.0	230	31 197	+16	16:16	4000 120	- 3 Gal	
Kewanee	EWA 113.8	225	80 117	+40	16:56	4000 120	8 Gal	
Mindo		195	110	+54	17:50	4000 125	- 12 Gal	
Аррг			77 0	+08	17:58		- 2 Gal	
				118			-	
Rascagoula Regional	PnS	085	91	+35		3000 158	- 18 Gal	

ATIS							
	DEPERTURE	ARRIVAL					
INFORMATION		INFORMATION					
CEILING		CEILING					
VISIBILITY		VISIBILITY					
TEMP / DEWPOINT	/	TEMP / DEWPOINT	/				
WINDS		WINDS					
ALTIMETER		ALTIMETER					
RWY IN USE		RWY IN USE					
REMARKS		REMARKS					

Figure 10-19. Navigation log.

structural icing should not be a problem. Make a note to do an operational check of the pitot heat during preflight and to take evasive action immediately should even light icing conditions be encountered in flight. This may require returning to BHM or landing at an intermediate spot before reaching GPT. The go/no-go decision is constantly reevaluated during the flight.

Once at the airport, conduct a thorough preflight inspection. A quick check of the logbooks indicates all airworthiness requirements have been met to conduct this IFR flight including an altimeter, static, and transponder test within the preceding 24 calendar months. In addition, a log on the clipboard indicates the VOR system has been checked