TABLE 4

Resin Hydro- (mass %) photoic (mass %) Photoacid Resin (mass %) photoic (mass %) Resin (mass %) Resin (mass %) Pattern (mass %) Resin (mass	PEB Etc	ching esis- ance A A
Resin (mass %) phobic (mass %) phobic (mass %) Basic (mass %) Basic (mass %) Compound (0.01 (µC) Pattern (nmass %) Profile (nmass %) P	PEB Etc	A A
Example 2-2 P-2 — S-1/S-2 z11 N-3 W-4 19 rectangular 87.5 63 (80/20) 535 2 Example 2-3 P-3 — S-1/S-2 z11 N-3 W-4 22 rectangular 100.0 63 (80/20) 535 2	0.8 1.0	A
Example 2-2 P-2 — S-1/S-2 z11 N-3 W-4 19 rectangular 87.5 63 (80/20) 535 2 Example 2-3 P-3 — S-1/S-2 z11 N-3 W-4 22 rectangular 100.0 63 (80/20) 535 2	1.0	
Example 2-3 P-3 — S-1/S-2 z11 N-3 W-4 22 rectangular 100.0 63 (80/20) 535 2	1.4	A
· · ·		
	1.6	A
63 (80/20) 535 2 Example 2-5 P-5 — S-1/S-2 211 N-3 W-4 27 rectangular 112.5	1.0	A
63 (80/20) 535 2 Example 2-6 P-6 — S-1/S-2 z123 N-7 W-3 18 rectangular 75.0	0.7	A
63 (60/40) 35 2 Example 2-7 P-7 — S-1/S-2 z114 N-9 W-4 17 rectangular 75.0	0.9	A
63 (70/30) 35 2 Example 2-8 P-8 — S-1/S-2 z114 N-9 W-4 20 rectangular 87.5	1.2	A
63 (70/30) 35 2 Example 2-9 P-9 — S-1/S-2 z114 N-9 W-4 25 rectangular 100.0	1.4	A
63 (70/30) 35 2 Example 2-10 P-10 — S-1/S-2 z114 N-9 W-4 28 rectangular 112.5	1.6	A
63 (70/30) 35 2 Example 2-11 P-11 — S-1/S-2 z39 N-10 W-1 25 rectangular 100.0	1.5	A
63 (90/10) 35 2 Example 2-12 P-12 — S-1/S-2 z39 N-10 W-1 20 rectangular 75.0	1.3	A
63 (90/10) 35 2 Example 2-13 P-13 — S-1 z121 N-6 W-4 18 rectangular 87.5	1.1	A
63 35 2 Example 2-14 P-14 — S-1/S-4 z32 N-8 none 22 rectangular 87.5	1.6	A
63 (80/20) 35 2 Example 2-15 P-15 — S-1/S-3 z5 N-9 W-3 24 rectangular 87.5	1.2	A
63 (80/20) 35 2 Example 2-16 P-16 — S-2/S-4 z33 N-6 W-1 20 rectangular 100.0	1.4	A
63 (50/50) 35 2 Example 2-17 P-17 — S-1/S-4 z119 N-1 W-1 29 rectangular 100.0		A
63 (70/30) 35 2 Example 2-18 P-18 — S-1/S-2 z118 N-5 W-3 26 rectangular 100.0		A
63 (80/20) 35 2 Example 2-19 P-19 — S-3 z11 N-4 W-2 28 rectangular 100.0		A
63 35 2		
Example 2-20 P-20 — S-1/S-3 z69/z122 N-2 W-2 29 rectangular 100.0 63 (70/30) 35(20/80) 2		A
Example 2-21 P-21 — S-1/S-2 z127 N-3 W-3 24 rectangular 75.0 63 (80/20) 35 2	0.7	A
Example 2-22 P-1/P-22 — S-1/S-2 z67 N-7 W-4 25 rectangular 75.0 63(50/50) (70/30) 35 2	0.9	A
Example 2-23 P-23 — S-1/S-2 z108 N-8 W-4 20 rectangular 87.5 63 (80/20) 35 2	0.9	A
Example 2-24 P-24 HR-1 S-2/S-1 — N-6 W-3 23 rectangular 125.0 88 10 (90/10) 2	1.5	A
Example 2-25 P-34 HR-24 S-1/S-2 z132 N-11 W-4 25 rectangular 100.0	1.5	A
86 3 (60/40) 10 1 Example 2-26 P-35 HR-29 S-1/S-2 z133 N-12 W-4 24 rectangular 87.5	1.3	A
62 5 (80/20) 30 3 Example 2-27 P-29 — S-2/S-1 z130 N-11 W-2 28 rectangular 87.5	1.7	A
94 (70/30) 5 1 Example 2-28 P-26 — S-2/S-1 — N-12 W-3 26 rectangular 100.0	1.1	A
98 (80/20) 2 Example 2-29 P-31 — S-2 — N-11 W-3 29 rectangular 87.5	1.4	A
97 3 Example 2-30 P-38 — S-1/S-2 z132 N-11 W-1 26 rectangular 87.5		A
78 (70/30) 20 2		В
Example 2-1 63 (70/30) 35 2 tapered		
Comparative Ab'-2 S-1/S-2 z118 N-5 W-3 36 reverse 150.0 Example 2-2 63 (80/20) 35 2 tapered	1.9	В
Comparative Ab'-3 S-3 z11 N-4 W-2 30 tapered 125.0 Example 2-3 63 35 2	3.5	A
Comparative Ab-4 S-1/S-3 z69/z122 N-2 W-2 31 tapered 125.0 Example 2-4 63 (70/30) 35(20/80) 2	3.3	A