FURTHER INFORMATION CONTINUED FROM PCT/ISA/ 210
to clamp the feedwater sparger repair assembly to the core spray pipe.
<del></del>