Figure 2-1 shows how to connect the Expansions to a Storwize V5010.




Figure 2-1 Storwize V5010 SAS cabling

Figure 2-2 shows how to connect the Expansions to a Storwize V5020.




Figure 2-2 Storwize V5020 SAS cabling