10

15

20

25

45

50

P-05

P-04

-continued

$$Mw = 19400$$

 $Mw/Mn = 1.94$

$$Mw = 104400$$

 $Mw/Mn = 1.89$

$$Mw = 10350$$
 $Mw/Mn = 1.80$

$$\begin{aligned} Mw &= 13600 \\ Mw/Mn &= 2.02 \end{aligned} \tag{65}$$

Mw = 22400Mw/Mn = 1.65

$$\begin{array}{c} Mw = 30560 \\ Mw/Mn = 1.80 \end{array}$$

$$Mw = 20100$$

 $Mw/Mn = 1.72$

соон