

gemini-2.5-flash-lite

Enter your question about the above documents

what's the 11th guideline?

Get Answer

## Answer:

When utilizing AC motors with frequency inverters, ensure that the Maximum Speed rating indicated on the nameplate is not surpassed.

Response time: 3.29 s

References

11. When using AC motors with frequency inverters, be certain that the Maximum Speed rating (on nameplate) is not exceeded.

Citations

• File: 1b5001 • Page: 1 • Score: 1.5293896198272705

11. When using AC motors with frequency inverters, be certain that the Maximum Speed rating (on nameplate) is not exceeded.

Developed by Leticia Bossatto Marchezi

Deploy :