Stator Final Inspection

Stator MRB

6'-0.16"

L4 M4 N4

Lehmann Cutback Lathe # 2

ASSET # 0017

Material Clearance Area

Lehmann Cutback Lathe # 2

ASSET # 0017

Material Clearance Area

Material Clearance

Breakout Unit / Disassembly Bench # 1

ASSET # 0163

Control Unit

Caution Area

Material Clearance

Breakout Unit / Disassembly Bench # 2

ASSET # 0164

Control Unit

Caution Area

2'-0.95"

L5 M5 N5

42'-3.42"

Chiller Connections

L7 M7 N7

IDF

Remote Data Racks

RR H010A

1 H19

1 H20

HM14

1 H22

HM15

P3 Q3 R3

Dry Cooler Pump station

Pump station

Surge Tank

Quincy Air Compressor

Nitrogen Bulk Storage

BAC Cooling Tower ASSET# N07

LOADING ZONE

HR-42 Vacuum Furnace

ASSET # 0097

HR-42 Vacuum Furnace

ASSET # 0144

HR-42 Vacuum Furnace

ASSET # 0114

1 TON JIB

1 TON JIB

VACUUM FURNACE AREA

H012

Furnace Prep Area

1 H21

A B C D E F

P5 Q5 R5 S5 U5 V5

Stator DS1

P7 Q7 R7 S7 U7 V7

H030-D

01

1/4 T

H037-F H037-E

H037

H037-A H037-B H037-C H037-D

STATORS / ROTORS OFFICE

H036-A H036-B H036-C H036-D

H036

H036-E H036-E H036-G H036-H I

H034-D

H034

H034-F

H034-C

H034-B

H034-E

H034-A

IDF

CONF

H035

Puma 800L

ASSET # N39

Material Clearance Area

Tooling Cabinet

Work Bench

Shot Peen Area

N71

MEN RR H033

WOMEN RR H032

H031-A H031-B H031-C

HSE

H031

H030-D

H030

H030-A

H030-B

H030-E

H030-F

H030-C

H030-G

SHIPPING / PLANNING OFFICE

CONF

H029

COFFEE VENDING

PROBLEM P.O.

U9 V9

31200lb RACK

25" TOOL OUTLINE

31200lb RACK

25" TOOL OUTLINE