



STANDARD TOLERANCES UNLESS SPECIFIED

$$x = \pm 0.100$$

$$x \cdot x = \pm 0.050$$

$$x_{\cdot}xx = \pm 0.010$$

ANGLES = $\pm 0.50^\circ$

1. REFER TO CAD

Digitized by srujanika@gmail.com

2. MACHINED 0.5×0.5 CHAMFER ON THREADS.

3. BEAD BLAST SURFACE TREATMENT.
 4. ENSURE SPECIFIED TOLERANCES
ARE MAINTAINED AFTER BLASTING.
 5. PERFORM FINAL MACHINING ON CRITICAL
FEATURES AFTER BLASTING IF REQUIRED.

PROJECT	2	PART NAME	3	QUANTITY	PROJ. ANG.	SIZE	SCALE	LAST UPDATED
REMORPH		XYTTM		2	 	A4	1:1	12 Dec. 24
1	2	3	4	5	6			