

1

2

3

4

5

6

A

A

B

B

C

C

STANDARD TOLERANCES
UNLESS SPECIFIED



x = ± 0.100

$x.x$ = ± 0.050

$x.xx$ = ± 0.010

ANGLES = $\pm 0.50^\circ$

1. REFER TO CAD FOR UNDEFINED GEOMETRY.



2. BEAD BLAST SURFACE TREATMENT.
3. ENSURE SPECIFIED TOLERANCES ARE MAINTAINED AFTER BLASTING.
4. PERFORM FINAL MACHINING ON CRITICAL FEATURES AFTER BLASTING IF REQUIRED.

PROJECT	PART NAME	QUANTITY	PROJ. ANG.	SIZE	SCALE	LAST UPDATED
REMORPH	CRTS	1		A4	1:1	12 Dec. 24