

1 2 3 4 5 6

A

A

B

B

C

C

STANDARD TOLERANCES
UNLESS SPECIFIED



x = ± 0.100
x.x = ± 0.050

x.xx = ± 0.010

ANGLES = $\pm 0.50^\circ$

1. MACHINED 0.5×0.5 CHAMFER ON THREADS.
2. REFER TO CAD FOR UNDEFINED GEOMETRY.

3. BEAD BLAST SURFACE TREATMENT.
4. ENSURE SPECIFIED TOLERANCES
ARE MAINTAINED AFTER BLASTING.
5. PERFORM FINAL MACHINING ON CRITICAL
FEATURES AFTER BLASTING IF REQUIRED.



| PROJECT | PART NAME | QUANTITY | PROJ. ANG. | SIZE | SCALE | LAST UPDATED |
|---------|-----------|----------|------------|------|-------|--------------|
| REMORPH | FTLZIB | 2 | | A4 | 1:1 | 12 Dec. 24 |

1 2 3 4 5 6