
Worst case for a given tolerance
scaled worst direction: surrogate
scaled worst direction: simulator
box worst case: surrogate
box worst case: simulator
worst H/H_0
10^0
10^1
10^2
10^3
10^4
x1.74
x3.86
x9.66
x121
x2.84e+03
2
4
6
8
10
tolerance X (every parameter within ±X%)