

Trapezoidal-discretised buck inductor current under PWM
(buck @ $f_{sw} = 100\text{ kHz}$, $L = 100\text{ }\mu\text{H}$, $V_{in} = 12\text{ V}$, $V_{out} = 5\text{ V}$, duty 0.5)

