

How to order assembled PCBs from JLCPCB


1. Upload the Gerber ZIP:




Result:




2. Select "stackup"






3. Select "PCB assembly"





4. Tooling holes set by customer Please note: these holes are included in the PCB design. You just need to select this option.






5. Add production files use bom.xlsx and positions.xlsx, which are included in the production folder







The following screen shows the placement of the components. Some components are not positioned correctly. You can ignore this. It will be corrected by JLCPCB.

