



ART FILM - SILK\_BOTTOM




ART FILM - SILK\_BOTTOM

## ART FILM - SOLDERMASK\_TOP



ART FILM - SOLDERMASK\_TOP




ART FILM - SOLDERMASK\_BOTTOM

## ART FILM - PASTEMASK\_TOP

```
0 0
00
00
         000000000
      0000000000
000000
0 0 0 0 0 0 0 0 0
00 00 00 00 00
```

ART FILM - PASTEMASK\_TOP




ART FILM - PASTEMASK\_BOTTOM

		00	00 00 00 00			
00	00	00			0 0	00
	0 00					
0 0	- 55	00		00	а	
				00 00 00		
0 0	0 0		00000	0 0 0		
	00					88
	***					0
o o		0 0	° 0 0	00		0
0	0 0	0 0	0 0			
			00			
	0 0	\$ \$	\$ \$ \$		0000	$\bigcirc$

DRILL CHART: TOP to BOTTOM							
ALL UNITS ARE IN MILLIMETERS							
FIGURE	FINISHED_SIZE	PLATED	QTY				
	0.5	PLATED	6				
	0.5	PLATED	265				
۰	0.6	PLATED	6				
0	0.7	PLATED	1 6				
0	0.8001	PLATED	8				
<b>♦</b>	1.1999	PLATED	8				
Δ	1.5	PLATED	5				
0	3.4	PLATED	4				

ART FILM - DRILL\_CHART



ART FILM - DIMENSION