


## Firmware Update

## G-M202-AC-10G RTL9210B

The firmware update is only suitable for the following model: G-M202-AC-10G

## Step as follows.

- 1. Connect the enclosure with the SSD built-in to the PC.
- 2.Open file\MPTools For RTL9210B\ UTHSB\_MPtool\_Lite\_v1.12.1.423\ UTHSB\_MPtool\_Lite.exe
- 3. Check if the update tool has detected the enclosure and displays it on scree



## The update tool is already set correctly, do not change the settings.

- 4. Click Update Device button.
- 5. After the update tool displays "Pass" message, safely remove the enclosure via "Safely Remove hardware and Eject Media" menu.
- 6. Disconnect the USB cable from the PC.
- 7. Connect the enclosure to the PC again

