FRIENDLY NOTES DONT'S

Dont's

- Do not use Clutch Pedal as Foot Rest. This will reduce clutch life.
- Do not Coast vehicle in Neutral and engine switched-off position. This is a safety hazard.
- Do not run engine without Radiator Cap. Use genuine Cap only, to keep system pressurised.
- 4. Do not overtighten engine oil filter.
- 5. Front and rear suspension shock absorbers fitted on this vehicle have in-built rebound stopper. There is no separate rebound stopper fitted on the vehicle. Hence, do not drive the vehicle either without shock absorbers OR with non-genuine shock absorbers, otherwise suspension is likely to be damaged.
- If your vehicle has a turbocharged engine, do not stop the engine at once, allow it to run at idling speed for atleast 1 minute. Also do not accelerate engine till the engine oil pressure has built up.

- Do not cause heating of A/C pipe (where fitted), while welding/ brazing in its viscinity.
- 8. Do not disturb the fast idling control device actuator setting, where fitted.
- Do not open any hose/pipe points of A/C system (where fitted).
- 10. Do not put your hand inside the condenser fan when the grille is removed. Disconnect power supply to fan and switch off engine before any maintenance work, where applicable.
- Do not open HP system under any condition. It should be handled by trained professional only. (i.e. HP Pump, Rail, Injector, HP lines)
- 12. Do not clean Engine
 Compartment with high pressure
 water jet. It can cause
 Malfunctioning of electronic
 components. Cleaning can be
 done with high pressure air.