Measurement error for θ_{M1} and corrected θ_M at 5Hz Measurements Error [Deg] Rotor angle [Deg]