

DC Power Supply
(PSU)



or

Battery
48.1V (54.6V~41.6V)
6Ah / 288Wh
50A BMS




Power Bus PCB (2 Layer

Hot Swap Controller (LM5066L)

40~70V 50A

Fault Timer ?? ms



Leg



3.7V Lipo 13S2P

UVLO ???
OVLO ???

Battery Charger
54.6V 2A

