

Seawell School & Homestead Road Redesign

Lily Hayward, Patrick Dickinson, Morgan Thorstenson, Sage Weatherwax

Our Goals


- Increase pedestrian and bike safety by providing separated lanes, signaled crossing, and Hawk crossing
- Increase visibility
- Add wayfinding signs for children
- Control speed of motor vehicles
- Increase visibility of crossings
- ADA compliance
- Adhere to the towns "Vision Zero" policy initiative


Segment Concerns: Intersection of

Seawell School Rd. & High School Rd.


- Existing Rectangular Flashing Beacons & Crossings could be improved
- High pedestrian traffic during dismissal
- Overflow HS parking at Unity Center.
- High speed vehicle traffic through intersection
- H.S. Athletic teams use intersection to access trails.
- Vehicles using shoulder as queuing lane for dismissal and risky driver behavior.








- Convert empty space on the road to a two-way cycle track, and separate the bikers from drivers using flexposts.
- Add wayfinding signs to orient pedestrians and bicyclists to direction and distance key locations
- Add temporary roundabout to control increased traffic during the beginning and end of schools, while providing more structure for less experienced drivers.
- Add public art at the intersection





Segment concerns: Interception of Seawell and Savannah Terrace

- No pedestrian crosswalks
- Unsubstantial bike infrastructure
- ADA concerns on the sidewalk, when nearing the bus lot.



- Adjust the gradient of the sidewalk, decreasing the slope of the hill. Add guard rails to any point with a steeper incline or decline.
- Add a hawk crossing right after the intersection of Savannah Terrace.




Segment concerns: Seawell School Rd.& Private Driveways

- Lack Of Safe Active Mobility Crossings
- Wide Road With A Continuous Left Turn Lane
- Lack Of Bike Infrastructure
- High Speed Vehicle Traffic






- Add two hawk crossings to seawell road to give pedestrians more opportunities to cross
 - The crossing time will be set at twenty two seconds giving young children ample time to cross
- Construct medians to slow traffic, and increase awareness of drivers
- Using existing lane, add a bus cutout at the existing bus stop



Segment Concerns: Seawell School Rd & Kove Rd

- Lack Of Safe Active Mobility Crossings
- Wide Road/ Lanes
- Lack Of Bike Infrastructure
- High Speed Drivers/ Inattentive Drivers
- Kove rd And Seawell School rd Intersection Has 4
 Lanes





- Move sidewalk back to separate the pedestrians crossing from bike lanes
- Add a brick paver on the sidewalk to differentiate it from the road.
 - RRFB installed to warn drivers of cyclists crossing
- HAWK signal located south of Kove Rd



Segment concerns: Intersection of Homestead & Seawell School Rd.


- High Vehicle Traffic and Speeds
- Lack of bicycle infrastructure on Seawell School Road
- Unprotected bike lanes on Homestead Road
- Insufficient pedestrian crosswalk protection





- Add a roundabout, with biking and walking paths
 - Add a signaled crossing with brick paver in the roundabout at the Northbound approach
 - Use of green paint to indicate bike/ped activity
 - Apron for buses and emergency vehicle access
 - Add pedestrian refuges
- Add the triangular paint to signal to cars that they need to yield to pedestrian or oncoming traffic
- Made sure the bike lane in closer proximity to car traffic than pedestrian while still being separated.





Policy Recommendations

• Extend school zone to Homestead Road.

• Extend school zone operational hours to 4 P.M. *currently 3:40 P.M.*

- Involve school community in a "safe routes to school" night after retrofit is complete.
- Include spanish on wayfinding signs.
- Improve transit frequency and coverage in the area to better provide access beyond students.
- Reducing speed limit to 25 along Seawell Rd from Homestead Rd. to Seawell Elementary driveway.

Thank you!

Questions?

