TABLE I. Relative Emission Rates for K X-Rays

Element	$\kappa_{\alpha_2}/\kappa_{\alpha_1}$	$K\alpha_3/K\alpha_1$			Kβ ₄ /Kα ₁	·	Кв ₃ /Кв	Кв/Ка
12 ^{Mg}								0.013
14 ^{Si}								0.027
15 ^S								0.059
18 ^{Ar}								0.105
20 ^{Ca}	0.502							0.128
22 ^{Ti}	0.503							0.134
24 ^{Cr} 26 ^{Fe}	0.504 0.506	,						0.135
26°° 28 ^N 1	0.508							0.135
30 ^{Zn}	0.510							0.135 0.138
32 ^{Ge}	0.513							0.138
34 ^{Se}	0.515							0.157
36 ^X r	0.517			0.019				0.172
38Sr	0.520			0.030				0.180
40 ² r	0.523			0.037				0.190
42 ^{Mo}	0.525			0.041				0.197
44 ^{Ru}	0.527			0.045				0.204
46 Pd	0.529			0.048				0.210
48 ^{Cd}	0.532			0.053			0.519	0.213
50 ^{Sn}	0.534			0,055			0.519	0.220
52 ^{Te}	0.537			0.058			0.519	0.225
S4 ^{Xe}	0.539			0.064			0.518	0.232
56 ^{Ba}	0.543			0.070			0.518	0.237
58 ^{Ce}	0.546	0.11x10 ⁻³		0.076			0.518	0.242
60 Nd	0.549 0.552	0.11x10 0.14x10 ⁻³		0.083 0.086			0.518 0.517	0.247 0.250
62 Sm	0.556	0.14x10 0.17x10 ⁻³	0.192	0.089	0.85x10 ⁻³	3.02x10 ⁻³	0.517	0.255
64 ^{Gd}	0.560	0.21x10 ⁻³	0.198	0.089	0.92×10^{-3}	3.43×10^{-3}	0.517	0.257
66 ^{Dy} 68 ^{Er}	0.564	0.26x10 ⁻³	0.202	0.088	0.96x10 ⁻³	3.85×10^{-3}	0.518	0.260
68 70 ^{Yb}	0.567	0.30×10^{-3}	0.207	0.087	1.04x10 ⁻³	4.23×10^{-3}	0.518	0.264
70 72 ^H f	0.572	0.36×10^{-3}	0.212	0.085	1.16x10 ⁻³	4.62×10^{-3}	0.518	0.267
74 ^W	0.576	0.43×10^{-3}	0.216	0.086	1,28x10 ⁻³	5.04×10^{-3}	0.518	0.269
76 ⁰ s	0.580	0.51x10 ⁻³	0.222	0.087	1.43×10 ⁻³	5.44x10 ⁻³	0.519	0.273
78 ^{Pt}	0.583	0.63×10^{-3}	0.226	0.091	1.61×10^{-3}	5.84x10 ⁻³	0.520	0.275
_{RO} Hg	0.588	0.76×10^{-3}	0.228	0.096	1.80x10 ⁻³	6.24x10 ⁻³	0.520	0.278
82 ^{Pb}	0.593	0.91x10 ⁻³	0.228	0.102	2.02x10 ⁻³	6.64×10^{-3}	0.521	0.280
84 ^{Po}	0.597	1.12x10 ⁻³	0.228	0.108	2.26x10 ⁻³	7.05×10^{-3}	0.522	0.283
86 ^{Rn}	0.602	1.32×10^{-3}	0.228	0.113	2.52×10^{-3}	7.48×10^{-3}	0.523	0.286
88 ^{Ra}	0.608	1.58x10 ⁻³ 1.85x10 ⁻³	0.230	0.117	2.80×10^{-3}	7.80×10^{-3}	0.524	0.287
90 Th	0.613	$\frac{1.85 \times 10^{-3}}{2.15 \times 10^{-3}}$	0.232	0.120	3.13×10^{-3} 3.47×10^{-3}	8.25x10 ⁺³ 8.65x10 ⁺³	0.525	0.288
92 ^U	0.619 0.625	Z.13X10	0.234 0.234	0.123 0.12\$	3.47X10	8.05XIU	0.527	0.289 0.291
94 Pu	0.632		0.234	0.128			0.528 0.529	0.291
96 ^{Cm}	0.642		0.234	0.128			0.529	0.295
98 ^{Cf}	0.648		0.240	0.135			0.533	0.297
100 ^{Fm}	J		31 b 1 C	31430			0.000	V1271

🗽 page 94 for Explanation of Table