Category	Command	Shortcut(s)	Search Shortcut
File	New	Ctrl+N	
File	Open	Ctrl+O	
File	Open Recent		
File	Recent File		
File	Browse Recent Documents	R	
File	Close	Ctrl+W	
File	Make Drawing from Part		
File	Make Assembly from Part		
File	Save	Ctrl+S	
File	Save As		
File	Save All		
File	Page Setup		
File	Print Preview		
File	Print	Ctrl+P	
File	Print3D		
File	Publish to 3DVIA.com		
File	Publish to eDrawings		
File	Pack and Go		
File	Send To		
File	Reload		
File	Find References		
File	Properties		
File	Exit		
Edit	Undo	Ctrl+Z	
Edit	Redo	Ctrl+Y	
Edit	Repeat Last Command	Enter	
Edit	Select All	Ctrl+A	
Edit	Cut	Ctrl+X	
Edit	Copy	Ctrl+C	
Edit	Paste	Ctrl+V	
Edit	X Delete	Delete	
Edit	Copy to Adobe Illustrator		
Edit	Rebuild	Ctrl+B	r
Edit	◆ Rollback		
Edit	Roll to Previous		
Edit	Roll to End		
Edit	Suppress		
Edit	This Configuration		
Edit	All Configurations		
Edit	Specified Configurations		
Edit	Unsuppress		

Category	Command	Shortcut(s)	Search Shortcut
Edit	† This Configuration		
Edit	All Configurations		
dit	Specified Configurations		
Edit	Unsuppress with Dependents		
Edit	This Configuration		
Edit	All Configurations		
dit	Specified Configurations		
dit	Sketch		
dit	Sketch Plane		
Edit	Exit Sketch without Saving Changes		
dit	Design Table		
dit	Edit Table		
Edit	Edit Table in New Window		
Edit	Bend Table		
dit	Edit Table		
Edit	Edit Table in New Window		
dit	Delete		
dit	Object		
dit	Display Content		
Edit	Display as Icon		
Edit	Reset Size		
Edit	Definition		
Edit	Flip Normal		
dit	Appearance		
Edit	Appearance		
Edit	Material		ma
dit	Copy Appearance	Ctrl+Shift+C	
Edit	Paste Appearance	Ctrl+Shift+V	
Edit	Sketch/Curve Color		
dit	Properties		
/iew	Redraw	Ctrl+R	
/iew	Screen Capture		
/iew	Image Capture		
/iew	Record Video		
/iew	Stop Video Record		
/iew	Display		
/iew	Wireframe		
/iew	Hidden Lines Visible		
/iew	Hidden Lines Removed		
/iew	Shaded With Edges		
View	Shaded		

Category	Command	Shortcut(s)	Search Shortcut
View	Praft Quality HLR/HLV		
View	Shadows In Shaded Mode		
View	Ambient Occlusion		
View	Perspective		
View	Section View		sec
View	amera View		
View	Curvature		
View	Zebra Stripes		
View	Surface Curvature Combs		
View	🔊 Draft Analysis		
View	Undercut Analysis		
View	Parting Line Analysis		
View	RealView Graphics		
View	Cartoon		
View	Tangent Edges Visible		
View	Tangent Edges as Phantom		
View	Tangent Edges Removed		
View	Isolate		
View	Modify		
View	orientation	SpaceBar	
View	🔎 Zoom to Fit	Ctrl+F	zf
View	🔊 Zoom to Area		
View	Zoom In/Out		
View	Zoom to Selection		
View	Rotate		
View	Pan		
View	G Roll		
View	Turn Camera		
View	Previous View		
View	Set Current View As		
View	Front		
View	Back		
View	<b>Т</b> ор		
View	Bottom		
View	Left		
View	Right		
View	Rotate About Scene Floor		
View	Zoom About Screen Center		
View	Perspective		
View	Section View		
View	Zebra Stripes		

Category	Command	Shortcut(s)	Search Shortcut
View	Draft Analysis		
/iew	Dudercut Analysis		
View	Parting Line Analysis		
View	Lights and Cameras		
View	Add Directional Light		
View	Add Point Light		
/iew	Add Spot Light		
View	Add Sunlight		
View	and Camera		
View	Add Walk-through		
View	Properties		
View	Light1		
View	Delete		
View	Light1		
View	Hide / Show		
View	Hide All Types		
View	Abc All Annotations		
View	Axes		
View	Temporary Axes		
View	Cameras		
View	Center of mass		
View	Coordinate Systems		
View	Datum Reference Frame		
View	Curves		
View	D1 Dimension Names		
View	₩ Lights		
View	Live Section Planes		
View	Origins		
View	Parting Lines		
View	Planes	Shift+P	
View	Points		
View	Routing Points		
View	Sketches	Shift+T	
View	Sketch Dimensions		
View	Sketch Planes		
View	Weld Bead		
View	Annotation Link Errors		
View	Annotation Link Variables		
View	Decals		
View	# Grid		
View	Simulation Symbols		

Category	Command	Shortcut(s)	Search Shortcut
View	L Sketch Relations	Shift+R	
View	Bodies		
View	Primary Planes		
View	Toolbars		
View	Command Manager		
View	2D to 3D		
View	Align		
View	Annotation		
View	Assembly		
View	R Blocks		
View	Configurations		
View	Curves		
View	Dimensions/Relations		
View	DimXpert		
View	Display States		
View	Prawing		
View	Explode Sketch		
View	Fastening Feature		
View	Features		
View	B Formatting		
View	Layer		
View	Layout Tools		
View	Line Format		
View	Macro		
View	Mold Tools		
View	MotionManager		
View	Quick Snaps	F3	
View	Reference Geometry		
View	Render Tools		
View	Screen Capture		
View	Selection Filter		
View	Sheet Format		
View	Sheet Metal		
View	Sketch		
View	SOLIDWORKS MBD		
View	SOLIDWORKS Add-ins		
View	N Spline Tools		
View	Standard		
View	Standard Views		
View	Surfaces		
View	Table		

Category	Command	Shortcut(s)	Search Shortcut
View	Tools		
View	View		
View	View (Heads-Up)		
View	€ Web		
View	Weldments		
View	Customize	Alt+C	
View	Workspace		
View	Default		
View	Widescreen		
View	Dual Monitor		
View	User Interface		
View	FeatureManager Tree Area	F9	
View	□ Dynamic Reference Visualization (Parent)		
View	Dynamic Reference Visualization (Child)		
View	Toolbars	F10	
View	Task Pane	Ctrl+F1	
View	Motion Manager		
View	Status Bar		
View	Full Screen	F11	
Insert	Boss/Base		
Insert	Extrude	В	
Insert	Revolve		
Insert	₹ Sweep		
Insert	₽ Loft		lo
Insert	Boundary		
Insert	Thicken		
Insert	Cut		
Insert	Extrude	С	
Insert	Revolve		
Insert	Sweep		
Insert	Loft		
Insert	Boundary		
Insert	Thicken		
Insert	With Surface		
Insert	Features		
Insert	Fillet/Round	F	f
Insert	Chamfer		
Insert	Hole Wizard		
Insert	Thread		
Insert	i Simple		
Insert	raft		

Category	Command	Shortcut(s)	Search Shortcut
Insert	Shell		
Insert	Rib		
Insert	Scale		
Insert	Oome		
Insert	📤 Freeform		
Insert	Peform		
Insert	衡 Indent		
Insert	Flex		
Insert	Wrap		
Insert	Cavity		
Insert	Join		
Insert	Combine		
Insert	Intersect		
Insert	Split		
Insert	Move/Copy		m
Insert	Delete/Keep Body		
Insert	Imported		
Insert	Save Bodies		
Insert	Create Assembly		
Insert	Pattern/Mirror		
Insert	C Linear Pattern		pat
Insert	Circular Pattern		
Insert	<b>Ե</b> ւ Mirror		mi
Insert	Table Driven Pattern		
Insert	Sketch Driven Pattern		
Insert	Curve Driven Pattern		
Insert	를 Fill Pattern		
Insert	Variable Pattern		
Insert	Fastening Feature		
Insert	Mounting Boss		
Insert	¶ Snap Hook		
Insert	Snap Hook Groove		
Insert	Went		
Insert	lip / Groove		
Insert	FeatureWorks		
Insert	Recognize Features		
Insert	Options		
Insert	Surface		
Insert	Extrude		
Insert	Revolve		
Insert	₹ Sweep		

Category	Command	Shortcut(s)	Search Shortcut
Insert	<b>↓</b> Loft		
Insert	Boundary Surface		
Insert	Planar		
Insert	Flatten		
Insert	Fillet/Round	F	f
Insert	Offset		
Insert	Radiate		
Insert	Ruled Surface		
Insert	Fill.		
Insert	🃤 Freeform		
Insert	Mid Surface		
Insert	Parting Surface		
Insert	Extend		
Insert	Trim		
Insert	◆ Untrim		
Insert	Knit		
Insert	Move/Copy		m
Insert	Face		
Insert	Delete		
Insert	Replace		
Insert	Move		
Insert	Heal Edges		
Insert	Import Diagnostics		
Insert	Curve		
Insert	Split Line		
Insert	Projected		
Insert	Composite		
Insert	Curve Through XYZ Points		
Insert	Curve Through Reference Points		
Insert	Helix/Spiral		
Insert	Reference Geometry		
Insert	Plane	G	pl
Insert	Live Section Plane		
Insert	Axis		
Insert	Coordinate System		cs
Insert	□ Point		
Insert	Center of Mass		
Insert	Mate Reference		
Insert	Grid System		
Insert	Sheet Metal		
Insert	Base Flange		

Category	Command	Shortcut(s)	Search Shortcut
Insert	Convert To Sheet Metal		
Insert	Edge Flange		
Insert	Miter Flange		
Insert	Swept Flange		
Insert	Hem		
Insert	₹ Jog		
Insert	Sketched Bend		
Insert	Cross Break		
Insert	Closed Corner		
Insert	Welded Corner		
Insert	Break Corner		
Insert	Corner Relief		
Insert	Corner Trim		
Insert	Sheet Metal Gusset		
Insert	Unfold		
Insert	Fold		
Insert	Lofted Bends		
Insert	Bends		
Insert	Rip		
Insert	Bend Table		
Insert	From File		
Insert	New		
Insert	Forming Tool		
Insert	Weldments		
Insert	Weldment		
Insert	Structural Member		
Insert	Trim/Extend		
Insert	J Gusset		
Insert	end Cap		
Insert	Fillet Bead		
Insert	Weld Bead		
Insert	Molds		
Insert	insert Mold Folders		
Insert	Parting Line		
Insert	Shut-Off Surfaces		
Insert	Parting Surface		
Insert	Tooling Split		
Insert	Core		
Insert	Scale		
Insert	Radiate Surface		
Insert	Ruled Surface		

Category	Command	Shortcut(s)	Search Shortcut
Insert	Split		
Insert	Cavity		
Insert	Exploded View		
Insert	Explode Line Sketch		
Insert	Model Break View		
Insert	Part		
Insert	Mirror Part		
Insert	Sketch		
Insert	3D 3D Sketch		
Insert	3D Sketch On Plane		
Insert	Derived Sketch		
Insert	Sketch From Drawing		
Insert	DXF/DWG		
Insert	Design Study		
Insert	RAdd		
Insert	Parameters		
Insert	Tables		
Insert	Bill of Materials		bom
Insert	Design Table		
Insert	Title Block Table		
Insert	General Table		
Insert	Annotations		
Insert	A Note		
Insert	D Balloon		
Insert	Stacked Balloon		
Insert	✓ Surface Finish Symbol		
Insert	Weld Symbol		
Insert	Geometric Tolerance		
Insert	A Datum Feature Symbol		
Insert	Datum Target		
Insert	Cosmetic Thread		
Insert	Area Hatch/Fill		
Insert	Location Label		
Insert	Object		
Insert	Ryperlink		
Tools	SOLIDWORKS Applications		
Tools	SOLIDWORKS Explorer		
Tools	Part Reviewer		
Tools	Xpress Products		
Tools	DriveWorksXpress		
Tools	OFMXpress		

Category	Command	Shortcut(s)	Search Shortcut
Tools	SimulationXpress		
Tools	FloXpress		
Tools	SustainabilityXpress		
Tools	SOLIDWORKS PDM		
Tools	Get Latest Version		
Tools	Get		
Tools	Check Out		
Tools	Check In		
Tools	Undo Check Out		
Tools	Properties		
Tools	Options		
Tools	Defeature		
Tools	ਜੇਵਣ Export To AEC		
Tools	Select		
Tools	Magnified Selection		
Tools	Box Selection		
Tools	S Lasso Selection		
Tools	Select All	Ctrl+A	
Tools	Invert Selection		
Tools	Power Select		
Tools	Compare		
Tools	DrawCompare		
Tools	Documents		
Tools	Features		
Tools	Geometry		
Tools	Report Manager		
Tools	Find/Modify		
Tools	Find and Replace Annotation		
Tools	Find/Modify Features		
Tools	🛅 Simplify		
Tools	Feature Paint		
Tools			
Tools	Sketch Entities		
Tools	Line	L	I
Tools	Corner Rectangle		
Tools	Center Rectangle		
Tools	3 Point Corner Rectangle		
Tools	3 Point Center Rectangle		
Tools	Parallelogram		
Tools	straight Slot		
Tools	Centerpoint Straight Slot		

Category	Command	Shortcut(s)	Search Shortcut
Tools	3 Point Arc Slot		
Tools	Centerpoint Arc Slot		
Γools	Polygon		
Tools	Circle		
Tools	Perimeter Circle		
Tools	Centerpoint Arc		
Tools	Tangent Arc		
Tools	3 Point Arc		a
Tools	© Ellipse		е
Tools	Partial Ellipse		
Tools	V Parabola		
Tools	Conic		
Tools	N Spline		
Tools	Style Spline		
Tools	Spline on Surface		
Tools	🖟 Equation Driven Curve		
Tools	□ Point		
Tools	Centerline		
Tools	Midpoint Line		
Tools	A Text		
Tools	Plane		
Tools	Route Line		
Tools	Belt/Chain		
Tools	Sketch Tools		
Tools	Fillet		
Tools	Chamfer		
Tools	C Offset Entities		0
Tools	Convert Entities		
Tools	Intersection Curve		
Tools	Face Curves		
Tools	□ <b>#</b> Segment		
Tools	Trim		tr
Tools	Extend		
Tools	Split Entities		
Tools	<b>□</b> Jog Line		
Tools	Construction Geometry		
Tools	Make Path		
Tools	다리 Mirror		
Tools	Dynamic Mirror		
Tools	Stretch Entities		
Tools	Move		

Category	Command	Shortcut(s)	Search Shortcut
Tools	Rotate		
Tools	Scale		
Tools	Сору		
Tools	Replace Entity		
Tools	많 Linear Pattern		
Tools	다. Circular Pattern		
Tools	Edit Linear Pattern		
Tools	Edit Circular Pattern		
Tools	Edit Polygon		
Tools	Create Sketch from Selections		
Tools	Repair Sketch		
Tools	SketchXpert		
Tools	Align		
Tools	Sketch		
Tools	Align Grid/Origin		
Tools	Modify		
Tools	Close Sketch to Model		
Tools	Check Sketch for Feature		
Tools	2D to 3D		
Tools	Front		
Tools	<b>Т</b> ор		
Tools	Right		
Tools	Bottom		
Tools	Left		
Tools	Back		
Tools	Auxiliary		
Tools	Extrude		
Tools	Cut		
Tools	Sketch Picture		
Tools	Area Hatch/Fill		
Tools	Sketch Settings		
Tools	K Automatic Relations		
Tools	Automatic Solve		
Tools	Enable Snapping		
Tools	No Solve Move		
Tools	Detach Segment on Drag		
Tools	Override Dims on Drag/Move		
Tools	Blocks		
Tools	Make		b
Tools	Edit		
Tools	A Insert		

Category	Command	Shortcut(s)	Search Shortcut
Tools	Add/Remove Entities		
Tools	Rebuild		
Tools	Save		
Tools	Explode		
Tools	Spline Tools		
Tools	Add Tangency Control		
Tools	* Add Curvature Control		
Tools	Insert Spline Point		
Tools	Insert Control Vertex		
Tools	Simplify Spline		
Tools	Convert to Style Spline		
Tools	Convert to Interpolating Spline		
Tools	Fit Spline		
Tools	Show Spline Handles		
Tools	Show Spline Control Polygon		
Tools	Show Inflection Points		
Tools	Show Minimum Radius of Curvature		
Tools	Show Curvature		
Tools	Dimensions		
Tools	Smart		
Tools	Horizontal		
Tools	Vertical		
Tools	💤 Ordinate		
Tools	Horizontal Ordinate		
Tools	Vertical Ordinate		
Tools	1/2 Angular Running Dimension		
Tools	Path Length		
Tools	Align Ordinate		
Tools	Fully Define Sketch		
Tools	Relations		
Tools	<u></u> Add		
Tools	L Display/Delete		
Tools	Quick Snaps		
Tools	Points		
Tools	Center Points		
Tools	Mid-points		
Tools	Quadrant Points		
Tools	X Intersections		
Tools	Nearest		
Tools	Ò Tangent		
Tools	Yerpendicular		

Category	Command	Shortcut(s)	Search Shortcut
Tools	Parallel		
Tools	Horizontal/Vertical		
Tools	H/V To Points		
Tools	<b>├</b> Length		
Tools	Grid		
Tools	▲ Angle		
Tools	Geometry Analysis		
Tools	Equations		
Tools	Thickness Analysis		
Tools	Symmetry Check		
Tools	DimXpert		
Tools	Auto Dimension Scheme		
Tools	Location Dimension		
Tools	Size Dimension		
Tools	<b>P</b> BasicDimension		
Tools	A Datum		
Tools	☐Ⅲ Geometric Tolerance		
Tools	Pattern Feature		
Tools	Show Tolerance Status		
Tools	Copy Scheme		
Tools	Delete All Tolerances		
Tools	TolAnalyst Study		
Tools	Macro		
Tools	Edit		
Tools	New		
Tools	II● Record		
Tools	▶ Run		
Tools	Stop		
Tools	1 C:\markforged\MF Design Library\Macros\pdf test.s		
Tools	2 C:\Users\bennett\Dropbox (Markforged)\Markforge		
Tools	3 C:\Users\bennett\Dropbox (Markforged)\Markforge		
Tools	4 C:\Users\bennett\Dropbox (Markforged)\Markforge		
Tools	5 C:\Users\bennett\Desktop\Change Note 2.swp		
Tools	6 C:\Users\bennett\Desktop\Custom Properties.swp		
Tools	7 C:\Users\bennett\Desktop\Macro1.swp		
Tools	8 C:\Users\bennett\Dropbox (Markforged)\Markforge		
Tools	9 C:\Users\bennett\Dropbox (Markforged)\Markforge		
Tools	Evaluate		
Tools	Measure	М	
Tools	Mass Properties		
Tools	Section Properties		

Category	Command	Shortcut(s)	Search Shortcut
Tools	Performance Evaluation		
Tools	Check		
Tools	Import Diagnostics		
Tools	Deviation Analysis		
Tools	Add-Ins		
Tools	Save/Restore Settings		
Tools	Customize	Alt+C	
Tools	Options		
Window	↔ Span Displays		
Window	Viewport		
Window	Single View		
Window	Two View - Horizontal		
Window	Two View - Vertical		
Window	Four View		
Window	Link Views		
Window	New Window		
Window	Cascade		
Window	Tile Horizontally		
Window	Tile Vertically		
Window	Arrange Icons		
Window	Close All		
Window	Browse Open Documents		
Help	③ SOLIDWORKS Help		
Help	SOLIDWORKS Tutorials		
Help	SOLIDWORKS PDM Help Topics		
Help	API Help Topics		
Help	Search		
Help	③ SOLIDWORKS Help	Н	
Help	Commands	W	
Help	Files and Models	I	
Help	MySolidWorks		
Help	Marken Knowledge Base	К	
Help	Community Forum	0	
Help	₿ Blogs		
Help	CAD Models		
Help	Training		
Help	E Twitter		
Help	You Youtube		
Help	Manufacturers		
Help	Release Notes		
Help	What's New		

Category	Command	Shortcut(s)	Search Shortcut
Help	HTML		
Help	PDF		
Help	🍞 Interactive		
Help	What's New Examples		
Help	Introducing SOLIDWORKS (pdf)		
Help	Moving from 2D to 3D		
Help	Use SOLIDWORKS Web Help		
Help	Check for Updates		
Help	SolidNetWork License Manager		
Help	My Products		
Help	About SOLIDWORKS		
Help	About SOLIDWORKS PDM		
Others	Front	Ctrl+1	
Others	<b>☐</b> Back	Ctrl+2	
Others	Left Left	Ctrl+3	
Others	Right	Ctrl+4	
Others	<b>П</b> Тор	Ctrl+5	
Others	Bottom	Ctrl+6	
Others	sometric sometric	Ctrl+7	
Others	♣ Normal To	Ctrl+8,N	
Others	Command option toggle	A	
Others	Expand/Collapse Tree		
Others	Collapse all Items.	Shift+C	
Others	Filter Edges	E	
Others	Find/Replace		
Others	Next Edge		
Others	Force Regen	Ctrl+Q	
Others	Shortcut Bar	S	
Others	Show Flat Tree View	Ctrl+T	
Others	° ▼ Filter Vertices	V	
Others	Scroll to FeatureManager tree bottom	End	
Others	Escape		
Others	Toggle Notes Upper Case.	Shift+F3	
Others	Toggle Selection Filter Toolbar	F5	
Others	Toggle Selection Filters	F6	
Others	Abs Spell Checker	F7	
Others	Hide/Show Display Pane.	F8	
Others	Scroll to FeatureManager tree top	Home	
Others	Next Command Manager Tab	Ctrl+Next	
Others	Select Annotation View	SingleQuote	
Others	Previous Command Manager Tab	Ctrl+Prior	

Category	Command	Shortcut(s)	Search Shortcut
Others	View Selector	Ctrl+SpaceBar	
Others	Filter Faces	Х	
Others	Accept Edge	Υ	
Others	Zoom Out	Z	
Others	Zoom In	Shift+Z	
Others	Previous View	Ctrl+Shift+Z	
Others	Move Selection Breadcrumbs, Confirmation Corner	D	
Others	× Cancel		
Others	— Make Horizontal		
Others	Make Vertical		
Others	Make Collinear		
Others	Make Coradial		
Others	Make Perpendicular		
Others	Make Parallel		
Others	Make Tangent		
Others	Make Concentric		
Others	Make Midpoint		
Others	Make Intersection		
Others	Make Coincident		
Others	→ Make Curves Equal Length		
Others	= Make Equal		
Others	☑ Make Symmetric		
Others	Make Fixed		
Others	Make Pierce		
Others	Make Tangent Face		
Others	✓ Merge Points		
Others	Make Normal		
Others	Make Parallel to YZ plane		
Others	Make Parallel to ZX plane		
Others	C= Adds equal curvature to the common end of the sele		
Others	T  ■ Adds equal tangent to the common end of the selection		
Others	Make AlongZ		
Others	Show Triad Manipulator		
Others	Instant3D		
Others	Instant2D		
Others	Parent/Child		
Others	Trimetric		
Others	Dimetric		
Others	Exit Isolate		
Others	Select Other		
Others	Hide/Show Components		

Category	Command	Shortcut(s)	Search Shortcut
Others	Change Layer		
Others	layer Properties		
Others	Flexible or Rigid		
Others	SmartMates		
Others	N Hide the Hovered-over Component/Bodies	TAB	
Others	Now the Hovered-over Component/Bodies	Shift+TAB	
Others	Now all the hidden Components/Bodies	Ctrl+Shift+TAB	
Others	Small (default)		
Others	Medium		
Others	<b>○</b> Large		
Search	Search SOLIDWORKS Help	Н	
Search	Search Commands	W	
Search	Search Files and Models	I	
Search	Search MySolidWorks		
Search	Search Knowledge Base	К	
Search	Search Community Forum	0	
Search	Search Blogs		
Search	Search CAD Models		
Search	Search Training		
Search	Search Twitter		
Search	You Search Youtube		
Search	Search Manufacturers		
Macros	New Macro Button		