


C1-3 Hall sensors are DRV5055A1QLPG

B20D Ymax=8000 Zmax=10600 B2 Endbell Ymax=8200 Zmax=7100 B2 Hall magnet wheel Ymax=8400 Zmax=10400

Linear Labs Inc				
Steppers / Sensors				
Doug Gammill	Rev 1.0	2 - 6 4		
	7/9/2021	3 of 4		



CH1-3 Hall sensors are DRY5055A1QLPG

Linear Labs Inc			
Sensor1			
Doug Gammill	Rev 1.0	4 of 4	
	7/9/2021		

