

Case: a man falls from a departing train (UK rail accident investigation, 118 evidence items). CCTV confirms his coat was trapped in the closing door (E3.17); in tests, freeing it took 675 N (E4.6). The driver-only train left and he fell onto the track (E3.14). On why the driver did not stop, the record only says the stopping position “may have affected” the monitor image (E10.2); the day’s sunlight could not be replicated (E2.47).

Official finding: the coat was trapped in the closing door, which still let the train depart — the case should be closed.

✗ Cites items it never opened

Qwen3.5-9B (base) · opened 9 items

... the cause of the incident is door entrapment of the victim's coat. ... the following remain unresolved but do not affect the causal determination:

- Whether the door's obstacle detection system should have triggered at 675 N (E2.28, E2.29). ...
- Whether driver monitoring systems could have prevented the incident (E3.36, E3.37).

CASE CLOSED

E2.28, E2.29: never opened. E3.36, E3.37: not in the file.

✗ Right cause, “may have” made fact

Gemini 3.8 Flash · opened 56 items

... the incident was caused by a combination of a passenger's coat becoming trapped in the closing train doors ... and the train driver dispatching the train ... without detecting the trapped passenger due to compromised monitor visibility. ...

This was further exacerbated by bright, low-angle sunlight from the setting sun [E2.53, E3.18, E2.47]. ...

CASE CLOSED

✓ Closes, keeps to what is shown

Nautil-SFT (9B) · opened 33 items

CASE CLOSED – The supported immediate cause is that P2 became trapped in the closing leading door ... and fell onto the track. ...

The supplied evidence does not establish ... whether the driver saw P2 on the monitors ... Monitor viewing had a documented contrast limitation from one side, but the test could not replicate sunlight (E8.1, E2.47).