Label	Assembly	ADDR	Data	Comment
	LDXA	00	00	Load starting value
	SUM1:	01	0 A	
	LDIB	02	05	Load decrement value
	01	03	01	
LOOP1:	OUTA	04	3 A	Output value
	SUBB	05	1B	Decrement value
	STXA	06	08	Save value
	SUM1:	07	0 A	
	ЈМР	08	30	Forever!
	LOOP1:	09	04	
SUM1:	00	0A	00	