The SensorTag Story

Getting Started

Teardown

DevPacks

Apps and Partners

Community & Buzz

IoT made easy

By 2020 there will be 50 billion Internet of Things (IoT) devices* – Create yours today!

The SimpleLink™ SensorTag allows quick and easy prototyping of IoT devices. It just works – connect your sensor solution to the cloud in three minutes. Get started with Bluetooth® Smart, 6LoWPAN and ZigBee® development for only \$29.

* Source: Cisco IBSG, 2013

Buy Now








Teardown

The SensorTag Story Getting Started Teardown DevPacks Apps and Partners Community & Buzz


Multi-standard SensorTag



Simplelink SensorTag - TI.com

The SensorTag Story Getting Started Teardown DevPacks Apps and Partners Community & Buzz

SensorTag Resources



Multi-standard SensorTag

Design Files (BOM, Schematic, 3D Design Files)



iOS App

iOS source code example

Android App

Android source code example

BLE-STACK for SensorTag firmware



Cloud-based development tools

Code Composer Studio Integrated Development Environment

IAR Embedded Workbench for ARM®

Bluetooth low energy Device Monitor

The SensorTag Story Getting Started Teardown DevPacks Apps and Partners Community & Buzz

6LoWPAN SensorTag firmware

Sensors and Services*

+	Infrared and Ambient Temperature Sensor
+	Ambient Light Sensor
+	Humidity Sensor
+	Barometric Pressure Sensor
+	9- axis Motion Tracking Device – Accelerometer, Gyroscope and Compass
+	Magnet Sensor
+	Over The air Download (OAD)
_	Full GATT table

Full GATT table

The S	The SensorTag Story		Getting S	ardown	DevPacks	Apps and Partners	Community & Buzz	
0x1	1	0x2800	GATT Primary Service Declaration	0x1800	R	Generic Acc	ess Service	
0x2	2	0x2803	GATT Characteristic Declaration	02:03:00:00:2A	R	Device Nam	ne	
0x3	3	0x2A00	Device Name		R			
0x4	4	0x2803	GATT Characteristic Declaration	02:05:00:01:2A	R	Appearance	2	
0x5	5	0x2A01	Appearance		R			
0x6	6	0x2803	GATT Characteristic Declaration	02:07:00:04:2A	R	Peripheral I	Preferred Connection Parameters	
0x7	7	0x2A04	Peripheral Preferred Connection Parameters		R			
0x8	8	0x2800	GATT Primary Service Declaration	0x1801	R	Generic Att	ribute Service	
0x9	9	0x2803	GATT Characteristic Declaration	20:0A:00:05:2A	R	Service Cha	nged	
0xA	10	0x2A05	Service Changed		ı			
0xB	11	0x2902	Client		RW	Write "01:00	ס" to enable notifications, "00:00" to מ	lisable

0xC	12	0x2800	GATT Primary Service Declaration	0x180A	R	Device Information Service	
0xD	13	0x2803	GATT Characteristic Declaration	02:0E:00:23:2A	R	System ID	
0xE	14	0x2A23	System ID		R		
0xF	15	0x2803	GATT Characteristic Declaration	02:10:00:24:2A	R	Model Number String	
0x10	16	0x2A24	Model Number String		R		
0x11	17	0x2803	GATT Characteristic Declaration	02:12:00:25:2A	R	Serial Number String	
0x12	18	0x2A25	Serial Number String		R		
0x13	19	0x2803	GATT Characteristic Declaration	02:14:00:26:2A	R	Firmware Revision String	
0x14	20	0x2A26	Firmware Revision String	30:2E:38:37:45:20:2 8:4F:63:74:20:31:36: 20:32:30:31:34:29:0 0	R	0.87E (Oct 16 2014)	
0x15	21	0x2803	GATT Characteristic Declaration	02:16:00:27:2A	R	Hardware Revision String	

The S	ensorTa	g Story	Getting St	tarted Teard	own	DevPacks	Apps and Partners	Community & Buzz
0x17	23	0x2803	GATT Characteristic Declaration	02:18:00:28:2A	R	Software Revi	ision String	
0x18	24	0x2A28	Software Revision String		R			
0x19	25	0x2803	GATT Characteristic Declaration	02:1A:00:29:2A	R	Manufacturer	r Name String	
0x1A	26	0x2A29	Manufacturer Name String		R			
0x1B	27	0x2803	GATT Characteristic Declaration	02:1C:00:2A:2A	R	IEEE 11073-20	0601 Regulatory Certification Dat	a List
0x1C	28	0x2A2A	IEEE 11073-20601 Regulatory Certification Data List		R			
0x1D	29	0x2803	GATT Characteristic Declaration	02:1E:00:50:2A	R	PnP ID		
0x1E	30	0x2A50	PnP ID		R			
0x1F	31	0x2800	GATT Primary Service Declaration	F000AA00-0451-400 0-B000-0000000000 00	R	IR Temperatu	ire Service	
0x20	32	0x2803	GATT Characteristic Declaration	12:21:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:01:AA:00:F0	R	IR Temperatu	ire Data	

The S	ensorTa	g Story	Getting S	Started Teard	own	DevPacks Apps and Partners Community & E			
0x22	34	0x2902	Client Characteristic Configuration		RW	Write "01:00" to enable notifications, "00:00" to disable			
0x23	35	0x2803	GATT Characteristic Declaration	0A:24:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:02:AA:00:F0	R	IR Temperature Config			
0x24	36	0xAA02	IR Temperature Config		RW	Write "01" to start Sensor and Measurements, "00" to put to sleep			
0x25	37	0x2803	GATT Characteristic Declaration	0A:26:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:03:AA:00:F0	R	IR Temperature Period			
0x26	38	0xAA03	IR Temperature Period		RW	Period = [Input*10] ms, (lower limit 300 ms), default 1000 ms			
0x27	39	0×2800	GATT Primary Service Declaration	F000AA20-0451-400 0-B000-0000000000 00	R	Humidity Service			
0x28	40	0x2803	GATT Characteristic Declaration	12:29:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:21:AA:00:F0	R	Humidity Data			
0x29	41	0xAA21	Humidity Data		RN	TempLSB:TempMSB:HumidityLSB:HumidityMSB			
0x2A	42	0x2902	Client Characteristic Configuration		RW	Write "01:00" to enable notifications, "00:00" to disable			
0x2B	43	0x2803	GATT Characteristic Declaration	0A:2C:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:22:AA:00:F0	R	Humidity Config			
0x2C	44	0xAA22	Humidity Config		RW	Write "01" to start measurements, "00" to stop			

The S	ensorTa	g Story	Getting St		own	DevPacks	Apps and Partners	Community & Buzz		
0x2E	46	0xAA23	Humidity Period	.51.04.25.70.00.10	RW	Period = [In	put*10] ms, (lower limit 100 ms),	default 1000 ms		
0x2F	47	0x2800	GATT Primary Service Declaration	F000AA40-0451-400 0-B000-0000000000 00	R	Barometer	Service			
0x30	48	0x2803	GATT Characteristic Declaration	12:31:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:41:AA:00:F0	R	Barometer	Barometer Data			
0x31	49	0xAA41	Barometer Data		RN	TempLSB:T	empMSB:PressureLSB:PressureM	SB		
0x32	50	0x2902	Client Characteristic Configuration		RW	Write "01:0	0" to enable notifications, "00:00"	to disable		
0x33	51	0x2803	GATT Characteristic Declaration	0A:34:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:42:AA:00:F0	R	Barometer	Configuration			
0x34	52	0xAA42	Barometer Configuration		RW		o start Sensor and Measurements	s, "00" to put to sleep, "02" to		
0x35	53	0x2803	GATT Characteristic Declaration	0A:36:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:44:AA:00:F0	R	Barometer	Period			
0x36	54	0xAA44	Barometer Period		RW	Period = [In	put*10] ms, (lower limit 100 ms),	default 1000 ms		
0x37	55	0x2800	GATT Primary Service Declaration	F000AA80-0451-400 0-B000-0000000000 00	R	Movement	Service			
0x38	56	0x2803	GATT Characteristic Declaration	12:39:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:81:AA:00:F0	R	Movement	Data			

The S	ensorTa	g Story	Getting St	arted Teard	own	DevPacks Apps and Partners Community & Buzz
0x3A	58	0x2902	Client Characteristic Configuration		RW	Write "01:00" to enable notifications, "00:00" to disable
0x3B	59	0x2803	GATT Characteristic Declaration	0A:3C:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:82:AA:00:F0	R	Movement Config
0x3C	60	0xAA82	Movement Config		RW	Axis enable bits:gyro-z=0,gyro-y,gyro-x,acc-z=3,acc-y,acc-x,mag=6 Range: bit 8,9
0x3D	61	0x2803	GATT Characteristic Declaration	0A:3E:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:83:AA:00:F0	R	Movement Period
0x3E	62	0xAA83	Movement Period		RW	Period = [Input*10]ms (lower limit 100ms), default 1000ms
0x3F	63	0x2800	GATT Primary Service Declaration	F000AA70-0451-400 0-B000-0000000000 00	R	Luxometer Service
0x40	64	0x2803	GATT Characteristic Declaration	12:41:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:71:AA:00:F0	R	Luxometer Data
0x41	65	0xAA71	Luxometer Data		RN	LSB:MSB
0x42	66	0x2902	Client Characteristic Configuration		RW	Write "01:00" to enable notifications, "00:00" to disable
0x43	67	0x2803	GATT Characteristic Declaration	0A:44:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:72:AA:00:F0	R	Luxometer Config
0x44	68	0xAA72	Luxometer Config		RW	Write "01" to start Sensor and Measurements, "00" to put to sleep

The S	ensorTa	g Story	Getting St	arted Teard	own	DevPacks	Community & Buzz	
0x46	70	0xAA73	Luxometer Period	.51.04.75.84 4.00.110	RW	Period = [Inp	ut*10]ms (lower limit 1000ms), o	default 2000ms
0x47	71	0x2800	GATT Primary Service Declaration	0xFFE0	R	Simple Keys S	Service	
0x48	72	0x2803	GATT Characteristic Declaration	10:49:00:E1:FF	R	Key press sta	ite	
0x49	73	0xFFE1	Key press state		N			
0x4A	74	0x2902	Client Characteristic Configuration		RW	Write "01:00"	to enable notifications, "00:00"	to disable
0x4B	75	0x2901	Characteristic User Description		R			
0x4C	76	0x2800	GATT Primary Service Declaration	F000AA64-0451-400 0-B000-0000000000 00	R	IO Service		
0x4D	77	0x2803	GATT Characteristic Declaration	0A:4E:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:65:AA:00:F0	R	IO Data		
0x4E	78	0xAA65	IO Data	5F	RW		mote mode: bit 0 - red led; bit 1 - ensor self test result (exp. 0x5F)	green led; bit 2 - buzzer. In
0x4F	79	0x2803	GATT Characteristic Declaration	0A:50:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:66:AA:00:F0	R	IO Config		
0x50	80	0xAA66	IO Config		RW	0:local mode	; 1:remote mode; 2:test mode	

The S	ensorTa	g Story	Getting St	tarted Teard	own	DevPacks Apps and Partners Community & B			
0x52	82	0x2803	GATT Characteristic Declaration	1A:53:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:01:AC:00:F0	R	Register Data			
0x53	83	0xAC01	Register Data		RWN	Data from serial device, variable length (see Register Address)			
0x54	84	0x2902	Client Characteristic Configuration		RW	Write "01:00" to enable notifications, "00:00" to disable			
0x55	85	0x2803	GATT Characteristic Declaration	0A:56:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:02:AC:00:F0	R	Register Address			
0x56	86	0xAC02	Register Address		RW	length(byte, max 16);internal addr (1 to 4 bytes)			
0x57	87	0x2803	GATT Characteristic Declaration	0A:58:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:03:AC:00:F0	R	Register Device ID			
0x58	88	0xAC03	Register Device ID		RW	byte 1 (interface): 0=I2C0,1=I2C1,2=SPI1,3=SPI2,4=SPI3,5=MCU; byte 2: device addr			
0x59	89	0x2800	GATT Primary Service Declaration	F000CCC0-0451-400 0-B000-0000000000 00	R	Connection Control Service			
0x5A	90	0x2803	GATT Characteristic Declaration	12:5B:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:C1:CC:00:F0	R	Connection Parameters			
0x5B	91	0xCCC1	Connection Parameters		RN	ConnInterval,SlaveLatency,SupervisionTimeout (2 bytes each)			
0x5C	92	0x2902	Client Characteristic		RW	Write "01:00" to enable notifications, "00:00" to disable			

The S	ensorTa	g Story	Getting S	tarted Teard	own	DevPacks	Apps and Partners	Community & Buz
			Characteristic Declaration	0:00:00:00:B0:00:40 :51:04:C2:CC:00:F0				
0x5E	94	0xCCC2	Request Connection Parameters		W	MinConnInt bytes each)	erval, Max Conn Interval, Slave Laten	cy,SupervisionTimeout (2
0x5F	95	0x2803	GATT Characteristic Declaration	08:60:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:C3:CC:00:F0	R	Disconnect	request	
0x60	96	0xCCC3	Disconnect request		W	Change the	value to disconnect	
0x61	97	0x2800	GATT Primary Service Declaration	F000FFC0-0451-400 0-B000-0000000000 00	R	OAD Service	2	
0x62	98	0x2803	GATT Characteristic Declaration	1C:63:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:C1:FF:00:F0	R	OAD Image	Identify	
0x63	99	0xFFC1	OAD Image Identify		WN		dentify image type 'A', '1' to identi e type (2), size/4 (2), user data (4).	fy 'B'. Data in notfication 8
0x64	100	0x2902	Client Characteristic Configuration		RW	Write "01:00	" to enable notifications, "00:00" t	o disable
0x65	101	0x2901	Characteristic User Description		R			
0x66	102	0x2803	GATT Characteristic Declaration	1C:67:00:00:00:00:0 0:00:00:00:B0:00:40 :51:04:C2:FF:00:F0	R	OAD Image	Block	
0x67	103	0xFFC2	OAD Image Block		WN	Image block	(18 bytes). Block no. (2 bytes), OA	D image block (16 bytes)

The S	The SensorTag Story		Getting Started	Teardown	DevPacks	Apps and Partners	Community & Buzz
0x69	105	0x2901	Characteristic User Description	R			