


Circuit diagram of screw rod two post -(CE)



		PS	switching power supply	SQ ₉	nut limit switch column 2
		HL	indicator lamp	SQ ₈	nut limit switch column 2
M	motor	BZR	buzzer	SQ ₇	nut limit switch column 1
KM ₄	AC contractor	HE ₂	proximity switch column 2	SQ ₆	nut limit switch column 1
KM ₃	AC contractor	HE ₁	proximity switch column 1	SQ ₅	down limit switch column 2
KM ₂	AC contractor	SB ₃	change-over switch	SQ ₄	down limit switch column 1
KM ₁	AC contractor	SB ₂	down button	SQ ₃	limit switch anti-collision rod
FU	fuse	SB ₁	up button	SQ ₂	up limit switch column 2
QS	main switch	SB ₀	emergency stop button	SQ ₁	up limit switch column 1