↑ TREATMENT	₿ BUDGET_GROUP	↑ MWP_PROJECT_STATUS	⊕ MIN	⊕ MAX
Chip Seal	CAPM	Programmed	0.3237	0.3453
Cold In-Place Recycling	CAPM	Programmed	0.2892	1.0846
Grind PCC for Smoothness	CAPM	Programmed	0.1796	0.2154
Grind/Replace slabs	CAPM	Programmed	0.0669	4.26
HMA Medium Overlay	CAPM	Programmed	-0.5434	80.3437
HMA Thin Overlay	CAPM	Programmed	0.1581	1.3098
PCC overlay	CAPM	Programmed	0.0092	0.7778
Slab Replacement	CAPM	Programmed	-0.0093	0.5343
Chip Seal	Corrective Maintenance	Programmed	0.6601	2.872
Cold In-Place Recycling	Corrective Maintenance	Programmed	0.3918	4.9391
Digouts	Corrective Maintenance	Programmed	0.0002	0.0369
HMA Thin Overlay	Corrective Maintenance	Programmed	0.1382	0.9468
Slab Replacement	Corrective Maintenance	Programmed	0.0696	90.9093
Chip Seal	Preventive Maintenance	Programmed	0.0175	3.3854
Grind/Replace slabs	Preventive Maintenance	Programmed	4.1999	4.3318
Groove PCC Pavement	Preventive Maintenance	Programmed	0	0
HMA Thin Overlay	Preventive Maintenance	Programmed	0.0267	27.1304
HMA Thin Overlay - Preventive	Preventive Maintenance	Programmed	0.3465	0.3661
Microsurfacing	Preventive Maintenance	Programmed	0.3248	0.3248
Slab Replacement	Preventive Maintenance	Programmed	-0.0492	0.0235
CRCP Lane Replacement	Rehab	Programmed	0.0737	0.3108
Crack Seat and Overlay	Rehab	Programmed	0.2825	0.8739
Grind/Replace slabs	Rehab	Programmed	0.0726	1.3738
HMA Thick Overlay	Rehab	Programmed	-0.2469	1.7182
PCC Lane Replacement	Rehab	Programmed	-0.3017	1.3888
Slab Replacement with Pre-Cast	Rehab	Programmed	-0.0001	0.0005
Cold In-Place Recycling	CAPM	Scenario Recommended	0.3395	2.2454
Grind PCC for Smoothness	CAPM	Scenario Recommended	0.0032	2.9552
Grind/Replace slabs	CAPM	Scenario Recommended	0.1908	2.0004
HMA Medium Overlay	CAPM	Scenario Recommended	0.068	0.5032
Cold In-Place Recycling - Class 3	Corrective Maintenance	Scenario Recommended	0.2539	1.52
HMA Thin Overlay	Corrective Maintenance	Scenario Recommended	0.3252	5.1539
Seal Coat	Corrective Maintenance	Scenario Recommended	0.4087	6.3913
Slab Replacement	Corrective Maintenance	Scenario Recommended	0.2356	2.2078
HMA Thin Overlay - Preventive	Preventive Maintenance	Scenario Recommended	0.1722	4.5783
Seal Coat - Preventive	Preventive Maintenance	Scenario Recommended	0.2152	8.7696
Crack Seat and Overlay	Rehab	Scenario Recommended	0.9117	1.0504
Full Depth Reclamation	Rehab	Scenario Recommended	0.2813	1.3105
HMA Thick Overlay	Rehab	Scenario Recommended	0.1028	0.2492
PCC Lane Replacement	Rehab	Scenario Recommended	0.2278	0.4038