⊕ TREATMENT	⊕ BUDGET_GROUP	↑ MWP_PROJECT_STATUS	⊕ MIN	∯ MAX
Chip Seal	CAPM	Programmed	0.3654	0.4174
Cold In-Place Recycling	CAPM	Programmed	0.3117	0.5026
Grind PCC for Smoothness	CAPM	Programmed	0.14	0.2027
Grind/Replace slabs	CAPM	Programmed	0.192	4.0694
HMA Medium Overlay	CAPM	Programmed	0.0866	7.9536
HMA Thin Overlay	CAPM	Programmed	0.2927	0.5722
PCC overlay	CAPM	Programmed	0.0124	0.7877
Slab Replacement	CAPM	Programmed	0.0167	0.9408
HMA Thin Overlay	Corrective Maintenance	Programmed	0.001	99.3052
Microsurfacing	Corrective Maintenance	Programmed	0.0834	0.0834
Slab Replacement	Corrective Maintenance	Programmed	0	21.8659
Chip Seal	Preventive Maintenance	Programmed	0.4915	3.075
Grind/Replace slabs	Preventive Maintenance	Programmed	4.7517	4.8453
Groove PCC Pavement	Preventive Maintenance	Programmed	0	0
HMA Thin Overlay	Preventive Maintenance	Programmed	0.5145	11.8735
HMA Thin Overlay - Preventive	Preventive Maintenance	Programmed	26.9329	29.9155
Microsurfacing	Preventive Maintenance	Programmed	0.408	0.408
Slab Replacement	Preventive Maintenance	Programmed	-0.0036	0.0069
CRCP Lane Replacement	Rehab	Programmed	-0.2395	0.4726
Crack Seat and Overlay	Rehab	Programmed	0.2939	0.9107
Grind/Replace slabs	Rehab	Programmed	-1.032	1.4013
HMA Thick Overlay	Rehab	Programmed	0.0297	1.9234
PCC Lane Replacement	Rehab	Programmed	-0.3172	1.4143
Slab Replacement with Pre-Cast	Rehab	Programmed	0.0006	0.0006
Cold In-Place Recycling	CAPM	Scenario Recommended	0.3382	2.2454
Grind PCC for Smoothness	CAPM	Scenario Recommended	0.0304	1.2175
Grind/Replace slabs	CAPM	Scenario Recommended	0.7014	1.2844
HMA Medium Overlay	CAPM	Scenario Recommended	0.1318	0.3936
HMA Thin Overlay	Corrective Maintenance	Scenario Recommended	0.3165	0.8174
Seal Coat	Corrective Maintenance	Scenario Recommended	1.0717	2.4587
Slab Replacement	Corrective Maintenance	Scenario Recommended	0.4948	1.2485
HMA Thin Overlay - Preventive	Preventive Maintenance	Scenario Recommended	0.2209	2.5096
Seal Coat - Preventive	Preventive Maintenance	Scenario Recommended	0.5522	7.0739
Crack Seat and Overlay	Rehab	Scenario Recommended	0.9664	1.0465
Full Depth Reclamation	Rehab	Scenario Recommended	0.2897	1.3105
HMA Thick Overlay	Rehab	Scenario Recommended	0.1942	0.1942
PCC Lane Replacement	Rehab	Scenario Recommended	0.2298	0.3909