Total No. of Questions: 8]

[Total No. of Printed Pages: 4

Roll No .....

## **AU/ME-4003 (CBGS)**

## **B.E. IV Semester**

Examination, May 2018

## **Choice Based Grading System (CBGS) Machine Drawing and CAD**

Time: Three Hours

Maximum Marks: 70

Note: Answer any five questions. All questions carry equal marks.

- Draw any five conventional representations of machines components.
  - Sketch any two types of structural riveted, indicating proportionate dimensions.
- Sketch the following welding symbol along with respective illustration.
  - Single V-butt weld
  - Single U-butt weld
  - Square butt weld
  - Filled weld

rgpvonline.com

rgpvonline.com

- Spot weld
- 3. Assemble the parts of a knuckle joint, shown in figure-1 and draw
  - Sectional view from the front and
  - View from above

rgpvonline.com . . . . . . . . . . . . . . . . . rgpvonline.com

rgpvonline.com

rgpvonline.com

[2]

4.	Assemble the parts of a Stuffing box, shown in figure-2	and
	draw	14

- Half sectional view from the front, showing top half in section and
- The view from the left

What are soft ware and hardware required to produce CAD rgpvonline.com drawing. Explain any one in each.

What are the commands used in 3D models and explain any two.

7. Explain any five commands of the following:

- Line and polyline
- Circle
- Hatching
- Text

rgpvonline.com

rgpvonline.com

- Dimensioning
- Layers/levels
- Colours

Compare 2D and 3D wireframe modeling with respect to their utility for an engineering industry.

Explain the parametric representation of curves. Why its more used compared to non-parametric (implicit) representation?

14


rgpvonline.com

rgpvonline.com

rgpvonline.com

rgpvonline.com

rgpvonline.com



Parts list

rgpvonline.com

rgpvonline.com


SI. No.	Name	Matl.	Qty.
1	Fork end	Forged steel	1
2	Eye end	Forged steel	1
3	Pin	Mild steel	1
4	Collar	Mild steel	1
5	Taper pin	Mild steel	1

Figure - 1

rgpvonline.com

[4]

## For Question No. 4



Parts list

rgpvonline.com

rgpvonline.com

rgpvonline.com

rgpvonline.com

Part No.	Name	Matl.	Qty.			
1	Body	CI	1			
2	Gland	Brass	1			
3	Bush	Brass	1			
4	Stud	MS	2			
5	Nut M12	MS	2			

Figure-2

rgpvonline.com

- rgpvonline.com

 $L^{2}X$ 

rgpvonline.com