OR

## B.E. V Semester

Examination, December 2014

## Metrology Measurement And Control

Time: Three Hours

Maximum Marks: 70

**Note:** i) Answer five questions. In each question part A, B, C is compulsory and D part has internal choice.

- ii) All parts of each questions are to be attempted at one place.
- iii) All questions carry equal marks, out of which part A and B (Max.50 words) carry 2 marks, part C (Max.100 words) carry 3 marks, part D (Max.400 words) carry 7 marks.
- iv) Except numericals, Derivation, Design and Drawing etc.
- 1. a) Define the term standard of measurement?
  - b) Define interchangeability?
  - c) Define clearly the accuracy and precision.
  - d) In a hole and shaft combination of 25 mm nominal size H7 hole limits are +0.021 mm and +0.000 mm. and es shaft limits are -0.040 mm and -0.073 mm. State the value of
    - i) Maximum and Minimum clearance obtainable
    - ii) Allowance
    - iii) Tolerance of hole and shaft

RGPVONLINE.COM

- iv) MML shaft and hole
- v) What type of fit it is

OR

Explain in brief the Michelson Interferometer?

- 2. a) Why slip gauges are needed?
  - b) Give names of angular measuring instruments?
  - c) Classify different types of comparators?
  - d) Explain the difference between a comparator and measuring instruments.

Explain with suitable sketch the principal of Autocollimators in brief?

- 3. a) What do you mean by surface finish?
  - b) Name the methods of surface roughness evaluation?
  - c) What do you mean by roughness and waviness of machined surface?
  - d) Explain with neat sketch the working of Talysurf instrument for surface measurement?

OR

In a measurement of surface roughness, heights of 20 successive peaks and troughs were measured from a datum and were: 35, 25, 40, 22, 35, 18, 42, 25, 35, 22, 36, 18, 42, 22, 32, 21, 37, 18, 35, 20 microns.

If these measurements were obtained over a length of 20 mm, determine the C.L.A. and R.M.S. value of rough surface.

- 4. a) Name the methods used for measuring gear tooth thickness?
  - b) Discuss the use of base tangent method?
  - c) What do you mean by constant chord method?
  - d) Describe the two wire method of finding the effective diameter of screw threads?

OR

RGPVONLINE.COM

What is best wire size? Derive the expression for same in terms of the pitch and angle of thread?

- 5. a) Discuss the vision system?
  - b) What do you mean by laser scanning gauge?
  - c) Write down the application of laser metrology?
  - d) Explain the working principle of coordinate measuring machine?

)R

Explain the working principle of laser interferometer?