## Choice Based Grading System (CBGS) Machine Drawing and CAD

Time: Three Hours

Maximum Marks: 70

Note: i) Attempt any four questions.

- ii) Question No.3 is compulsory.
- 1. Draw elevation, plan and right side view of the machine block 14 given in figure 1.




Figure 1: A Cast Iron block

- 2. Draw the conventional representation of the following machine elements 14
  - External thread
- Internal thread

Bearing

http://www.rgpvonline.com

But joint

Fillet weld

Surface roughness

Spur gear

PTO

The parts of cross head are given in Figure 3. Draw the full sectional point view of the cross head assembly.

- Draw double riveted chain lap joint of 18 mm thick plates. Show at least three rivets in the plan and add a sectional elevation. Also mark all dimensions. 14
- Explain the following terms used in CAD

14

a) CPU

http://www.rgpvonline.com

http://www.rgpvonline.com

- Input devices
- RAM and ROM
- Display devices
- Output devices
- What is meant by edit functions in drafting. List down commonly used 5 edit functions giving their uses.
- 7. Write short notes on any two

14

- Knuckle joint
- Advantages of CAD
- 3D models




Figure 2

IC engine connecting rod (parts)




Figure 3
Cross-head (Vertical type) parts

\*\*\*\*\*

http://www.rgpvonline.com

http://www.rgpvonline.com