

time to apply < 34 sec							
Trial	current wristband (s)	knobby (alone) (s)	knobby (assisted) (s)	slap bracelet (s)	tape measure (s)	magnet (s)	
1	7	10	8	1	2	2	
2	9	8	8	1	2	3	
3	8	7	5	1	3	2	
4	8	8	8	1	4	4	
5	9	11	7	1	5	3	
6	8	10	8	1	3	3	
7	10	11	10	1	3	3	
8	9	10	11	1	3	4	
9	8	10	10	1	2	3	
Sum	76	85	75	9	27	27	
Average	8.444444444	9.444444444	8.333333333	1	3	3	
Median	8	10	8	1	3	3	
weight(in g)							
	Trial	current wristband (s)	knobby (alone) (s)		slap bracelet (s)		magnet (s)
	1	<1	16		9		33
wrist clearance (pass/fail)							
	Trial	current wristband (s)	knobby (alone) (s)		slap bracelet (s)	tape measure (s)	magnet (s)
	1	pass	pass		fail	pass	pass
	2	pass	pass		fail	pass	pass
accomodate all wrist sizes (pass fail)							
	trial	current wristband (s)	knobby (alone) (s)		slap bracelet (s)	tape measure (s)	magnet (s)
	10 mm	fail	pass		pass	pass	pass
	18 mm	pass	pass		pass	pass	pass
complexity of actions per step (rank 1-4 for each step)							
	step	current wristband (s)	knobby (alone) (s)	knobby (assisted) (s)	slap bracelet (s)	tape measure (s)	magnet (s)
	1	Grasp strap - 1	put hand in - 1	put hand in - 1	Slap - 1	hold and pull strap - 2	Put on the skeleton - 2

	2	Pull strap - 1	hold in palm - 3	hold to wrist - 2		put hand in - 1	Put hand in - 1
	3	Align tab with slot - 4	tighten by twisting - 4	tighten by twisting - 3		release the strap - 1	exert force to wristband - 3
	4	Press snap closed - 3	measure with 2 fingers - 2	measure with 2 fingers - 1		press child lock button - 1	adjust the size - 2
	5	Hold buckle steady - 2					
	6	Check fit with fingers - 2					
	7	remove excess with scissors - 4					
	sum		10	7	1	5	8
force before rupture (N)							
	trial	current wristband (s)	knobby (sharp) (s)	knobby (rounded) (s)	slap bracelet (s)	tape measure (s)	magnet (s)
	1	0.363	6.1	14.51	0.363	14.51	6.1