Group 5

MEETING AGENDA

Meeting Time: 12:30 PM Location: AQ 5029, SFU Date: 05/09/2019	
--	--

Meeting called by	Jerry
Kind of Meeting	Beta Planning Meeting
Facilitator	Jerry
Note Taker	Jeff
Time Management	Jerry
Attendees:	Keith, Scott, Ryne, Jeffery, Jerry

Topics

Time	Discussion Topic	Presenter	Deadline
12:30 PM	Catch up	All	
12:40 PM	Hardware Planning	All	
1:30 PM	Software Planning	All	

Notes:			

MEETING MINUTES

- 1. Hardware
 - a. DWM debug
 - i. Two board solder joints are bad
 - ii. Two send corrupted data
 - b. Battery/Charging circuit
 - i. Look for TP4056 charging circuit (x5) [Jeff]
 - ii. Velleman mm104 Charger
 - iii. Battery for ID tag (Done)
 - iv. Battery for beacons (Any can do) [Jeff]
 - c. Case/Cover 3D printing
 - i. tinkerCAD block design
 - ii. Vote for Tetrahedron [Cube box for beacon]
- 2. Software
 - a. UI
 - b. CRUD
 - c. Wifi Hostapd / UDP
 - i. Config file: https://github.com/liuyal/Archive/blob/master/Python/AP tests/config
- 3. DEMO

Action Items	Person Responsible	Deadline