



Technical Service BULLETIN

September 9, 2003

Title:

TRIM GARNISH LOOSE

Models:

'91 – '07 All Models

REVISED

B0017-03

BODY

TSB REVISION NOTICE:

- April 24, 2006: Model year applicability has been defined to 1991 – 2007. The Inspection/Replacement Procedure has been updated with parts information for applicable model year Avalon, Camry, and Solara vehicles.
- March 3, 2004: The TSB has been changed to include new inspection and replacement instructions.

Previous versions of this TSB should be discarded.

Introduction

Customers may experience an interior trim panel either loose or fitting poorly due to a deformed or missing panel attachment clips. When a trim garnish (A, B, C, or D pillar garnish, door trim panel, etc.) is removed and reinstalled using the old clips, there is a possibility that the garnish may exhibit a loose condition. To prevent this condition from occurring, please use the following procedures.

Applicable Vehicles

- 1991 – 2007 model year Toyota vehicles.

Warranty Information

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
N/A	Not Applicable to Warranty	–	–	–	–

Inspection/ Replacement Procedure

All Models:

All trim panel attachment clips must be inspected prior to reassembly and replaced if any damage or wear is detected. If NO damage is visible, the clip may be reused. **Always** check to make sure that the garnish is properly attached after reinstallation of all interior trim panels.



**Inspection/
Replacement
Procedure**
(Continued)

2005 – 2006 model year Avalon, 2002 – 2007 model year Camry, and 2004 – 2006 model year Solara:

When removing the A-pillar garnish panels, replace the plastic attachment clips. Refer to the table below for appropriate part numbers.

MODEL	MODEL YEAR	PART NUMBER	PART NAME	QTY
Avalon	2005 – 2006	90467-A0025	Clip, Attachment	1
		90950-A8001		1
Camry (NAP)	2002 – 2006	90467-09204		1
		90109-A0030*		2
	2007	90467-A0006		1
		90950-A8001		1
Camry (Japan)	2002 – 2006	90467-09204		1
		90109-06369*		2
	2007	90467-10161		1
		90950-08004		1
Solara	2004 – 2006	90467-A0025		1
		90950-A8001		1

* Vehicles equipped with Side Curtain Air Bags.